

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 07 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1604840853

OPERATOR

Initial Report Final Report

Name of Company <i>OXY USA WTP LP</i> <i>192403</i>	Contact: Jennifer Duarte
Address PO BOX 4294; HOUSTON, TX 77210	Telephone No. 713-513-6640
Facility Name SIMPSON CDM COM #1H BATTERY	Facility Type CTB

Surface Owner	Mineral Owner	API No. 30-015-42012
---------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	29	21S	27E	480	NORTH	310	EAST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release GAS - FLARE	Volume of Release 300 MCF	Volume Recovered 0
Source of Release GAS - FLARE	Date and Hour of Occurrence 02/16/2016 - BEGAN/END	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
NGSG - compressor battery change

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Duarte</i>	OIL CONSERVATION DIVISION	
Printed Name: JENNIFER DUARTE	Approved by Environmental Specialist <i>[Signature]</i>	
Title: ENVIRONMENTAL SPECIALIST	Approval Date: <i>3/8/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>jennifer_duarte@oxy.com</i>	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 03/07/2016	Phone: 713-513-6640	

* Attach Additional Sheets If Necessary

** 2LP-5519*

Bratcher, Mike, EMNRD

From: Jennifer_Duarte@oxy.com
Sent: Monday, March 07, 2016 4:45 PM
To: Bratcher, Mike, EMNRD
Subject: FINAL C141 - SIMPSON CDM COM #1 BATTERY
Attachments: SIMPSON CDM COM #1H - FINAL C141.pdf

Mike,

Please find the attached C141 for the Simpson CDM Com # 1 Battery.

I am hopeful that emailing you will be acceptable to help reduce mailing cost. I am requesting a read receipt as confirmation you have received this form.

Should you prefer a different way of handling, please let me know and I will be glad to adjust.

Thank you,

Jennifer Duarte

**Environmental Specialist
713-513-6640**