

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

MAR 14 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

NAB 1607447305

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: GRAVE DIGGER FEDERAL COM #001H	Facility Type: Battery
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-37665	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	2	20S	25E	330'	North	380'	West	Eddy

Latitude 32.6087532 Longitude -104.4628143

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 bbls PW	Volume Recovered: 19 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 2/28/2016 10:00 am	Date and Hour of Discovery: 2/28/2016 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a corroded flowline that ran to the water tank. A vacuum truck was dispatched to recover the standing fluid.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined facility. Concho will have the spill site evaluated for additional remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Robert Grubbs Jr.</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Robert Grubbs Jr.	Approval Date: <i>3/14/16</i>	Expiration Date: <i>NIA</i>
Title: Senior Environmental Coordinator	Conditions of Approval: <input type="checkbox"/> Remediation per O.C.D. Rules & Guidelines	
E-mail Address: rgrubbs@concho.com	SUBMIT REMEDIATION PROPOSAL NO	
Date: March 11, 2016 Phone: 432-683-7443	LATER THAN: <i>4/14/16</i>	

* Attach Additional Sheets If Necessary.

2RP-3611

Patterson, Heather, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Monday, March 14, 2016 10:00 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; 'agroves@slo.state.nm.us'; 'dvstrang@slo.state.nm.us'; Martin, Ed; Naranjo, Mark M.
Subject: (Notification/C-141Initial)GRAVE DIGGER FEDERAL COM #001H (30-015-37665)
Attachments: 2-28-2016 Grave Digger Federal Com #1H (TB) Initial.pdf

MR. BRATCHER,

COG OPERATING LLC IS REPORTING A RELEASE ON THE GRAVE DIGGER FEDERAL COM #001H (30-015-37665)
UNIT D SECTION 2, TOWNSHIP 20S RANGE 25E
THE RELEASE OCCURRED AT 2/28/2016 AT 10:00 AM
RELEASED: 20 BBLs PW
RECOVERED: 19 BBLs PW

THIS RELEASE WAS CAUSED WHEN A CORRODED STEEL FLOWLINE INSIDE THE CONTAINMENT. VACUUM TRUCKS WERE DISPATCHED TO RECOVER THE STANDING FLUID. ATTACHED IS A C-141 FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

ROBERT GRUBBS JR.
SR. ENVIRONMENTAL COORDINATOR
432.683.7443 (MAIN)
432.818.2369 (DIRECT)
432.661.6601 (CELL)
432.221.0892 (FAX)
RGRUBBS@CONCHO.COM
MAILING ADDRESS:
ONE CONCHO CENTER
600 W. ILLINOIS AVENUE
MIDLAND, TEXAS 79701

CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.