

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

APR 1 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

**RECEIVED**

**PAB1609639585 Release Notification and Corrective Action**

**NAB1609639712**

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC <b>229137</b>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Woolley Tank Battery	Facility Type: Tank Battery
Surface Owner: Federal	Mineral Owner:
	API No. NA

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	28	17S	30E					Eddy

Latitude 32.810986° Longitude -103.979151°

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 85 bbls PW	Volume Recovered: 75 bbls PW
Source of Release: Filter Pot	Date and Hour of Occurrence: 3/20/16 11:30 am	Date and Hour of Discovery: 3/20/16 11:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM	
By Whom? Robert Grubbs Jr.	Date and Hour: 3/21/2016 12:38 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused by a corroded nipple on a filter pot. All fluid was contained within the bermed area. A vacuum truck was dispatched to removal all standing fluids.

Describe Area Affected and Cleanup Action Taken.\*  
The impacted area was to the south of the tanks inside the containment. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: <i>Mike Bratcher</i>	
Title: Senior Environmental Coordinator	Approval Date: <b>4/5/16</b>	Expiration Date: <b>N/A</b>
E-mail Address: rgrubbs@concho.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: April 1, 2016 Phone: 432-683-7443	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary .

**LATER THAN: 5/5/16**

**2RP-3633**

**Bratcher, Mike, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Friday, April 01, 2016 12:34 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'james\_amos@blm.gov' (james\_amos@blm.gov); 'stucker@blm.gov'  
**Subject:** (C-141 Initial) Woolley Federal Tank Battery  
**Attachments:** 3-20-2016 Woolley Tank Battery (TB) Initial.pdf

MR. BRATCHER,

ATTACHED IS A C-141 FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

*THANK YOU,*

**ROBERT GRUBBS JR.  
SR. ENVIRONMENTAL COORDINATOR  
432.683.7443 (MAIN)  
432.818.2369 (DIRECT)  
432.661.6601 (CELL)  
432.221.0892 (FAX)  
RGRUBBS@CONCHO.COM  
MAILING ADDRESS:  
ONE CONCHO CENTER  
600 W. ILLINOIS AVENUE  
MIDLAND, TEXAS 79701**

**CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.**



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.