

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

APR 06 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1609926539

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Jake Harrington, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	432-214-5175
Facility Name	Snapping 2 State 1-Y	Facility Type	Oil

Surface Owner State	Mineral Owner State	API No.	30-015-39104
---------------------	---------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	2	26S	31E	330	FSL	1710	FWL	Eddy

Latitude: 32.0657578

Longitude: -103.7519608

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced water release	5bbls	0bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Heater treater fire tube	April 2, 2016 @ 11:33 AM	April 2, 2016 @ 11:33 AM
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Kellie Jones, OCD	
By Whom?	Date and Hour	
Ray Carter, Assistant Production Foreman	April 3, 2016 @ 7:05 AM	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Fire tube on heater treater had a hole releasing approximately 5bbls produced water on to location. The immediate actions were to make sure the well was down so the inlet on the heater treater could be closed and the drain opened to send the remaining fluid to the water tanks to stop any further release. A vacuum truck was able to pull the remaining fluid from the heater treater to ensure it was completely empty. The heater treater has been taken out of service until repairs can be made.

Describe Area Affected and Cleanup Action Taken.* The release was 5bbls produced water with 0bbls recovered located on the West side of location close to the heater treater in approximately a 15'x20' area. All fluid remained on location. An environmental agency will be contacted for remediation of the affected area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By: <i>Mike Brundage</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: 4/7/16
E-mail Address: Sheila.Fisher@dmv.com	Expiration Date: N/A	Conditions of Approval:
Date: April 6, 2016	Phone: 575.748.1829	Remediation per O.C.D. Rules & Guidelines <input checked="" type="checkbox"/>
SUBMIT REMEDIATION PROPOSAL NO		

LATER THAN: 5/11/16

2RP-3636

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Keyes, Jamie, EMNRD
Sent: Wednesday, April 06, 2016 10:49 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: FW: Snapping 2 State 1-Y_5bbls pw_4.2.15
Attachments: Snapping 2 State 1-Y_5bbls pw_Initial C-141_4.2.16.doc; Snapping 2 State 1-Y_5bbls pw_GIS Image_4.2.16.pdf; Snapping 2 State 1-Y_5bbls pw_picture 1 of 1_4.2.16.JPG

Enjoy!

From: Fisher, Sheila [mailto:Sheila.Fisher@dvn.com]
Sent: Wednesday, April 06, 2016 9:43 AM
To: Keyes, Jamie, EMNRD; Amber Groves (agroves@slo.state.nm.us)
Cc: Fulks, Brett; Carter, Ray; Harrington, Jake
Subject: Snapping 2 State 1-Y_5bbls pw_4.2.15

Good Morning,

Attached please find the Initial C-141, GIS Image and photo for the 5bbl produced water release at the Snapping 2 State 1-Y.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.