

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

APR 11 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DAB 11610331294

OPERATOR

Initial Report Final Report

Name of Company <i>Devon Energy Production 10137</i>		Contact Jake Harrington, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Telephone No. 432-214-5175
Facility Name Ross Ranch 10 Fed 1 SWD		Facility Type SWD
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-29605

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	26S	31E	1980	North	660	East	Eddy

Latitude: 32.059235486

Longitude: -103.75905787

NATURE OF RELEASE

Type of Release Produced Water Release	Volume of Release 66bbls	Volume Recovered 66bbls
Source of Release Fiberglass produced water tank	Date and Hour of Occurrence April 7, 2016 @ 8:00 AM	Date and Hour of Discovery April 7, 2016 @ 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Ray Carter, Asst. Production Foreman	Date and Hour Shelly Tucker, BLM April 7, 2016 @ 11:00Am Mike Bratcher, OCD April 7, 2016 @ 11:05	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
The fiber glass body of the gun barrel tank had a crack where the suction line for the injection pump came into the tank. The gun barrel was bypassed to stop the release and a vacuum truck was contacted. Repairs are currently in progress.

Describe Area Affected and Cleanup Action Taken.*
The spill was approximately 66bbls produced water into lined containment and all 66bbls were recovered by vacuum truck. The liner was checked for holes and no holes were found and no further action is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Sheila Fisher	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>4/12/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>Sheila.Fisher@dvn.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: <i>4/11/16</i> Phone: <i>575.748.1829</i>		

* Attach Additional Sheets If Necessary

2RP-3641

Patterson, Heather, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Monday, April 11, 2016 12:54 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Shelly Tucker (stucker@blm.gov)
Cc: Carter, Ray; Harrington, Jake; Fulks, Brett; Scrogum, Sandy
Subject: Ross Ranch 10 Fed 1 SWD_66bbl pw release_4.7.16
Attachments: Ross Ranch 10 Fed 1 SWD_66bbl pw release_Initial & Final C-141_4.7.16.doc; Ross Ranch 10 Fed 1 SWD_66bbl pw release_GIS Image_4.7.16.JPG.pdf; Ross Ranch 10 Fed 1 SWD_66bbl pw release_picture 1 of 2_4.7.16.JPG; Ross Ranch 10 Fed 1 SWD_66bbl pw release_picture 2 of 2_4.7.16.JPG

Good Morning,

Attached please find the Initial & Final C-141, GIS Image and photos for the 66bbl produced water release inside lined containment at the Ross Ranch 10 Fed 1 SWD.

If you have any questions please feel free to contact me.

Thank you

Sheila Fisher
Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.