




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1610447059

1RP - 4243

CHEVRON MIDCONTINENT LP

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

x Initial Report Final Report

Name of Company Chevron MidContinent, LP	Contact Kim Klahsen
Address 56 Texas Camp Road; Lovington NM 88260	Telephone No. 575-396-4414 (Cell (432-894-3298))
Facility Name West Lovington Unit Battery- Near well # WLU -77	Facility Type- Production Battery

Surface Owner State of NM	Mineral Owner State of NM	Lease No. B-3009
---------------------------	---------------------------	------------------

API 30.025.31261

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	5	17 S	36 E					Lea

Latitude N 32-53.179 Longitude 103-18.411

NATURE OF RELEASE

Type of Release Trunk line leak	Volume of Release 0.5 bbs oil and 20 bbls produced water	Volume Recovered 15 bbls water and 15 gallons oil.
Source of Release- Production line	Date and Hour of Occurrence 6/23/09 3:00 PM	Date and Hour of Discovery 6/23/09 @ 3:30 PM
Was Immediate Notice Given? x Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Larry Ridenour	Date and Hour 6/23/09 @ 4:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes x No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* Water course was not impacted.

Describe Cause of Problem and Remedial Action Taken.*
External corrosion on a trunk line.

Describe Area Affected and Cleanup Action Taken.*

Affected equipment was shut in to prevent additional release of material. Area will be sampled and action will be determined after receiving sample results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Kim Klahsen</i>	Approved by District Supervisor:	
Printed Name: <i>Kim Klahsen</i>	Approval Date:	Expiration Date:
Title: <i>HES Specialist</i>	Conditions of Approval:	
E-mail Address: <i>KDKL@chevron.com</i>	Attached <input type="checkbox"/>	
Date: <i>6-24-09</i>	Phone: <i>432-894-3298</i>	