




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1610448552

1RP - 4245

SOUTHERN UNION GAS SERVICES, LTD.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company	Southern Union Gas Services, Ltd.	Contact	Rose Slade
Address	P.O. Box 1226 Jal, N.M. 88252	Telephone No.	432-940-5147
Facility Name	Lea County Field Dept.	Facility Type	Cal "A" line Natural Gas Gathering line

Surface Owner: BLM	Mineral Owner:	Lease No.
--------------------	----------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	3	26	34					Lea

Latitude N32 03.910 Longitude W103 27.358


NATURE OF RELEASE

Type of Release : Crude Oil, Produced water and Natural Gas	Volume of Release: 15 bbls.	Volume Recovered: 8 bbls.
Source of Release : 16" Natural Gas Pipeline	Date and Hour of Occurrence not known	Date and Hour of Discovery 12/14/09 5:15 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Robert	
By Whom? Rose Slade	Date and Hour: 12/14/09 at 10:15 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.*
The 16" Natural gas pipeline developed a leak due to external corrosion operating at approximately 30 psi on the pipeline. The line was clamped and will be replaced at a later time.

Describe Area Affected and Cleanup Action Taken: The affected area was approximately 19' wide by 69' in length. The environmental consultant will remediate the area affected and provide OCD with the required documentation for closure on this site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Rose L. Slade	Approved by District Supervisor:	
Title: EHS Compliance Specialist	Approval Date:	Expiration Date:
E-mail Address: rose.slade@sug.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/11/2010	Phone: 432-940-5147 (cell)	

* Attach Additional Sheets If Necessary