

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 14 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 10101020594

0137

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company	Contact Brett Fulks, EHS Professional
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 432.301.3223
Facility Name Grandi 22-3	Facility Type Gas

Surface Owner	Mineral Owner	API No 30-015-33922
----------------------	----------------------	----------------------------

LOCATION OF RELEASE

Unit Letter A	Section 22	Township 22S	Range 27E	Feet from the 660	North/South Line FNL	Feet from the 1210	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: Longitude:

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release Unknown	Volume Recovered : 0
Source of Release Produced water line to SWD was damaged by third party <i>12/15/15</i>	Date and Hour of Occurrence <i>12/15/2016 12:00PM</i>	Date and Hour of Discovery 3/18/2016 12:00PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
On July 2nd of 2015, Blue Wally Construction submitted a One Call Ticket for installing a sprinkler system for a private home owner. Devon Energy's line locating department responded with positive response by flagging the line and requesting in the notes that Blue Wally Construction contact Devon Energy so that a representative could be present to witness the dig. Blue Wally Construction failed to contact Devon Energy as requested and installed the sprinkler system at some point. In December of 2015, Devon Energy produced through the line to a commercial SWD for a short duration of time. In March of 2016, the home owner contacted Devon Energy, believing that the line had developed a leak due to staining in his yard. Devon Energy pressured the line on 3/18/16 to identify if and exactly where the leak was. Then on 3/21/16, Devon excavated a small area around the line to identify how the line had failed. A cut into the line was identified right underneath the sprinkler system line that was routed over the top of the line. Currently the exact volumes that were released from the line are unknown.

Describe Area Affected and Cleanup Action Taken.*
The area affected is a private residential yard at the approximate coordinate of: Lat:32.383947 Lon:104.168534 in WGS84. An environmental remediation company will be contacted to delineate and remediate the spill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brett Fulks</i>	OIL CONSERVATION DIVISION	
Printed Name: Brett Fulks	Signed By: <i>Mike Lawrence</i>	
Title: EHS Professional	Approved by Environmental Specialist:	
E-mail Address: brett.fulks@dmv.com	Approval Date: <i>4/15/16</i>	Expiration Date: <i>N/A</i>
Date: 04/07/2016 Phone: 432-301-3223	Conditions of Approval:	
	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 5/15/16**

2RP-3647

Bratcher, Mike, EMNRD

From: Fulks, Brett <Brett.Fulks@dnv.com>
Sent: Thursday, April 14, 2016 2:46 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: Grandi #2H Disposal Line Damage C-141
Attachments: Grandi 2H Disposal Line Damage C-141.pdf

Good Afternoon,

Heather, per our conversation on the phone today, attached please find the initial C-141 for the produced water release at the on the SWD line for the Grandi #2 well.

If you have any questions please feel free to contact me.

Thanks,

Brett Fulks
EHS Representative

Devon Energy Corporation
6488 Seven Rivers Highway
Artesia, New Mexico 88210
575 748 1844 Direct
432 301 3223 Mobile



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.