

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 19 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1611050323

OPERATOR

Initial Report Final Report

Name of Company	CAZA Operating, LLC <i>249099</i>	Contact	Robert Gilbert
Address	200 N Loraine, Midland Tx	Telephone No.	575-390-0690
Facility Name	Forehand Ranch 27 State Com 1H	Facility Type	Production Battery
Surface Owner	Mineral Owner	API No.	30-015-39844

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	27	23S	27E	252'	South	1900'	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	30 bbl	Volume Recovered	0
Source of Release	Bad 1" Valve	Date and Hour of Occurrence	4/17/16 am	Date and Hour of Discovery	2:00 pm 4/17/16
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left message on NMOCD phone.			
By Whom?	Robert Gilbert	Date and Hour	4/18/16 4:37 pm, Monday		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Broken 1" valve. Replaced valve. Made 1 call for backhoe to clean up spill area. One call will clear Thursday morning.
No oil was able to be recovered.

Describe Area Affected and Cleanup Action Taken.*
Spill area was inside dyke and outside dyke on roadway. Small amount off of caliche roadway.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Gilbert</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Gilbert	Approved by Environmental Specialist: <i>Mike Brander</i>	
Title: Field Supervisor	Approval Date: <i>4/19/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: r.gilbert73@gmail.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: 4-18-16 Phone: 575-390-0690	Attached <input type="checkbox"/>	

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 5/20/16 *2RD-3452*

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Skyla and Robert Gilbert <r.sgilbert73@gmail.com>
Sent: Tuesday, April 19, 2016 9:22 AM
To: Bratcher, Mike, EMNRD
Subject: Caza Operating Forehand Ranch 27-1 Spill Notice
Attachments: Forehand Ranch 27-1 Spill Report C-141.pdf