

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION** Form C-141  
ARTESIA DISTRICT Revised August 8, 2011

Submitted Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*DAB/6/11/654086* OPERATOR  Initial Report  Final Report

Name of Company <i>Beach Exploration, Inc. 1903</i>	Contact Jack Rose
Address 800 N. Marienfeld, Suite 200, Midland, TX 79701	Telephone No. 432/683-6226
Facility Name Eastland Queen Unit	Facility Type Waterflood Central Battery

Surface Owner State	Mineral Owner State	API No. 30-015-25655
		Unit Number: 300337

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	1	19S	29E	990	North	990	West	Eddy

Latitude 32.6939° Longitude -104.0338°

**NATURE OF RELEASE**

Type of Release Fresh Water	Volume of Release Est. 210 bbl	Volume Recovered 160 bbl
Source of Release Fresh Water valve washed out	Date and Hour of Occurrence Est 4/20/16 7:15 a.m.	Date and Hour of Discovery 4/20/16 9:45
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Beach Exploration, Inc. from OCD	
By Whom? OCD	Date and Hour 4/20/16 10:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* Inlet Fresh Water motor control valve was being repaired. Supply valve at Rockhouse fresh water well NW1/4 Sec. 3 19S 29E, was pinched back as a valve at the battery was also to limit water entry. Someone opened the Rockhouse valve and all that volume washed out our battery valve.		
Describe Area Affected and Cleanup Action Taken.* Rockhouse supply valve was closed. The fresh water (full stream) comes in at 2000 BWPD. We estimate it was open 2.6 hrs spilling an estimated 215 bbl fresh water. We vacuumed up 160 bbl of fresh water. We also repaired our battery berm and cleaned up our sump.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jack M. Rose</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jack M. Rose	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Engineer	Approval Date: <i>4/25/16</i>	Expiration Date: <i>NIA</i>
E-mail Address: bmartin@beachexp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/22/2016 Phone: 432/683-6226	<i>closure pending</i>	

\* Attach Additional Sheets If Necessary

*OLD inspection*  
Remediation per O.C.D. Rules & Guidelines  
**SUBMIT REMEDIATION PROPOSAL NO**  
**LATER THAN: 5/26/16** *2016-3659*

**Patterson, Heather, EMNRD**

---

**From:** Brenda Martin <bmartin@beachexp.com>  
**Sent:** Friday, April 22, 2016 11:22 AM  
**To:** Patterson, Heather, EMNRD  
**Subject:** RE: More photos and api email 2 of 2  
**Attachments:** C 141 BEACH EXPLORATION INC..pdf  
  
**Importance:** High

Heather,

Our C-141 on fresh water spill is attached. Please let me know if you need a hard copy and/or any changes.

Thank you,

Brenda Martin  
Production  
Beach Exploration, Inc.  
800 North Marienfeld  
Suite 200  
Midland, Texas 79701  
(432) 683-6226 Telephone  
(432) 683-1038 Fax  
e-mail: bmartin@beachexp.com

-----Original Message-----

**From:** Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]  
**Sent:** Wednesday, April 20, 2016 11:28 AM  
**To:** Brenda Martin  
**Subject:** RE: More photos and api email 2 of 2

Thank you Brenda,

I have a meeting and will be out of the office the rest of the day. Feel free to leave a message, or call my cell if you have any updates or questions.

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

-----Original Message-----

**From:** Brenda Martin [mailto:bmartin@beachexp.com]  
**Sent:** Wednesday, April 20, 2016 10:29 AM  
**To:** Patterson, Heather, EMNRD  
**Subject:** RE: More photos and api email 2 of 2

Heather,

We have pumper on the way!! Thank you so much for calling. I will update you after pumper gets back with me and fill out paper work etc.

Thanks

Brenda Martin  
Production  
Beach Exploration, Inc.  
800 North Marienfeld  
Suite 200  
Midland, Texas 79701  
(432) 683-6226 Telephone  
(432) 683-1038 Fax  
e-mail: bmartin@beachexp.com

-----Original Message-----

From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]  
Sent: Wednesday, April 20, 2016 11:13 AM  
To: bmartin@beachexp.com  
Cc: Bratcher, Mike, EMNRD; Naranjo, Mark M.; agroves@slo.state.nm.us; rkasuboski@slo.state.nm.us  
Subject: FW: More photos and api email 2 of 2

A few more pictures.

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

-----Original Message-----

From: Kasuboski, Robert [mailto:rkasuboski@slo.state.nm.us]  
Sent: Wednesday, April 20, 2016 10:02 AM  
To: Patterson, Heather, EMNRD  
Cc: Groves, Amber; Naranjo, Mark M.  
Subject: More photos and api

Found another sign. API 30-015-25655

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---