

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.,
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1612340054 OPERATOR Initial Report Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: BUENA VISTA 2 STATE #001H	Facility Type: Battery
Surface Owner: State	Mineral Owner: State
API No. 30-015-40789	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	02	20S	30E	1130'	South	330'	East	Eddy

Latitude 32.5981522 Longitude -103.9353943

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 8 bbls PW	Volume Recovered: 5 bbls PW
Source of Release: Fittings/Connections	Date and Hour of Occurrence: 4/14/2016 10:00 am	Date and Hour of Discovery: 4/14/2016 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION
ARTESIA DISTRICT
APR 29 2016
RECEIVED**

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a pipe fitting on battery lines. A vacuum truck was dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within the lined containment of the facility. Concho will have the spill site inspected to determine any possible contamination from the release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: 5/2/16	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: April 29, 2016	Phone: 432-683-7443	

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 6/3/16 **2RP-3664**

* Attach Additional Sheets If Necessary.

Patterson, Heather, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Friday, April 29, 2016 12:41 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'agroves@slo.state.nm.us'; 'dvstrang@slo.state.nm.us'; Martin, Ed; Naranjo, Mark M.
Subject: (Notification/C-141 Initial) BUENA VISTA 2 STATE #001H (30-015-40789)
Attachments: 4-14-2016 BUENA VISTA 2 STATE #001H (TB) Initial.pdf

MR. BRATCHER,


COG OPERATING LLC IS REPORTING A RELEASE ON THE BUENA VISTA 2 STATE #001H (30-015-40789)
SECTION 02 TOWNSHIP 20S RANGE 30E
THE RELEASE OCCURRED AT 10:00 AM ON 4/14/2016
RELEASED: 8 BBLs PW
RECOVERED: 5 BBLs PW

THIS RELEASE WAS CAUSED BY A PIPE FITTING ON BATTERY LINES. A VACUUM TRUCK WAS DISPATCHED TO RECOVER ALL STANDING FLUID. THIS RELEASE OCCURRED WITHIN THE LINED CONTAINMENT OF THE FACILITY. ATTACHED IS A C-141 FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

ROBERT GRUBBS JR.
SR. ENVIRONMENTAL COORDINATOR
432.683.7443 (MAIN)
432.818.2369 (DIRECT)
432.661.6601 (CELL)
432.221.0892 (FAX)
RGRUBBS@CONCHO.COM
MAILING ADDRESS:
ONE CONCHO CENTER
600 W. ILLINOIS AVENUE
MIDLAND, TEXAS 79701

CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.