

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0AB1613058084 229137 OPERATOR Initial Report Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.:	432-683-7443
Facility Name:	LOVING I STATE #003	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-015-32446

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	01	24S	27E	1980	North	660	West	Eddy

Latitude 32.6090431 Longitude 104.452919

NATURE OF RELEASE

Type of Release:	Volume of Release:	Oil 1bbl	Volume Recovered:	Oil 1bbl
Oil and Produced Water	Produced Water 35bbls		Produced Water 33bbls	
Source of Release:	Date and Hour of Occurrence:		Date and Hour of Discovery:	
Produced Water Tank	04-26-2016 10:01pm		04-26-2016 10:01pm	
Was Immediate Notice Given?	If YES, To Whom?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Mike Bratcher - NMOCD / Amber Groves - SLO			
By Whom?	Date and Hour:			
Robert Grubbs Jr	04-29-2016 12:35pm			
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				

NM OIL CONSERVATION
ARTESIA DISTRICT
MAY 06 2016

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused by a surface casing valve left open to a line that dumped into the water tank causing it to run over. A vacuum truck was dispatched to remove all free standing fluids.

Describe Area Affected and Cleanup Action Taken.*
Initially 1bbl of oil and 35bbls of produced water were released due to a surface casing valve left open to a line that dumped into the water tank causing it to run over. The valve was closed to prevent this from occurring again. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Approved by Environmental Specialist:		
Robert Grubbs Jr.			
Title:	Approval Date:	Expiration Date:	
Senior Environmental Coordinator	5/6/16	NIA	
E-mail Address:	Conditions of Approval:	Attached <input type="checkbox"/>	
rgrubbs@concho.com			
Date:	Phone:	Remediation per O.C.D. Rules & Guidelines	
05-06-2016	432-683-7443		

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 6/10/16 2RP-3681

Patterson, Heather, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Friday, May 06, 2016 12:11 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'agroves@slo.state.nm.us'; 'dvstrang@slo.state.nm.us'; Martin, Ed; Naranjo, Mark M.
Subject: (C-141 Initial) LOVING 1 STATE #003
Attachments: 04-29-2016 Loving 1 State #003 (TB) Initial.pdf


MR. BRATCHER / MS. GROVES,

ATTACHED IS A C-141 FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME

THANK YOU,

**ROBERT GRUBBS JR.
SR. ENVIRONMENTAL COORDINATOR
432.683.7443 (MAIN)
432.818.2369 (DIRECT)
432.661.6601 (CELL)
432.221.0892 (FAX)
RGRUBBS@CONCHO.COM
MAILING ADDRESS:
ONE CONCHO CENTER
600 W. ILLINOIS AVENUE
MIDLAND, TEXAS 79701**

CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Patterson, Heather, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, April 27, 2016 1:35 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'agroves@slo.state.nm.us'; 'dvstrang@slo.state.nm.us'; Martin, Ed; Naranjo, Mark M.
Subject: (Notification) LOVING 1 STATE #003 (30-015-32446)

MR. BRATCHER,

COG OPERATING LLC IS REPORTING A RELEASE ON THE LOVING 1 STATE #003 (30-015-32446)

UNIT E SECTION 1 TOWNSHIP 24S RANGE 27E

THE RELEASE OCCURRED AT 12:01 PM ON 4/26/2016

RELEASED: 1 BBLs OIL ; 35 BBLs PW


RECOVERED: 1 BBLs OIL ; 33 BBLs PW

THIS RELEASE WAS CAUSED BY A TANK OVERFLOW. THE AREA IS BEING EVALUATED AND A C-141 WILL BE SUBMITTED. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

ROBERT GRUBBS JR.
SR. ENVIRONMENTAL COORDINATOR
432.683.7443 (MAIN)
432.818.2369 (DIRECT)
432.661.6601 (CELL)
432.221.0892 (FAX)
RGRUBBS@CONCHO.COM
MAILING ADDRESS:
ONE CONCHO CENTER
600 W. ILLINOIS AVENUE
MIDLAND, TEXAS 79701

CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained

herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.