

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1613135426

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production <i>LD137</i>	Contact Jake Harrington, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 432-214-5175
Facility Name Cotton Draw Unit 172H	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-42426
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	I	25S	31E	0195	South	1345	East	Eddy

Latitude: 32.090941

Longitude: -103.433837

NATURE OF RELEASE

Type of Release Produced water release	Volume of Release 20bbls	Volume Recovered 0bbls
Source of Release Gasket between the valve & pipe	Date and Hour of Occurrence May 6, 2016 @ 1:30 PM	Date and Hour of Discovery May 6, 2016 @ 1:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Matt Nettles, Asst. Production Foreman	Date and Hour May 6, 2016 @ 2:30 Shelly Tucker, BLM May 6, 2016 @ 2:45 Mike Bratcher, OCD	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

NM OIL CONSERVATION
ARTESIA DISTRICT

MAY 09 2016

RECEIVED

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Gasket blew out on main water line between the valve and the pipe. The valves on each side of the line were immediately shut so the line could be bypassed to stop the water flow. The line is currently out of service waiting on repairs.

Describe Area Affected and Cleanup Action Taken.*
20bbls produced water was released in the right-of-way with 0bbls recovered. The release was in the right-of-way South of location in a 75' x 75' area. All fluid remained in the right-of-way. An environmental agency will be contacted for remediation of the affected area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>5/10/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines checked <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: 5/9/16 Phone: 575.748.1829	LATER THAN: <i>5/10/16</i>	

222-3683

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Monday, May 09, 2016 10:51 AM
To: Shelly Tucker (stucker@blm.gov); Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett; Nettles, Matt; Carter, Ray; Harrington, Jake
Subject: Cotton Draw Unit 172H_20bbl pw release_5.6.16
Attachments: Cotton Draw Unit 172H_20bbl pw release_Initial C-141_5.6.16.doc; Cotton Draw Unit 172H_20bbl pw release_GIS Image_5.6.16.pdf; Cotton Draw Unit 172H_20bbl pw release_pic 1 of 1_5.6.16.jpg

Good Afternoon,

Attached please find the Initial C-141, GIS Image and photos for the 20bbl produced water release at the Cotton Draw Unit 172H.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.