

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 12 2016

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1613733064

OPERATOR

Initial Report Final Report

Name of Company <i>Cimarex Energy</i> <i>11021083</i>	Contact <i>Christine Alderman</i>
Address <i>600 N Marienfeld Ste 600 Midland TX</i>	Telephone No. <i>432-853-7059</i>
Facility Name <i>Park Sate 36 Com #1</i>	Facility Type <i>production</i>

Surface Owner	Mineral Owner	API No. <i>30-015-33963</i>
---------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>I</i>	<i>36</i>	<i>24S</i>	<i>25E</i>	<i>1500</i>	<i>S</i>	<i>1100</i>	<i>E</i>	<i>Eddy</i>

Latitude *32.1705322* Longitude *-104.3443985*

NATURE OF RELEASE

Type of Release <i>produced water</i>	Volume of Release <i>100 bbls</i>	Volume Recovered <i>100 bbls</i>
Source of Release <i>vessel</i>	Date and Hour of Occurrence <i>12/31/2015</i>	Date and Hour of Discovery <i>12/31/2015</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Mike Bratcher/Heather Patterson</i>	
By Whom? <i>Gloria Garza</i>	Date and Hour <i>01/01/2016 4:20 pm</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The dump valve malfunctioned on a vessel causing the release

Describe Area Affected and Cleanup Action Taken.*
The fluids were contained in a LINED containment and were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Christine Alderman</i>	Approved by Environmental Specialist <i>[Signature]</i>	
Title: <i>ESH Supervisor</i>	Approval Date: <i>5/13/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>calderman@cimarex.com</i>	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: <i>01/04/2016</i> Phone: <i>432-853-7059</i>		

* Attach Additional Sheets If Necessary

2RP-3690

Bratcher, Mike, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Thursday, May 12, 2016 8:17 AM
To: Patterson, Heather, EMNRD; Gloria Garza
Cc: Bratcher, Mike, EMNRD; Bustamante, Amalia, EMNRD
Subject: RE: Reportable Spill - Park State 36 COM #1 Eddy County - 12/31/2015
Attachments: 20160512075427339.pdf

My apologies. I did it and didn't scan it in and send it.

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin
Midland TX
Cell – 432.853.7059

From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]
Sent: Wednesday, May 04, 2016 10:56 AM
To: Gloria Garza <ggarza@cimarex.com>
Cc: Christine Alderman <calderman@cimarex.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Bustamante, Amalia, EMNRD <Amalia.Bustamante@state.nm.us>
Subject: RE: Reportable Spill - Park State 36 COM #1 Eddy County - 12/31/2015

Did we get a C-141 for this release?

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Gloria Garza [mailto:ggarza@cimarex.com]
Sent: Friday, January 01, 2016 4:19 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Christine Alderman
Subject: Reportable Spill - Park State 36 COM #1 Eddy County - 12/31/2015

All

We had a release at the Park State 36 Com #1 yesterday 12/31/2015 at approximately 5PM due to a dump valve malfunction on a vessel causing a release of approximately 100 barrels of produced water, all fluids were contained and this facility does have a liner.

Once I get more information I will send in the C-141.

API Number: 3001533963

ULSTR: I-36-24S-25E

Footages 1500 FSL & 1100 FEL

Well Name & Number: PARK STATE 36 COM No. 001

Operator: CIMAREX ENERGY CO. OF COLORADO

UL or Lot	Section	Township	Range	Lot #	Feet From	N/S Line	Feet From	E/W Line	County
1	36	24S	25E	1	1500	S	1100	E	Eddy

Please call if you have any questions.

Gloria Garza
ES&H Specialist
432.234.3204