

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAY 19 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1614428823

157984

OPERATOR

Initial Report Final Report

Name of Company OCCIDENTAL PERMIAN LTD	Contact JENNIFER DUARTE
Address PO BOX 4294; HOUSTON, TX 77210	Telephone No. 713-513-6640
Facility Name EEYORE 34 STATE #1 SATTALITE BATTERY	Facility Type BATTERY
Surface Owner STATE	Mineral Owner STATE
API No. 30-015-39383	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	34	17S	28E	738	NORTH	488	EAST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release GAS - FLARE	Volume of Release 364 MCF	Volume Recovered 0 MCF
Source of Release GAS - FLARE	Date and Hour of Occurrence 05/18/2016 - BEGIN	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* FLARING DUE TO DCP CURTIALMENT.		
Describe Area Affected and Cleanup Action Taken.*		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Duarte</i>	OIL CONSERVATION DIVISION	
Printed Name: JENNIFER DUARTE	Approved by Environmental Specialist: <i>Mike L...</i>	
Title: ENVIRONMENTAL SPECIALIST	Approval Date: <i>5/20/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: jennifer_duarte@oxy.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 05/19/2016 Phone: 713-513-6640	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: *05/24/16*

JRP-3702

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Jennifer_Duarte@oxy.com
Sent: Thursday, May 19, 2016 4:38 PM
To: Bratcher, Mike, EMNRD
Subject: Flaring C141s
Attachments: Scanned from a Xerox Multifunction Device001.pdf; Scanned from a Xerox Multifunction Device002.pdf; Scanned from a Xerox Multifunction Device003.pdf

Please see that attached.

Thank you,
Jennifer Duarte
Environmental Specialist
713-513-6640