

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
MAR 23 2010
NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NAB 1614439861 *279579* OPERATOR Initial Report Final Report

Name of Company BP America Production Company	Contact Steve Pacheco
Address PO Box 129 Artesia, NM 88210	Telephone No. 575-677-3642
Facility Name Riverwolf Unit No. 10	Facility Type Oil Well
Surface Owner BLM	Mineral Owner BLM
Lease No. API # 3001500639	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	35	17S	27E	410		2235		Eddy

Latitude *32.7845001* Longitude *-104.248085*

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release Unknown	Volume Recovered Unknown
Source of Release Riverwolf Unit # 10 Well Bore	Date and Hour of Occurrence Unknown	Date and Hour of Discovery October 27, 2009
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Well was plugged by BP America Production Company, March 2009. Historical release found when new lessee was preparing to re-enter well, October 2009. Impacted soil was removed by Talon/LPE (working for BP) and disposed of at Lea Land Landfill. The site was backfilled with clean dirt. Activities were coordinated with Jim Amos, BLM, and Mike Bratcher, OCD.

Describe Area Affected and Cleanup Action Taken.*

Area impacted was approximately 20 ft x 10 ft x 12 ft deep immediately around the Riverwolf Unit #10 well bore. The area was excavated to hard bedrock and properly disposed. Clean fill was returned to the excavation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Steve M. Pacheco</i>	OIL CONSERVATION DIVISION	
Printed Name: Steve M. Pacheco	Approved by District Supervisor: <i>[Signature]</i>	
Title: Southeast New Mexico Team Lead	Approval Date: <i>5/20/10</i>	Expiration Date: <i>N/A</i>
E-mail Address: Steve.Pacheco@bp.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/> <i>2RP-3707</i>
Date: 3/4/2010	Phone: 575-677-3642	

* Attach Additional Sheets If Necessary