

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 07 2016

Form C-141
Revised August 8, 2011

District I
1625 N French Dr., Hobbs, NM 88240
District II
811 S First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1616054652

OPERATOR

Initial Report Final Report

Name of Company: <i>COG Operating LLC</i> <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: WILLOW 17 STATE SWD #001	Facility Type: SWD

Surface Owner: State	Mineral Owner:	API No. 30-015-41806
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	17	25S	28E	660'	South	660'	East	Eddy

Latitude 32.1243935 Longitude -104.1029892

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15 bbls PW	Volume Recovered: 0 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 5/27/2016 Unknown	Date and Hour of Discovery: 5/27/2016 2:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused by a check valve on a poly flowline. The broken check valve was replaced.

Describe Area Affected and Cleanup Action Taken.*
This release occurred in the pasture on the north edge of the facility and is approximately 0.1 acre in size. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert McNeill</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert McNeill	Signed By <i>Mike Brannon</i> Approved by Environmental Specialist:	
Title: Environmental Manager	Approval Date: <i>6/8/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: rmcneill@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: June 6, 2016 Phone: 432-230-0077	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>6/11/16</i>	

* Attach Additional Sheets If Necessary

ARP-3721

Bratcher, Mike, EMNRD

From: Robert McNeill <RMcNeill@concho.com>
Sent: Tuesday, June 07, 2016 2:29 PM
To: Bratcher, Mike; EMNRD; Patterson, Heather, EMNRD; Groves, Amber; Strang, Dana V.; Martin, Ed; Naranjo, Mark M.
Subject: Willow 17 State SWD #1 - C141
Attachments: 5-27-2016 Willow 17 State SWD #1 (FL) Initial.pdf

Mr. Bratcher/Ms. Groves,

COG Operating LLC is reporting a release on the Willow 17 State SWD #1 (30-015-41806)
Unit P Section 17 Township 25S Range 28E
The release occurred at 2:00 pm on 5/27/2016
Released: 15 bbls PW
Recovered: 0 bbls PW

This release was caused by a check valve on a poly flowline. The broken check valve was replaced. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Robert McNeill, P. E.
Environmental Manager
COG Operating LLC

One Concho Center
600 West Illinois Avenue
Midland, TX 79701
Office 432.221.0388
Cell 432.638.6470

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.