

JUN 07 2016

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submitted to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

*NAB1416126496*

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Hasta La Vista 1 DI Federal Com 001H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42533
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	5	20S	31E	100	North	2330	East	Eddy

Latitude 32.609315° Longitude -103.890512°

**NATURE OF RELEASE**

Type of Release	Crude Oil	Volume of Release	9 bbls	Volume Recovered	0 bbls
Source of Release	Flare	Date and Hour of Occurrence	5/26/2016 time unknown	Date and Hour of Discovery	5/26/2016 10:15 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Flare scrubber loaded up causing fluid to exit flare.

Describe Area Affected and Cleanup Action Taken.\*  
Leak affected 34,600 sq. ft. of pasture to the east of the flare due to high winds. Area was washed down with microblaze on morning of 5/27/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amy C. Ruth</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy C. Ruth	Signed By: <i>Mike [Signature]</i> Approved by Environmental Specialist:	
Title: EHS Remediation Specialist	Approval Date: <i>6/8/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: ACRuth@basspct.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/>	
Date: 6/7/2016 Phone: 432-661-0571	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: 7/9/16 *2RP-3725*

## Bratcher, Mike, EMNRD

---

**From:** Ruth, Amy C. <ACRuth@BassPet.Com>  
**Sent:** Tuesday, June 07, 2016 10:48 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Tucker, Shelly  
**Subject:** Initial C-141 - Hasta La Vista 1 DI Federal Com 001H 5-26-16  
**Attachments:** Initial C-141 HLV 1 DI Fed Com 001H 5-26-16.pdf; Initial Photo.jpg

All,

Here is an initial form C-141 for an accidental flare release at our Drill Island #4 just off south Hwy 222. The flare scrubber associated with the Hasta La Vista 1 DI Federal Com 001H loaded up and caused fluid to exit the flare. Winds carried a mist to the east. Microblaze was applied the following morning. We will have the same environmental contractor follow through with sampling, any additional remediation, and closure activities. Thank you and have a good day.



*Amy C. Ruth*

BOPCO, L.P.

EH&S Remediation Specialist

522 W. Mermod, Suite 704

Carlsbad, NM 88220

Office: (575)887-7329

Fax: (575)887-7473

Cell: (432)661-0571