

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUN 13 2016
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

~~NAB1614038811~~

Release Notification and Corrective Action

~~NAB1616628416~~

246289

OPERATOR

Initial Report Final Report

Name of Company	WPX Energy Inc/ RKI E&P, LLC	Contact	Lucas Smith
Address	3500 One Williams Center Tulsa, OK 74172	Telephone No.	817-727-9716
Facility Name:	East Pecos 22-3 Produced water Gathering Line	Facility Type :	PW Gathering System

Surface Owner:	Federal	Mineral Owner:	Federal	API No.	N/A
----------------	---------	----------------	---------	---------	-----

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	35	26S	29E	330	FNL	1750	FWL	Eddy

Latitude: 32.004234 N Longitude: -103.955950 W

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15 Bbls	Volume Recovered: 0 Bbls
Source of Release ESD at central water gathering shut in putting back pressure on line	Date and Hour of Occurrence 06/09/16	Date and Hour of Discovery 06/09/16 - 1400hrs MT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Spoke to Heather Patterson NMOCD and Jim Amos BLM	
By Whom? Lucas Smith	Date and Hour: 06/09/16- 1400hrs MT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

Line ruptured releasing produced water onto BLM right-of-way.

Describe Area Affected and Cleanup Action Taken.*

Produced water followed the path of the previous spill and stayed within the BLM pipeline right-of-way. NMOCD Incident #nAB1614039576. Developing workplan to address both releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Lucas J. Smith		OIL CONSERVATION DIVISION	
Printed Name: Lucas Smith		Approved by Environmental Specialist: 	
Title: EHS Manager		Approval Date: 6/14/16	Expiration Date: N/A
E-mail Address: Lucas.smith@wpxenergy.com		Conditions of Approval:	
Date: 06/13/16 Phone: 817-727-9716		Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7/14/16	

Attached

* Attach Additional Sheets If Necessary

202-3734

Patterson, Heather, EMNRD

From: Smith, Lucas <Lucas.Smith@wpxenergy.com>
Sent: Monday, June 13, 2016 8:18 AM
To: rpair@blm.gov; Patterson, Heather, EMNRD
Subject: WPX Energy/RKI E&P C-141 (East Pecos 22-3 produced water gathering line rupture) #2
Attachments: NM_Polyline_InitialC141(060916).doc

Heather/Randy, please see the attached C-141 for the East Pecos 22-3 produced water gathering line splice separation. The spill area is within the spill we had occur on 15 May 2016. Enviroclean was working on the workplan for that incident; plan to add this to the workplan. Previous spill: NMOCD Incident #nAB1614039576.

Coordinates: **Latitude:** 32.004234 N **Longitude:** -103.955950 W

Lucas Smith
Environmental Health and Safety Manager
WPXENERGY

539-573-0176 (Office)
817-727-9716 (Cell)
lucas.smith@wpxenergy.com

Quote: "In any moment of decision, the best thing you can do is the right thing. The worst thing you can do is nothing." *Theodore Roosevelt 26th U.S. President*

From: Smith, Lucas
Sent: Wednesday, May 18, 2016 9:45 AM
To: 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: RE: WPX Energy/RKI E&P C-141 (East Pecos 22-3 produced water gathering line rupture)

Lucas Smith
Environmental Health and Safety Manager
WPXENERGY

539-573-0176 (Office)
817-727-9716 (Cell)
lucas.smith@wpxenergy.com

Quote: "In any moment of decision, the best thing you can do is the right thing. The worst thing you can do is nothing." *Theodore Roosevelt 26th U.S. President*

From: Smith, Lucas

Sent: Wednesday, May 18, 2016 9:44 AM

To: 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>

Subject: WPX Energy/RKI E&P C-141 (East Pecos 22-3 produced water gathering line rupture)

Ladies, please see attached C-141. We have asked Enviroclean to collect samples and prepare a scope of work. Please feel free to give me a call if you have any questions (Please call cell #). Thank you both for your assistance!

Lucas Smith
Environmental Health and Safety Manager
WPXENERGY.

539-573-0176 (Office)
817-727-9716 (Cell)
lucas.smith@wpxenergy.com

Quote: "In any moment of decision, the best thing you can do is the right thing. The worst thing you can do is nothing." *Theodore Roosevelt 26th U.S. President*