

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUN 16 2016

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1616930688

6/13/16 OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company	Contact Danny Velo, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-703-3360
Facility Name Parkway West SWD #1	Facility Type Salt Water Disposal
Surface Owner State	Mineral Owner State
API No 30-015-42687	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	19S	29E	1255	North	430	West	Eddy

Latitude: 32.6354904 **Longitude:** -104.0698929

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 10 BBLS	Volume Recovered 10 BBLS
Source of Release Discharge pump line	Date and Hour of Occurrence 6/13/2016 @ 9:25pm	Date and Hour of Discovery 6/13/2016 @ 9:25pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher	
By Whom? David Simmons, Assistant Production Foreman	Date and Hour OCD- 6/13/2016 @ 9:35pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*
Corrosion occurred in the water discharge pump line resulting in a release of 10 BBLS produced water. The well and water injection pump was shut down immediately to prevent further release. Repairs to discharge pump line are in progress.

Describe Area Affected and Cleanup Action Taken.*
10 BBLS of produced water was released from a corroded discharge pump line that runs from the produced water tanks. All 10 BBLS of produced water released remained in concrete containment. None of the released fluid left location. Vacuum truck recovered all 10 BBLS of the released produced water. No further action is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: 6/17/16	Expiration Date: N/A
E-mail Address: Sarah.Gallegos-Troublefield@dvn.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 6/16/2016 Phone: 575.748.1864		

* Attach Additional Sheets If Necessary

2RP-3746

Patterson, Heather, EMNRD

From: Gallegos-Troublefield, Sarah <Sarah.Gallegos-Troublefield@dv.com>
Sent: Thursday, June 16, 2016 9:28 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett; Scrogum, Sandy
Subject: Parkway West SWD 1_10 BBLs PW_6-13-2016_Initial & Final C-141
Attachments: Parkway West SWD 1_10 BBLs PW_6-13-2016_Pic 2 of 3.jpeg; Parkway West SWD 1_10 BBLs PW_6-13-2016_Pic 3 of 3.jpeg; Parkway West SWD 1_10 BBLs PW_6-13-2016_GIS Image.pdf; Parkway West SWD 1_10 BBLs PW_6-13-2016_Initial & Final C-141.doc; Parkway West SWD 1_10 BBLs PW_6-13-2016_Pic 1 of 3.jpeg

Good Morning,

Please find attached the Initial & Final C-141, GIS Image and 3 photos of the Parkway West SWD #1 release of 10 BBLs produced water that occurred on 6/13/2016. Please be advised that the blue dot in the GIS Image represents the approximate location of the origin of the release.
Please contact me with any questions you may have.

Thank you and have a great day.

Respectfully,

Sarah Gallegos-Troublefield
Field Admin Support
Production

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 748 1864 Direct Line



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.