

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 01 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1618838854

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>102463</i>	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Government NBFD Battery, East Oil Tank	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No. 30-015-28841

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	11	20S	28E					Eddy County, NM

Latitude N 32.58240° Longitude W 104.15550°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20 bbls	Volume Recovered	0 bbls
Source of Release	Hole in the bottom of a tank	Date and Hour of Occurrence	06/21/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	06/21/2016 @ 4:12 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A hole in the bottom of the tank caused 20 bbls of produced water to leak onto the ground. No fluids were recovered and the tank was repaired.


Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 20' x 20' on location inside the lined containment. Remediation will be completed by removing the affected material and replacing it with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.


OIL CONSERVATION DIVISION

Signature:



Printed Name: Casey Summers

Approved by Environmental Specialist:



Title: NM Environmental Advisor

Approval Date: *7/6/16*

Expiration Date: *N/A*

E-mail Address: Casey_Summers@oxy.com

Conditions of Approval: Remediation per O.C.D. Rules & Guidelines

Date: *7-1-16*

Phone: (575) 513-8289

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: *8/1/16*

2RP-3762

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Friday, July 01, 2016 8:35 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: Casey_Summers@oxy.com; dusty_wilson@oxy.com; 'Cliff P. Brunson'; 'Ken Swinney'; jennifer_duarte@oxy.com; 'Jennifer Gilkey'
Subject: Initial C-141, Government NBF D Battery, East Oil Tank
Attachments: Initial C-141, Government NBF D E Oil Tank.pdf

Attached is the initial C-141 for a leak that occurred at the Government NBF D Battery, East Oil Tank on 06/21/2016 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland Blvd.
Hobbs, NM 88240
Business: (575) 397-6388
Cell: (575) 441-8619
kathy@bbcinternational.com

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Tuesday, June 21, 2016 4:12 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: Casey_Summers@oxy.com; dusty_wilson@oxy.com; jennifer_duarte@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; kathy@bbcinternational.com
Subject: Government Nbfd Battery, East Oil Tank 65758

This is to inform you that Oxy Permian had a leak at the Government Nbfd Battery at the East Oil Tank 65758 on June 21, 2016 in Eddy County, NM. Oxy released 20 bbls of produced water due to a hole in the bottom of the tank. The preliminary report indicates the leak measures 6' x 6' inside the lined containment on location. No fluids were recovered. The release is located in the SW ¼ of Section 11, T20S, R28E of Eddy County, NM. Driving directions: From Carlsbad, go east on US62/180 for 8 miles, turn left on Magnum Rd and go north 6 miles, turn left on Burton Flats Rd and go 1.7 miles, turn right on Buckskin Rd and go north 1 mile, turn left on lease road and go west 0.75 mile, turn 500 ft before the 3 way and location is on the left side of the road. GPS coordinates are not available at this time. API#30-015-28841

Kathy Purvis

BBC International, Inc.
1324 W. Marland Blvd.
Hobbs, NM 88240
Business: (575) 397-6388
Cell: (575) 441-8619
kathy@bbcinternational.com