

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1418849965 **Release Notification and Corrective Action**
F.JMW1333735410

OPERATOR Initial Report Final Report

Name of Company <i>Enterprise Field Services LLC 1000347</i>	Contact <i>Alena Miro</i>
<i>PO Box 4324, Houston, TX 77210</i>	Telephone No. <i>575-706-4926</i>
Facility Name <i>Pipeline ROW, 1003</i>	Facility Type: <i>Gas Gathering Pipeline</i>
Surface Owner <i>Henry McDonald</i>	Mineral Owner <i>NA - Pipeline</i>
Lease No. <i>NA</i>	

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>D</i>	<i>13</i>	<i>25S</i>	<i>28E</i>	<i>85</i>	<i>South</i>	<i>310</i>	<i>East</i>	<i>Eddy</i>

Latitude: *N 32.134004* Longitude: *W -104.046157*

NATURE OF RELEASE

Type of Release <i>Natural Gas and pipeline liquid</i>	Volume of Release: <i>892 MCF gas</i>	Volume Recovered: <i>N/A</i>
Source of Release <i>Pipeline Leak</i>	Date and Hour of Occurrence <i>6/25/2016 @ 11:30 MST</i>	Date and Hour of Discovery <i>6/25/2016 @ 11:30 MST</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Heather Patterson</i>	
By Whom? <i>Alena Miro</i>	Date and Hour <i>6/25/2016 @ 19:30 MST</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <i>Natural gas was released due to a pipeline leak. Pipeline segment was isolated, blown down, and repaired following standard one-call</i>		
Describe Area Affected and Cleanup Action Taken.*		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <i>Jon E. Fields</i>	Approved by District Supervisor: 	
Title: <i>Director, Field Environmental</i>	Approval Date: <i>7/1/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>jefields@egrod.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: <i>7/1/2016</i> Phone: <i>713-381-6684</i>		

* Attach Additional Sheets If Necessary

2RP-3763

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 01 2016

RECEIVED