

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011  
JUL 06 2016  
Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

*NAB1619027879*

**OPERATOR**

Initial Report  Final Report

<b>Name of Company</b> Devon Energy Production Company <i>6137</i>		<b>Contact</b> Matt Nettles, Production Foreman	
<b>Address</b> 6488 Seven Rivers Hwy Artesia, NM 88210		<b>Telephone No.</b> 575.513.5767	
<b>Facility Name</b> Belloq 2 State 5H		<b>Facility Type</b> Oil Well	
<b>Surface Owner State</b>		<b>Mineral Owner State</b>	
		<b>API No</b> 30-015-42896	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	2	23S	31E	200	FNL	1670	FWL	Eddy

**Latitude:** 32.34007062

**Longitude:** -103.75175405

**NATURE OF RELEASE**

<b>Type of Release</b> Produced Water (pw)	<b>Volume of Release</b> 7BBLS	<b>Volume Recovered</b> 5BBLS
<b>Source of Release</b> Waterline from heater to the storage tank	<b>Date and Hour of Occurrence</b> 7/1/2016 @ 7:30AM	<b>Date and Hour of Discovery</b> 7/1/2016 @ 7:30AM
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> NMOCD- Mike Bratcher	
<b>By Whom?</b> Leonard Aguilar, Assistant Production Foreman	<b>Date and Hour</b> NMOCD- 7/1/2016 @ 10:20AM	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse</b> N/A	

**If a Watercourse was Impacted, Describe Fully.\***  
N/A

**Describe Cause of Problem and Remedial Action Taken.\***  
7BBLS of produced water was released from the waterline that runs from the heater treater to the water storage tank due to a pin hole. The waterline was isolated to prevent further release. Repairs have been made to the line.

**Describe Area Affected and Cleanup Action Taken.\***  
7BBLS of pw was released as a result of waterline that failed. The release flowed in a southeastern direction and did not leave pad. 5BBLS of pw was recovered via vacuum truck. The approximate size of the total affected area was a 20ft by 20ft. An environmental company will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b> <i>Dana DeLaRosa</i>	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Dana DeLaRosa	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
<b>Title:</b> Field Admin Support	Approval Date: <i>7/8/16</i>	Expiration Date: <i>N/A</i>
<b>E-mail Address:</b> dana.delarosa@dvn.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	
<b>Date:</b> 7-6-2016 <b>Phone:</b> 575.746.5594	<b>LATER THAN:</b> <i>8/8/16</i> <span style="float: right;"><i>ARD-3766</i></span>	

\* Attach Additional Sheets If Necessary

**Bratcher, Mike, EMNRD**

---

**From:** DeLaRosa, Dana <Dana.DeLaRosa@dvn.com>  
**Sent:** Wednesday, July 06, 2016 2:09 PM  
**To:** Bratcher, Mike, EMNRD; agroves@slo.state.nm.us  
**Subject:** Belloq 2 State 5H\_7BBLS PW Release\_7.1.2016  
**Attachments:** Belloq 2 State 5H\_7BBLS PW\_7.1.2016.pdf; Belloq 2 State 5H\_7BBLS\_7.1.2016\_Pic 1 of 3.JPG; Belloq 2 State 5H\_7BBLS\_7.1.2016\_Pic 2 of 3.JPG; Belloq 2 State 5H\_7BBLS\_7.1.2016\_Pic 3 of 3.JPG; Belloq 2 State 5H\_7BBLSPW Release\_7.1.2016\_Intial C141.doc

Good afternoon,

Attached is the Initial C141, GIS Image and photos for the 7BBL produced water release that occurred on 7.1.2016 at the Belloq 2 State 5H. The red dot on the GIS Image represents the approximate origin of release.

Thank you,

*Dana DeLaRosa*

Field Admin Support  
Production  
B-Schedule



Devon Energy Corporation  
PO Box 250  
Artesia, NM 88211  
575-746-5594

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.