

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Plains Pipeline LP	Contact: Camille Bryant
Address: 2530 State HWY. 214, Denver City, TX 79323	Telephone No.: (575) 441-1099
Facility Name: New McKee Jct. Sump (IRP-3841)	Facility Type: Sump
Surface Owner: BLM	Mineral Owner:
Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	29	20S	38E					Lea

Latitude: N32.54213° Longitude: W103.17194°

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 40 bbls	Volume Recovered: 35 bbls
Source of Release: Sump	Date and Hour of Occurrence: 8/28/2015 @09:00	Date and Hour of Discovery: 8/28/2015 @09:25
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Verbal notification to Kellie Jones	
By Whom? Camille Bryant	Date and Hour: 8/28/2015 15 @ 15:04	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Check valve failed causing the sump to overflow, resulting in the release of crude oil
Describe Area Affected and Cleanup Action Taken: The released crude oil impacted an area measuring approximately 30' x 60' inside the facility the released fluids then flowed west impacted an area measuring approximately 60' x 100'.

Remediation activities at the release site were conducted in accordance with the NMOCD and BLM. Impacted soil was excavated and transported to an NMOCD permitted disposal facility. Laboratory analytical results from confirmation soil samples collected from the floor and sidewalls of the excavated area within the affected pasture indicated TPH concentrations where less than NMOCD Recommended Remediation Action Levels in each of the submission soil samples. Impacted soil within the affected portion of the facility was excavated to the maximum extent practicable, given the presence of numerous above and below ground pipelines as per the NMOCD.

Please reference the attached Remediation Summary and Closure Report for additional remediation details and the results of laboratory analysis from confirmation soil samples.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
	Approved by NMOCD: 	
Printed Name: Camille Bryant	Approval Date: 7/19/16	Expiration Date: _____
Title: Remediation Coordinator	Conditions of Approval: _____	
E-mail Address: cjbrant@paapple.com	Attached <input type="checkbox"/> IRP 3841	
Date: _____ Phone: (575) 441-1099		

* Attach Additional Sheets If Necessary