

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION Form C-141
ARTESIA DISTRICT Revised August 8, 2011
Submittal by 2016 appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 11619 738827

Name of Company: Linn Energy <i>2109324</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 2130 W Bender, Hobbs, NM 88240		Contact: EL Gonzales		
Facility Name: Turner B #082		Telephone No. 575-738-1739		
		Facility Type: Oil Producer		
Surface Owner: Federal		Mineral Owner: Federal	API No. 30-015-26385	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from	East/West Line	County
J	29	17S	31E	2550	South	1335	East	Eddy

Latitude: 32.80523284 Longitude: -103.8876114

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: Unknown	Volume Recovered: 0
Source of Release: Flow line	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 05/03/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On May 3, 2011, A BLM inspection of the site discovered a flowline leak in the road. A surface inspection form was submitted. On October 20, 2011, a second inspection of the site resulted in a secondary surface inspection form submitted.

Describe Area Affected and Cleanup Action Taken.

On June 23, 2016, DFSI personnel were on site to obtain samples within both of the leak areas. Within the release area, five samples were obtained and field sampled for chloride levels, as well as BTEX. The BTEX samples were performed using a Mini Rae Photoionization Detector (PID). All clean field samples under NMOCD and BLM regulatory guidelines were submitted for laboratory analysis at Cardinal Laboratories of Hobbs, NM to obtain confirmation, resulting in concentrations that decreased with depth.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: EL Gonzales	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Production Supervisor	Approval Date: 7/14/16	Expiration Date: N/A
E-mail Address: elgonzales@linnenergy.com	Conditions of Approval: <i>work plan approval</i>	Attached <input type="checkbox"/>
Date: 7/12/2016 Phone: 575-504-8002	<i>on 7/13/16</i>	

* Attach Additional Sheets If Necessary

2RP-3779

Patterson, Heather, EMNRD

From: Laura Flores <lflores@diversifiedfsi.com>
Sent: Tuesday, July 12, 2016 8:59 AM
To: Patterson, Heather, EMNRD
Cc: Gonzales, EL; Tucker, Shelly; Bratcher, Mike, EMNRD; Michael Burton; jamos@blm.gov
Subject: RE: Linn - Turner B #082 (11NU092TG) Work Plan
Attachments: Linn - Turner B #082 - Initial C-141.pdf

Good morning, Ms. Patterson.

Attached is a signed Initial C-141 for this site.

Please let me know if you have any questions.

Thank you,
Laura

-----Original Message-----

From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]
Sent: Monday, July 11, 2016 1:54 PM
To: Gonzales, EL <ELgonzales@linnenergy.com>; Tucker, Shelly (stucker@blm.gov) <stucker@blm.gov>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Cc: Michael Burton <mburton@diversifiedfsi.com>; Laura Flores <lflores@diversifiedfsi.com>; Amos, James (jamos@blm.gov) <jamos@blm.gov>
Subject: RE: Linn - Turner B #082 (11NU092TG) Work Plan

EL,

Did your turn in a C-141 for this event? I can't find one in our records.

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

-----Original Message-----

From: Gonzales, EL [mailto:ELgonzales@linnenergy.com]
Sent: Thursday, June 30, 2016 2:02 PM
To: Tucker, Shelly (stucker@blm.gov); Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Michael Burton (mburton@diversifiedfsi.com); Laura Flores; Amos, James (jamos@blm.gov)
Subject: FW: Linn - Turner B #082 (11NU092TG) Work Plan

Good Afternoon, Here is a work plan for your review and approval----- Thanks, E L

-----Original Message-----

From: Laura Flores [mailto:lflores@diversifiedfsi.com]
Sent: Thursday, June 30, 2016 8:53 AM
To: Gonzales, EL
Cc: Michael Burton
Subject: Linn - Turner B #082 (11NU092TG) Work Plan

Good morning, Mr. Gonzales.

Attached is the work plan for the Linn Turner B #082 (BLM Event No. 11NU092TG) site.

Thank you,

Laura Flores
Environmental Department
Diversified Field Service, Inc.
206 W Snyder | Hobbs, NM 88240
Phone: 575.964.8394 | Fax: 575.393.8396

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.