

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Pure Resources	Contact Larry D. Ridenour
Address HCR 60 Box 423 Lovington, NM 88260	Telephone No. 505.396.4414 x102
Facility Name Lovington Paddock Unit	Facility Type Test Station #7

Surface Owner City of Lovington	Mineral Owner State of New Mexico	Lease No. B1563
---------------------------------	-----------------------------------	-----------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	1	17S	36E					Lea

Latitude _____ Longitude _____ GW = 50+

NATURE OF RELEASE

Type of Release oil and produced water	Volume of Release 1 bbl oil 23 bbl water	Volume Recovered .5 bbl oil 20 bbl water
Source of Release header	Date and Hour of Occurrence 3/9/06 7:30 AM	Date and Hour of Discovery 3/9/06 9:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Capeton	
By Whom? Larry Williams	Date and Hour 3/9/06 10:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Nipple in header broke due to excessive stress from expansion on lines leading into the header.
Nipple replaced and line redone to relieve stress.

Describe Area Affected and Cleanup Action Taken.*

Vacuum truck picked up fluid.
Contaminated soil at header replaced with fresh soil.



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Williams</i>	OIL CONSERVATION DIVISION	
Printed Name: Larry Williams	Approved by District Supervisor:	
Title: HES Coordinator	Approval Date:	Expiration Date:
E-mail Address: LCWL@Chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/16/06	Phone: 505-394-1237	

* Attach Additional Sheets If Necessary

facility - FPAC 0607925495
incident - NPAC 0607925594

application - FPAC 0607925791