

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUL 21 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DAB11021045402

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Banjo BNO Federal #1	Facility Type Battery	

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-36923
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter P	Section 5	Township 26S	Range 30E	Feet from the 510	North/South Line South	Feet from the 330	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.06576 Longitude 103.89553

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 100 B/PW	Volume Recovered 100 B/PW
Source of Release Water Pump	Date and Hour of Occurrence 5/19/2016; AM	Date and Hour of Discovery 5/19/2016; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 5/20/2016; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The union on the discharge side of the water pump vibrated loose, causing the release. Vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 130' X 30' within the lined/bermed battery. Wells were shut off, the union on the pump was repaired and all produced water was recovered using a vacuum truck. Depth to Ground Water: > 100' (approximately 225', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on the battery being lined/bermed, all of the released water recovered; Yates Petroleum Corporation requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By:  Approved by Environmental Specialist.	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>7/25/16</u>	Expiration Date: <u>NIA</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>
Date: July 21, 2016	Phone: 575-748-4217	2RP-

* Attach Additional Sheets If Necessary

2RP-3794

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Thursday, July 21, 2016 12:59 PM
To: Bratcher, Mike, EMNRD
Subject: Form C-141 Initial/Final Report (5-19-2016)
Attachments: Banjo BNO Federal 1 (C141 05192016 Initial Final).pdf; Banjo BNO Federal 1 (05192016 C141).pdf

Mike,

Per our telephone conversation this morning, Yates is submitting the attached C-141, Initial/Final Report. I have also attached the C-141 that I signed and scanned on 5/27/2016, but was not submitted to your office.

Thank you.

Robert Asher
Sr. Environmental Supervisor
Health & Environmental Department
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)
Yates Safety Begins With YOUR Safety

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
