

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUL 25 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1621055488

OPERATOR

Initial Report Final Report

Name of Company <i>Devon Energy Production Company 10/37</i>		Contact <i>Matt Nettles, Production Foreman</i>
Address <i>6488 Seven Rivers Hwy Artesia, NM 88210</i>		Telephone No. <i>575.513-5767</i>
Facility Name <i>North Pure Gold 9 Federal 1</i>		Facility Type <i>Oil Well</i>
Surface Owner <i>Federal</i>	Mineral Owner <i>Federal</i>	API No <i>30-015-27178</i>

LOCATION OF RELEASE

Unit Letter <i>N</i>	Section <i>9</i>	Township <i>23S</i>	Range <i>31E</i>	Feet from the <i>330</i>	North/South Line <i>FSL</i>	Feet from the <i>1980</i>	East/West Line <i>FWL</i>	County <i>Eddy</i>
-------------------------	---------------------	------------------------	---------------------	-----------------------------	--------------------------------	------------------------------	------------------------------	-----------------------

Latitude: 32.3125916

Longitude: -103.7849503

NATURE OF RELEASE

Type of Release <i>Produced Water (PW) & Oil</i>	Volume of Release <i>3BBLS PW & 2BBLS Oil</i>	Volume Recovered <i>0BBLS</i>
Source of Release <i>Hole in the flowline</i>	Date and Hour of Occurrence <i>7/24/2016 @ 9:20AM</i>	Date and Hour of Discovery <i>7/24/2016 @ 9:20AM</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>OCD-Mike Bratcher BLM-Shelly Tucker</i>	
By Whom? <i>Leonard Aguilar, Assistant Production Foreman</i>	Date and Hour <i>OCD-7/24/2016 @ 10:03AM BLM-7/24/2016 @ 10:00AM</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse <i>N/A</i>	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
3BBLS PW and 2BBLS Oil was released due to a hole in the flowline located directly where the poly flowline transitions into metal pipe. The well was shut in and the valve at the heater was isolated to prevent further release. Repairs have been made.

Describe Area Affected and Cleanup Action Taken.*
3BBLS PW and 2BBLS Oil were released with 0BBLS recovered. The release originated from the poly flowline near the header on location and flowed in a Southwestern direction leaving pad into pasture. The approximate size of the total area affected on pad was 15ft by 15ft. The total affected area off pad was 10ft by 65ft. An environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dana DeLaRosa</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Dana DeLaRosa</i>	Signed By <i>Mike Bratcher</i>	
Title: <i>Field Admin Support</i>	Approved by Environmental Specialist:	Approval Date: <i>7/26/16</i> Expiration Date: <i>N/A</i>
E-mail Address: <i>dana.delarosa@dvn.com</i>	Remediation per O.C.D. Rules & Guidelines	
Date: <i>7/25/2016</i> Phone: <i>575.746.5594</i>	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>8/1/16</i> Attached <input type="checkbox"/> <i>ARP-3805</i>	

Bratcher, Mike, EMNRD

From: DeLaRosa, Dana <Dana.DeLaRosa@dvn.com>
Sent: Monday, July 25, 2016 2:39 PM
To: Tucker, Shelly; Bratcher, Mike, EMNRD
Subject: North Pure Gold 9 Federal 1_3BBL PW and 2BBL Oil_7.24.16
Attachments: North Pure Gold 9 Federal 1_3BBL PW & 2BBL Oil_7.24.16_Initial C141.doc; North Pure Gold 9 Federal 1_3BBL PW & 2BBL Oil_7.24.16_GIS Image.pdf; Pic 1 of 3.jpg; Pic 2 of 3.jpg; Pic 3 of 3.jpg

Attached is the Initial C141, GIS Image and photos for the 3BBL PW and 2 BBL Oil release on the North Pure Gold 9 Federal 1. The red dot on the GIS Image represents the approximate origin of release.

Dana DeLaRosa

Field Admin Support
Production
B-Schedule



Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575-746-5594

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.