

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

State of New Mexico
Energy Minerals and Natural Resources

JUL 27 2016 Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Federal 13 #2	Facility Type	production

Surface Owner	fed	Mineral Owner		API No.	30-015-33344
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	13	25S	26E	1565	S	1400	W	Eddy

Latitude 32.12696 Longitude -104.25042

NATURE OF RELEASE

Type of Release	oil	Volume of Release	40 bbls	Volume Recovered	30 bbls
Source of Release	tank	Date and Hour of Occurrence	07/25/2016	Date and Hour of Discovery	07/25/2016
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Shelly Tucker		
By Whom?	Christine Alderman	Date and Hour	07/27/2016		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.
A welded seam at the bottom of the tank developed a hole

Describe Area Affected and Cleanup Action Taken.
The oil was released into a lined/dirt filled containment. The impacted soils within the containment will be removed and replaced. No fluids were lost to surrounding ground.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Signed By: <i>[Signature]</i> Approved by Environmental Specialist	
Title: ESH Supervisor	Approval Date: 7/28/16	Expiration Date: N/A
E-mail Address: calderman@cimarex.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 07/27/2016 Phone: 432-853-7059		

* Attach Additional Sheets If Necessary

2 RD-3809

Bratcher, Mike, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Wednesday, July 27, 2016 8:35 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Subject: Federal 13#2 (API 30-015-33344)
Attachments: 20160727092935595.pdf

All,

We had a release at the above named lease. Approximately 40 bbls of oil was released from a steel tank. A welded area on the bottom of the tank developed a hole due to corrosion. All fluids were contained in a lined, caliche filled containment. The impacted soils within the containment will be removed and replaced.

C-141 attached.

Please let me know if you need further information. Thank you.

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin
Midland TX
Cell – 432.853.7059