

3R-1013

**Release Report/ General
Correspondence**

Williams SJ

Date: Apr-Jun 2016

②

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

APR 05 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Mitch Morris
Address 1755 Arroyo Drive, Bloomfield, NM 87413	Telephone No. 505-632-4708
Facility Name Buena Vista	Facility Type Compressor Station
Surface Owner Bureau of Land Management	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	32	24N	8W					San Juan

Latitude 36.2756 Longitude -107.698

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 328.51 MCF	Volume Recovered 0 MCF
Source of Release Valve	Date and Hour of Occurrence 3/14/2016, 10:00 AM	Date and Hour of Discovery 3/14/2016, 10:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

A valve on an inlet scrubber was inadvertently left open, allowing natural gas to vent at the hydrocarbon liquid storage tank. The valve was closed as soon as this discovery was made, eliminating the gas release to atmosphere.

Describe Area Affected and Cleanup Action Taken.*

No cleanup required with gas release to atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Mitch Morris	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 4/6/16	Expiration Date:
E-mail Address: mitch.morris@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: March 28, 2016	Phone: 505-632-4708	

* Attach Additional Sheets If Necessary

#NCS16097 32211

①

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 11 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Matt Webre
Address 1755 Arroyo Drive, Bloomfield, NM 87413	Telephone No. 505-632-4442
Facility Name Milagro Gas Plant	Facility Type Gas Treating Plant
Surface Owner Private	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	12	29N	11W					San Juan

Latitude 36.735966° N Longitude -107.942329° W

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 59 MCF	Volume Recovered 0 MCF
Source of Release Regulator/Valve	Date and Hour of Occurrence 02/04/16 at 1:31 PM MST	Date and Hour of Discovery 02/04/16 at 1:31 PM MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour NA	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Operator discovered regulator leaking on inlet sample location at Milagro Train 5. Line was no longer needed so removed line and returned valve to service. The release was estimated to have occurred over a period of 3 weeks. Approximately 59 MCF was released from the line into atmosphere.

Describe Area Affected and Cleanup Action Taken.*

No clean-up required for natural gas releases vented to atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Matt Webre	Approved by Environmental Specialist: 	
Title: EH&S Supervisor	Approval Date: 5/2/2016	Expiration Date:
E-mail Address: matt.webre@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 03/31/2016	Phone: 505-632-4442	

* Attach Additional Sheets If Necessary

NUF1605437593



District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Monica Sandoval
Address 1755 Arroyo Drive, Bloomfield, NM 87413	Telephone No. 505-632-4625
Facility Name Lateral N-2	Facility Type Pipeline
Surface Owner Federal- Middle Mesa Wildlife Area	Mineral Owner API No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	32	32N	6W					San Juan

Latitude 36.9379 Longitude -107.4811

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 250 MCF	Volume Recovered 0
Source of Release Drip tank blowing to atmosphere	Date and Hour of Occurrence 5/03/2016, 8:59AM MST	Date and Hour of Discovery 5/03/2016, 8:59AM MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Not Applicable	OIL CONS. DIV DIST. 3 MAY 18 2016
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not Applicable	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Williams's personnel were notified by a producer that a drip tank was blowing to atmosphere, upon notification Williams personnel asked producer to close valve. Williams's personnel then headed to location and was able to determine that cows had recently been moved to the area and a cow had bumped a valve open. To prevent reoccurrence Williams's personnel removed the valve from the piping.

Describe Area Affected and Cleanup Action Taken.*
No cleanup required with a gas release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica Sandoval</i>	OIL CONSERVATION DIVISION	
Printed Name: Monica Sandoval	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: <i>05/20/2016</i>	Expiration Date:
E-mail Address: Monica.Sandoval@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/13/2016 Phone: 505-632-4625		

* Attach Additional Sheets If Necessary

NMF1614135459

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Mitch Morris
Address 1755 Arroyo Dr, Bloomfield, NM 87413	Telephone No. 505-632-4708
Facility Name Trunk Q Pipeline	Facility Type Natural Gas Gathering Pipeline
Surface Owner BLM	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	28	26N	08W					San Juan

Latitude 36.34484° N Longitude -107.66087° W

NATURE OF RELEASE

Type of Release Condensate and Natural Gas	Volume of Release Approximately 5 bbls Condensate and 140 MCF of Natural Gas	Volume Recovered Approx. 5 bbls of condensate
Source of Release Pipeline	Date and Hour of Occurrence 04/22/16 at 11:30 AM MST	Date and Hour of Discovery 04/22/16 at 11:30 AM MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Not Applicable	
By Whom?	Date and Hour OIL CONS. DIV DIST. 3	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not Applicable	

MAY 18 2016

If a Watercourse was Impacted, Describe Fully.*
Not Applicable

Describe Cause of Problem and Remedial Action Taken.*
Williams Operations Technician was driving in the vicinity of the Trunk Q Pipeline and noticed a leak. The pipeline was immediately shut-in and blown down to atmospheric pressure.

Describe Area Affected and Cleanup Action Taken.*
A crew was immediately dispatched to commence cleanup and repair of the pipeline. Attached are the soil analytical results demonstrating that concentrations are below the NMOCD cleanup standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		OIL CONSERVATION DIVISION	
Signature: 	Approved by Environmental Specialist: 		
Printed Name: Mitch Morris	Approval Date: <u>5/20/2016</u> Expiration Date:		
Title: Environmental Specialist	Conditions of Approval:		
E-mail Address: Mitch.Morris@williams.com			Attached <input type="checkbox"/>
Date: 05/06/2016	Phone: 505-632-4708		

* Attach Additional Sheets If Necessary

NVF 1614137666

11



Hall Environmental Analysis Laboratory
4901 Hawkins NE
Albuquerque, NM 87109
TEL: 505-345-3975 FAX: 505-345-4107
Website: www.hallenvironmental.com

May 05, 2016

Mitch Morris

Williams Field Services

188 Co. Rd 4900

Bloomfield, NM 87413

TEL:

FAX

RE: Trunk Q Line Leak

OrderNo.: 1605107

Dear Mitch Morris:

Hall Environmental Analysis Laboratory received 3 sample(s) on 5/4/2016 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent. To access our accredited tests please go to www.hallenvironmental.com or the state specific web sites. In order to properly interpret your results it is imperative that you review this report in its entirety. See the sample checklist and/or the Chain of Custody for information regarding the sample receipt temperature and preservation. Data qualifiers or a narrative will be provided if the sample analysis or analytical quality control parameters require a flag. When necessary, data qualifiers are provided on both the sample analysis report and the QC summary report, both sections should be reviewed. All samples are reported, as received, unless otherwise indicated. Lab measurement of analytes considered field parameters that require analysis within 15 minutes of sampling such as pH and residual chlorine are qualified as being analyzed outside of the recommended holding time.

Please don't hesitate to contact HEAL for any additional information or clarifications.

ADHS Cert #AZ0682 -- NMED-DWB Cert #NM9425 -- NMED-Micro Cert #NM0190

Sincerely,

A handwritten signature in black ink, appearing to read 'Andy Freeman', is written over a light blue horizontal line.

Andy Freeman

Laboratory Manager

4901 Hawkins NE

Albuquerque, NM 87109

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Williams Field Services

Client Sample ID: Trunk Q Side Comp Site

Project: Trunk Q Line Leak

Collection Date: 5/3/2016 10:20:00 AM

Lab ID: 1605107-001

Matrix: SOIL

Received Date: 5/4/2016 7:55:00 AM

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORGANICS						Analyst: KJH
Diesel Range Organics (DRO)	ND	9.3		mg/Kg	1	5/4/2016 12:08:07 PM
Surr: DNOP	99.0	70-130		%Rec	1	5/4/2016 12:08:07 PM
EPA METHOD 8015D: GASOLINE RANGE						Analyst: NSB
Gasoline Range Organics (GRO)	ND	4.4		mg/Kg	1	5/4/2016 10:06:46 AM
Surr: BFB	92.6	80-120		%Rec	1	5/4/2016 10:06:46 AM
EPA METHOD 8021B: VOLATILES						Analyst: NSB
Benzene	ND	0.022		mg/Kg	1	5/4/2016 10:06:46 AM
Toluene	ND	0.044		mg/Kg	1	5/4/2016 10:06:46 AM
Ethylbenzene	ND	0.044		mg/Kg	1	5/4/2016 10:06:46 AM
Xylenes, Total	ND	0.087		mg/Kg	1	5/4/2016 10:06:46 AM
Surr: 4-Bromofluorobenzene	93.4	80-120		%Rec	1	5/4/2016 10:06:46 AM
EPA METHOD 300.0: ANIONS						Analyst: LGT
Chloride	63	30		mg/Kg	20	5/4/2016 11:39:45 AM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:	* Value exceeds Maximum Contaminant Level.	B Analyte detected in the associated Method Blank
	D Sample Diluted Due to Matrix	E Value above quantitation range
	H Holding times for preparation or analysis exceeded	J Analyte detected below quantitation limits
	ND Not Detected at the Reporting Limit	P Sample pH Not In Range
	R RPD outside accepted recovery limits	RL Reporting Detection Limit
	S % Recovery outside of range due to dilution or matrix	W Sample container temperature is out of limit as specified

Analytical Report

Lab Order 1605107

Date Reported: 5/5/2016

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Williams Field Services

Client Sample ID: Trunk Q Bottom Comp Site

Project: Trunk Q Line Leak

Collection Date: 5/3/2016 10:30:00 AM

Lab ID: 1605107-002

Matrix: SOIL

Received Date: 5/4/2016 7:55:00 AM

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORGANICS						Analyst: KJH
Diesel Range Organics (DRO)	ND	9.8		mg/Kg	1	5/4/2016 12:30:35 PM
Surr: DNOP	100	70-130		%Rec	1	5/4/2016 12:30:35 PM
EPA METHOD 8015D: GASOLINE RANGE						Analyst: NSB
Gasoline Range Organics (GRO)	ND	4.1		mg/Kg	1	5/4/2016 10:30:11 AM
Surr: BFB	93.4	80-120		%Rec	1	5/4/2016 10:30:11 AM
EPA METHOD 8021B: VOLATILES						Analyst: NSB
Benzene	ND	0.021		mg/Kg	1	5/4/2016 10:30:11 AM
Toluene	ND	0.041		mg/Kg	1	5/4/2016 10:30:11 AM
Ethylbenzene	ND	0.041		mg/Kg	1	5/4/2016 10:30:11 AM
Xylenes, Total	ND	0.083		mg/Kg	1	5/4/2016 10:30:11 AM
Surr: 4-Bromofluorobenzene	93.9	80-120		%Rec	1	5/4/2016 10:30:11 AM
EPA METHOD 300.0: ANIONS						Analyst: LGT
Chloride	ND	30		mg/Kg	20	5/4/2016 11:52:10 AM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:	* Value exceeds Maximum Contaminant Level.	B Analyte detected in the associated Method Blank
	D Sample Diluted Due to Matrix	E Value above quantitation range
	H Holding times for preparation or analysis exceeded	J Analyte detected below quantitation limits
	ND Not Detected at the Reporting Limit	P Sample pH Not In Range
	R RPD outside accepted recovery limits	RL Reporting Detection Limit
	S % Recovery outside of range due to dilution or matrix	W Sample container temperature is out of limit as specified

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Williams Field Services
Project: Trunk Q Line Leak
Lab ID: 1605107-003

Matrix: SOIL

Client Sample ID: Trunk Q Off of Row
Collection Date: 5/3/2016 10:45:00 AM
Received Date: 5/4/2016 7:55:00 AM

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed
EPA METHOD 8015M/D: DIESEL RANGE ORGANICS						Analyst: KJH
Diesel Range Organics (DRO)	14	9.5		mg/Kg	1	5/4/2016 12:52:31 PM
Surr: DNOP	98.8	70-130		%Rec	1	5/4/2016 12:52:31 PM
EPA METHOD 8015D: GASOLINE RANGE						Analyst: NSB
Gasoline Range Organics (GRO)	ND	4.4		mg/Kg	1	5/4/2016 10:53:34 AM
Surr: BFB	94.9	80-120		%Rec	1	5/4/2016 10:53:34 AM
EPA METHOD 8021B: VOLATILES						Analyst: NSB
Benzene	ND	0.022		mg/Kg	1	5/4/2016 10:53:34 AM
Toluene	ND	0.044		mg/Kg	1	5/4/2016 10:53:34 AM
Ethylbenzene	ND	0.044		mg/Kg	1	5/4/2016 10:53:34 AM
Xylenes, Total	ND	0.089		mg/Kg	1	5/4/2016 10:53:34 AM
Surr: 4-Bromofluorobenzene	95.4	80-120		%Rec	1	5/4/2016 10:53:34 AM
EPA METHOD 300.0: ANIONS						Analyst: LGT
Chloride	ND	30		mg/Kg	20	5/4/2016 12:04:35 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:	* Value exceeds Maximum Contaminant Level.	B Analyte detected in the associated Method Blank
	D Sample Diluted Due to Matrix	E Value above quantitation range
	H Holding times for preparation or analysis exceeded	J Analyte detected below quantitation limits
	ND Not Detected at the Reporting Limit	P Sample pH Not In Range
	R RPD outside accepted recovery limits	RL Reporting Detection Limit
	S % Recovery outside of range due to dilution or matrix	W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605107

05-May-16

Client: Williams Field Services

Project: Trunk Q Line Leak

Sample ID	MB-25147	SampType:	MBLK	TestCode:	EPA Method 300.0: Anions					
Client ID:	PBS	Batch ID:	25147	RunNo:	34005					
Prep Date:	5/4/2016	Analysis Date:	5/4/2016	SeqNo:	1047798	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Chloride	ND	1.5								

Sample ID	LCS-25147	SampType:	LCS	TestCode:	EPA Method 300.0: Anions					
Client ID:	LCSS	Batch ID:	25147	RunNo:	34005					
Prep Date:	5/4/2016	Analysis Date:	5/4/2016	SeqNo:	1047799	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Chloride	14	1.5	15.00	0	94.3	90	110			

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605107

05-May-16

Client: Williams Field Services

Project: Trunk Q Line Leak

Sample ID	LCS-25140	SampType:	LCS	TestCode:	EPA Method 8015M/D: Diesel Range Organics					
Client ID:	LCSS	Batch ID:	25140	RunNo:	33966					
Prep Date:	5/4/2016	Analysis Date:	5/4/2016	SeqNo:	1047132	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	46	10	50.00	0	93.0	65.8	136			
Surr: DNOP	4.7		5.000		94.2	70	130			

Sample ID	MB-25140	SampType:	MBLK	TestCode:	EPA Method 8015M/D: Diesel Range Organics					
Client ID:	PBS	Batch ID:	25140	RunNo:	33966					
Prep Date:	5/4/2016	Analysis Date:	5/4/2016	SeqNo:	1047133	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	ND	10								
Surr: DNOP	9.8		10.00		97.9	70	130			

Sample ID	1605107-001AMS	SampType:	MS	TestCode:	EPA Method 8015M/D: Diesel Range Organics					
Client ID:	Trunk Q Side Comp	Batch ID:	25140	RunNo:	33966					
Prep Date:	5/4/2016	Analysis Date:	5/4/2016	SeqNo:	1047158	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	51	9.5	47.71	0	108	33.9	141			
Surr: DNOP	4.6		4.771		95.4	70	130			

Sample ID	1605107-001AMSD	SampType:	MSD	TestCode:	EPA Method 8015M/D: Diesel Range Organics					
Client ID:	Trunk Q Side Comp	Batch ID:	25140	RunNo:	33966					
Prep Date:	5/4/2016	Analysis Date:	5/4/2016	SeqNo:	1047160	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	51	9.8	48.88	0	105	33.9	141	0.409	20	
Surr: DNOP	4.6		4.888		94.7	70	130	0	0	

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix

- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605107

05-May-16

Client: Williams Field Services

Project: Trunk Q Line Leak

Sample ID MB-25130	SampType: MBLK	TestCode: EPA Method 8015D: Gasoline Range								
Client ID: PBS	Batch ID: 25130	RunNo: 33977								
Prep Date: 5/3/2016	Analysis Date: 5/4/2016	SeqNo: 1047281			Units: mg/Kg					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	ND	5.0								
Surr: BFB	910		1000		91.4	80	120			

Sample ID LCS-25130	SampType: LCS	TestCode: EPA Method 8015D: Gasoline Range								
Client ID: LCSS	Batch ID: 25130	RunNo: 33977								
Prep Date: 5/3/2016	Analysis Date: 5/4/2016	SeqNo: 1047282			Units: mg/Kg					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	22	5.0	25.00	0	86.8	80	120			
Surr: BFB	970		1000		97.2	80	120			

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix

- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605107

05-May-16

Client: Williams Field Services


Project: Trunk Q Line Leak

Sample ID	MB-25130	SampType:	MBLK	TestCode:	EPA Method 8021B: Volatiles					
Client ID:	PBS	Batch ID:	25130	RunNo:	33977					
Prep Date:	5/3/2016	Analysis Date:	5/4/2016	SeqNo:	1047315	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	ND	0.025								
Toluene	ND	0.050								
Ethylbenzene	ND	0.050								
Xylenes, Total	ND	0.10								
Surr: 4-Bromofluorobenzene	0.93		1.000		92.9	80	120			

Sample ID	LCS-25130	SampType:	LCS	TestCode:	EPA Method 8021B: Volatiles					
Client ID:	LCSS	Batch ID:	25130	RunNo:	33977					
Prep Date:	5/3/2016	Analysis Date:	5/4/2016	SeqNo:	1047316	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	1.0	0.025	1.000	0	100	75.3	123			
Toluene	0.93	0.050	1.000	0	93.3	80	124			
Ethylbenzene	0.88	0.050	1.000	0	88.0	82.8	121			
Xylenes, Total	2.6	0.10	3.000	0	87.2	83.9	122			
Surr: 4-Bromofluorobenzene	0.93		1.000		93.4	80	120			

Qualifiers:

- | | |
|---|---|
| * Value exceeds Maximum Contaminant Level. | B Analyte detected in the associated Method Blank |
| D Sample Diluted Due to Matrix | E Value above quantitation range |
| H Holding times for preparation or analysis exceeded | J Analyte detected below quantitation limits |
| ND Not Detected at the Reporting Limit | P Sample pH Not In Range |
| R RPD outside accepted recovery limits | RL Reporting Detection Limit |
| S % Recovery outside of range due to dilution or matrix | W Sample container temperature is out of limit as specified |



Hall Environmental Analysis Laboratory
 4901 Hawkins NE
 Albuquerque, NM 87109
 TEL: 505-345-3975 FAX: 505-345-4107
 Website: www.hallenvironmental.com

Sample Log-In Check List

Client Name: WILLIAMS FIELD SERVI

Work Order Number: 1605107

RcptNo: 1

Received by/date: CM 05/04/16

Logged By: Anne Thorne 5/4/2016 7:55:00 AM

Anne Thorne

Completed By: Anne Thorne 5/4/2016

Anne Thorne

Reviewed By: JA 05/04/16

Chain of Custody

- 1. Custody seals intact on sample bottles? Yes No Not Present
- 2. Is Chain of Custody complete? Yes No Not Present
- 3. How was the sample delivered? Courier

Log In

- 4. Was an attempt made to cool the samples? Yes No NA
- 5. Were all samples received at a temperature of >0° C to 6.0°C Yes No NA
- 6. Sample(s) in proper container(s)? Yes No
- 7. Sufficient sample volume for indicated test(s)? Yes No
- 8. Are samples (except VOA and ONG) properly preserved? Yes No
- 9. Was preservative added to bottles? Yes No NA
- 10. VOA vials have zero headspace? Yes No No VOA Vials
- 11. Were any sample containers received broken? Yes No
- 12. Does paperwork match bottle labels? Yes No
(Note discrepancies on chain of custody)
- 13. Are matrices correctly identified on Chain of Custody? Yes No
- 14. Is it clear what analyses were requested? Yes No
- 15. Were all holding times able to be met? Yes No
(If no, notify customer for authorization.)

of preserved bottles checked for pH: _____
 (<2 or >12 unless noted)

Adjusted? _____

Checked by: _____

Special Handling (if applicable)

- 16. Was client notified of all discrepancies with this order? Yes No NA

Person Notified: _____ Date: _____

By Whom: _____ Via: eMail Phone Fax In Person

Regarding: _____

Client Instructions: _____

17. Additional remarks:

18. Cooler Information

Cooler No	Temp °C	Condition	Seal Intact	Seal No	Seal Date	Signed By
1	1.4	Good	Yes			

Chain-of-Custody Record

Client: WFS

Mailing Address: 188 CR4900

Bloomfield NM 87413

Phone #: 505-632-4708

Email or Fax #: mitch.morris@williams.com

QA/QC Package:
 Standard Level 4 (Full Validation)

Credentiation:
 NELAP Other _____

EDD (Type) _____

Turn-Around Time: Same Day

Standard Rush 5-4-16

Project Name: TRUNK & LINE LEAK


Project #: _____

Project Manager: Mitch Morris

Sampler: Morgan Killion

On Ice: Yes No

Sample Temperature: 14



HALL ENVIRONMENTAL ANALYSIS LABORATORY

www.hallenvironmental.com

4901 Hawkins NE - Albuquerque, NM 87109

Tel. 505-345-3975 Fax 505-345-4107

Analysis Request

Date	Time	Matrix	Sample Request ID	Container Type and #	Preservative Type	HEAL No.	BTEX + MIBE + IMBs (8021)	BTEX + MTBE + TPH (Gas only)	TPH 8015B (GRO / DRO / MRO)	TPH (Method 418.1)	EDB (Method 504.1)	PAH's (8310 or 8270 SIMS)	RCRA 8 Metals	Anions (F, Cl, NO ₃ , NO ₂ , PO ₄ , SO ₄)	8081 Pesticides / 8082 PCB's	8260B (VOA)	8270 (Semi-VOA)	Chloride	Air Bubbles (Y or N)	
5/16	1020	Soil	TRUNK & side composite	1-402	COOL	1105107	X	X											X	
5/16	1030	Soil	TRUNK & Bottom composite	1-402	L	202	X	X											X	
5/16	1045	Soil	TRUNK & OFF OF ROW	1-402	L	203	X	X											X	

Date: 5/16 Time: 1535 Relinquished by: Morgan Killion Received by: Christina Watten Date: 5/3/16 Time: 1535

Date: 3/16 Time: 1940 Relinquished by: Christina Watten Received by: [Signature] Date: 05/03/16 Time: 0755

Remarks: _____

If necessary, samples submitted to Hall Environmental may be subcontracted to other accredited laboratories. This serves as notice of this possibility. Any sub-contracted data will be clearly notated on the analytical report.

AT 05/04/16

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 11 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Williams Four Corners LLC	Contact: Mitch Morris
Address: Arroyo 1755 Arroyo Drive, Bloomfield, NM 87413	Telephone No.: (505) 632-4606
Facility Name: Chaco Compressor Station	Facility Type: Compressor Station
Surface Owner: BLM	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	27	29N	11W					San Juan

Latitude 36.690708° N Longitude -107.978413° W

NATURE OF RELEASE

Type of Release: Condensate	Volume of Release: 8 BBL condensate	Volume Recovered: 8 BBL condensate
Source of Release: Storage vessel	Date and Hour of Occurrence: Estimated 03/23/2016 at 10:10 AM MST	Date and Hour of Discovery: Estimated 03/23/2016 at 10:10 AM MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Not Applicable



Describe Cause of Problem and Remedial Action Taken.*

Williams personnel discovered a release of condensate due to hauling company missing a scheduled unloading event. Approximately 10 BBLs of condensate was released into the lined secondary containment at the station. The released condensate was removed with a vacuum truck.

Describe Area Affected and Cleanup Action Taken.*

There were no observed issues observed with the secondary containment liner. The condensate was removed from the lined secondary containment, therefore no further action is required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Matt Webre	Approved by Environmental Specialist: 	
Title: EH&S Supervisor	Approval Date: 3/31/2016	Expiration Date:
E-mail Address: matt.webre@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 04/07/2016	Phone: (505) 632-4442	

* Attach Additional Sheets If Necessary

NUF1615253786

1

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Mitch Morris
Address 1755 Arroyo Drive, Bloomfield, NM 87413	Telephone No. 505-632-4708
Facility Name Kutz Canyon Gas Plant	Facility Type Natural Gas Processing Plant
Surface Owner Bureau of Land Management	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter D	Section 13	Township 28N	Range 11W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------------------

Latitude 36° 40.064 N Longitude 107° 57.795 W

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 226.908 MCF	Volume Recovered 0
Source of Release Pressure Relief Valve (PRV)	Date and Hour of Occurrence 5/01/2016, 04:16 AM MST	Date and Hour of Discovery 5/01/2016, 04:16 AM MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Not Applicable	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not Applicable	

OIL CONS. DIV DIST. 3

If a Watercourse was Impacted, Describe Fully.*

MAY 18 2016

Describe Cause of Problem and Remedial Action Taken.*
A high liquid level in the inlet filter separator caused loss of compression at Kutz Plant. Compression loss caused the tailgate of the Kutz I process to enter recycle mode. A Pressure Relief Valve (PRV) opened when one of the processing vessels reached over-pressure conditions. Pressure Relief Valves (PRV) are designed to open at a predetermined set point to protect the integrity of equipment and ensure safe operating conditions. When compression was re-established, pressures in the plant normalized allowing the PRV to close automatically.

Describe Area Affected and Cleanup Action Taken.*
No cleanup required with a gas release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Mitch Morris	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 06/07/2016	Expiration Date:
E-mail Address: Mitch.Morris@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/06/2016 Phone: 505-632-4708		

* Attach Additional Sheets If Necessary

NVF 1618937683

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

APR 25 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Mitch Morris
Address 1755 Arroyo Dr, Bloomfield, NM 87413	Telephone No. 505-632-4708
Facility Name Crow Mesa Compressor Station	Facility Type Compressor Station
Surface Owner State of NM	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter E	Section 02	Township 24N	Range 08W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------------------

Latitude 36.34484° N Longitude -107.66087° W

NATURE OF RELEASE

Type of Release Condensate and Natural Gas	Volume of Release Approximately 10 bbls Condensate and 1,604 MCF of Natural Gas	Volume Recovered 8 bbls Condensate and Produced water mixture from secondary containment
Source of Release Storage Tank	Date and Hour of Occurrence 02/29/16 at 06:30 PM MST	Date and Hour of Discovery 02/29/16 at 06:30 PM MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith and Vanessa Fields, NMOCD	
By Whom? Kelsey Christiansen	Date and Hour 03/01/16 at 3:45 PM MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not Applicable	

If a Watercourse was Impacted, Describe Fully.*
Not Applicable


Describe Cause of Problem and Remedial Action Taken.*

While bringing the compressor units online at the Crow Mesa Compressor Station, a dump valve was inadvertently left open and caused overpressure gas to be routed to the onsite condensate tank. At some point during the night, liquids overran the tank and a portion of the liquids sprayed outside of the secondary containment. Gas loss was calculated to be approximately 1,604 MCF and it was estimated that 8 bbls of liquids were released inside the lined secondary containment and 2 bbls of liquids outside of the secondary containment. Cleanup crew was immediately mobilized to location and was able to hand excavate and construct temporary earthen berms to prevent potential runoff before remediation could commence.

Describe Area Affected and Cleanup Action Taken.*

The secondary containment liner was inspected and demonstrated integrity. Therefore, the release did not impact soils beneath the lined secondary containment. Impacted soil was removed and two confirmation soil samples were collected on March 14 and 15, 2016. One sample was collected from the area impacted within the facility and one from the area outside the facility. Attached are the soil analytical results demonstrating that concentrations are below the NMOCD cleanup standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: 	
Printed Name: Mitch Morris	Approval Date: 4/27/2016	Expiration Date:
Title: Environmental Specialist	Conditions of Approval:	
E-mail Address: Mitch.Morris@williams.com	Attached <input type="checkbox"/>	
Date: 04/21/2016	Phone: 505-632-4708	

* Attach Additional Sheets If Necessary

NVF 1608234490





Hall Environmental Analysis Laboratory
4901 Hawkins NE
Albuquerque, NM 87109
TEL: 505-345-3975 FAX: 505-345-4107
Website: www.hallenvironmental.com

March 16, 2016

Kelsey Christiansen
Williams Field Services
188 Co. Rd 4900
Bloomfield, NM 87413
TEL: (505) 632-4442
FAX

RE: Crow Mesa CDP Inside Fence

OrderNo.: 1603698

Dear Kelsey Christiansen:

Hall Environmental Analysis Laboratory received 1 sample(s) on 3/15/2016 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent. To access our accredited tests please go to www.hallenvironmental.com or the state specific web sites. In order to properly interpret your results it is imperative that you review this report in its entirety. See the sample checklist and/or the Chain of Custody for information regarding the sample receipt temperature and preservation. Data qualifiers or a narrative will be provided if the sample analysis or analytical quality control parameters require a flag. When necessary, data qualifiers are provided on both the sample analysis report and the QC summary report, both sections should be reviewed. All samples are reported, as received, unless otherwise indicated. Lab measurement of analytes considered field parameters that require analysis within 15 minutes of sampling such as pH and residual chlorine are qualified as being analyzed outside of the recommended holding time.

Please don't hesitate to contact HEAL for any additional information or clarifications.

ADHS Cert #AZ0682 -- NMED-DWB Cert #NM9425 -- NMED-Micro Cert #NM0190

Sincerely,

A handwritten signature in black ink, appearing to read "Andy Freeman".

Andy Freeman
Laboratory Manager
4901 Hawkins NE
Albuquerque, NM 87109

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Williams Field Services
Project: Crow Mesa CDP Inside Fence
Lab ID: 1603698-001

Client Sample ID: Crow Mesa cdp Inside Fence
Collection Date: 3/14/2016 1:15:00 PM
Received Date: 3/15/2016 8:00:00 AM

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed	Batch
EPA METHOD 300.0: ANIONS							Analyst: LGT
Chloride	ND	30		mg/Kg	20	3/15/2016 11:19:36 AM	24265
EPA METHOD 8015M/D: DIESEL RANGE ORGANICS							Analyst: KJH
Diesel Range Organics (DRO)	ND	9.9		mg/Kg	1	3/15/2016 10:49:41 AM	24246
Surr: DNOP	84.6	70-130		%Rec	1	3/15/2016 10:49:41 AM	24246
EPA METHOD 8015D: GASOLINE RANGE							Analyst: NSB
Gasoline Range Organics (GRO)	ND	3.7		mg/Kg	1	3/15/2016 8:43:35 AM	24232
Surr: BFB	107	66.2-112		%Rec	1	3/15/2016 8:43:35 AM	24232
EPA METHOD 8021B: VOLATILES							Analyst: NSB
Benzene	ND	0.018		mg/Kg	1	3/15/2016 8:43:35 AM	24232
Toluene	ND	0.037		mg/Kg	1	3/15/2016 8:43:35 AM	24232
Ethylbenzene	ND	0.037		mg/Kg	1	3/15/2016 8:43:35 AM	24232
Xylenes, Total	ND	0.074		mg/Kg	1	3/15/2016 8:43:35 AM	24232
Surr: 4-Bromofluorobenzene	110	80-120		%Rec	1	3/15/2016 8:43:35 AM	24232

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:		
*	Value exceeds Maximum Contaminant Level.	B Analyte detected in the associated Method Blank
D	Sample Diluted Due to Matrix	E Value above quantitation range
H	Holding times for preparation or analysis exceeded	J Analyte detected below quantitation limits
ND	Not Detected at the Reporting Limit	P Sample pH Not In Range
R	RPD outside accepted recovery limits	RL Reporting Detection Limit
S	% Recovery outside of range due to dilution or matrix	W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1603698

16-Mar-16

Client: Williams Field Services
Project: Crow Mesa CDP Inside Fence

Sample ID	MB-24265	SampType:	MBLK	TestCode:	EPA Method 300.0: Anions					
Client ID:	PBS	Batch ID:	24265	RunNo:	32825					
Prep Date:	3/15/2016	Analysis Date:	3/15/2016	SeqNo:	1006047	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Chloride	ND	1.5								

Sample ID	LCS-24265	SampType:	LCS	TestCode:	EPA Method 300.0: Anions					
Client ID:	LCSS	Batch ID:	24265	RunNo:	32825					
Prep Date:	3/15/2016	Analysis Date:	3/15/2016	SeqNo:	1006048	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Chloride	14	1.5	15.00	0	94.0	90	110			

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1603698
16-Mar-16

Client: Williams Field Services
Project: Crow Mesa CDP Inside Fence

Sample ID	MB-24246	SampType	MBLK	TestCode	EPA Method 8015M/D: Diesel Range Organics					
Client ID	PBS	Batch ID	24246	RunNo	32789					
Prep Date	3/15/2016	Analysis Date	3/15/2016	SeqNo	1004733	Units	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	ND	10								
Surr: DNOP	8.0		10.00		80.3	70	130			

Sample ID	LCS-24246	SampType	LCS	TestCode	EPA Method 8015M/D: Diesel Range Organics					
Client ID	LCSS	Batch ID	24246	RunNo	32789					
Prep Date	3/15/2016	Analysis Date	3/15/2016	SeqNo	1004810	Units	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	35	10	50.00	0	70.8	65.8	136			
Surr: DNOP	3.9		5.000		77.5	70	130			

Sample ID	1603698-001AMS	SampType	MS	TestCode	EPA Method 8015M/D: Diesel Range Organics					
Client ID	Crow Mesa cdp Insi	Batch ID	24246	RunNo	32789					
Prep Date	3/15/2016	Analysis Date	3/15/2016	SeqNo	1004960	Units	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	33	9.4	47.21	0	69.6	31.2	162			
Surr: DNOP	3.6		4.721		76.0	70	130			

Sample ID	1603698-001AMSD	SampType	MSD	TestCode	EPA Method 8015M/D: Diesel Range Organics					
Client ID	Crow Mesa cdp Insi	Batch ID	24246	RunNo	32789					
Prep Date	3/15/2016	Analysis Date	3/15/2016	SeqNo	1004961	Units	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	37	9.6	47.98	0	77.0	31.2	162	11.7	31.7	
Surr: DNOP	3.6		4.798		74.7	70	130	0	0	

Qualifiers:

- | | |
|---|---|
| * Value exceeds Maximum Contaminant Level. | B Analyte detected in the associated Method Blank |
| D Sample Diluted Due to Matrix | E Value above quantitation range |
| H Holding times for preparation or analysis exceeded | J Analyte detected below quantitation limits |
| ND Not Detected at the Reporting Limit | P Sample pH Not In Range |
| R RPD outside accepted recovery limits | RL Reporting Detection Limit |
| S % Recovery outside of range due to dilution or matrix | W Sample container temperature is out of limit as specified |

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1603698

16-Mar-16

Client: Williams Field Services
Project: Crow Mesa CDP Inside Fence

Sample ID	MB-24232	SampType	MBLK	TestCode	EPA Method 8015D: Gasoline Range					
Client ID	PBS	Batch ID	24232	RunNo	32794					
Prep Date	3/14/2016	Analysis Date	3/15/2016	SeqNo	1005398	Units	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	ND	5.0								
Surr: BFB	1100		1000		108	66.2	112			

Sample ID	LCS-24232	SampType	LCS	TestCode	EPA Method 8015D: Gasoline Range					
Client ID	LCSS	Batch ID	24232	RunNo	32794					
Prep Date	3/14/2016	Analysis Date	3/15/2016	SeqNo	1005399	Units	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	26	5.0	25.00	0	103	80	120			
Surr: BFB	1200		1000		116	66.2	112			S

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT
Hall Environmental Analysis Laboratory, Inc.

WO#: 1603698
 16-Mar-16

Client: Williams Field Services
Project: Crow Mesa CDP Inside Fence

Sample ID MB-24232	SampType: MBLK	TestCode: EPA Method 8021B: Volatiles								
Client ID: PBS	Batch ID: 24232	RunNo: 32794								
Prep Date: 3/14/2016	Analysis Date: 3/15/2016	SeqNo: 1005415	Units: mg/Kg							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	ND	0.025								
Toluene	ND	0.050								
Ethylbenzene	ND	0.050								
Xylenes, Total	ND	0.10								
Surr: 4-Bromofluorobenzene	1.2		1.000		115	80	120			

Sample ID LCS-24232	SampType: LCS	TestCode: EPA Method 8021B: Volatiles								
Client ID: LCSS	Batch ID: 24232	RunNo: 32794								
Prep Date: 3/14/2016	Analysis Date: 3/15/2016	SeqNo: 1005416	Units: mg/Kg							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	1.2	0.025	1.000	0	118	80	120			
Toluene	1.1	0.050	1.000	0	109	80	120			
Ethylbenzene	1.1	0.050	1.000	0	108	80	120			
Xylenes, Total	3.2	0.10	3.000	0	108	80	120			
Surr: 4-Bromofluorobenzene	1.2		1.000		122	80	120			S

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

Sample Log-In Check List

Client Name: WILLIAMS FIELD SERVI

Work Order Number: 1603698

RcptNo: 1

Received by/date: [Signature] 03/15/16

Logged By: Lindsay Mangin 3/15/2016 8:00:00 AM [Signature]

Completed By: Lindsay Mangin 3/15/2016 8:08:00 AM [Signature]

Reviewed By: [Signature] 03/15/16

Chain of Custody

- 1. Custody seals intact on sample bottles? Yes No Not Present
- 2. Is Chain of Custody complete? Yes No Not Present
- 3. How was the sample delivered? Courier

Log In

- 4. Was an attempt made to cool the samples? Yes No NA
- 5. Were all samples received at a temperature of >0° C to 6.0°C Yes No NA
- 6. Sample(s) in proper container(s)? Yes No
- 7. Sufficient sample volume for indicated test(s)? Yes No
- 8. Are samples (except VOA and ONG) properly preserved? Yes No
- 9. Was preservative added to bottles? Yes No NA
- 10. VOA vials have zero headspace? Yes No No VOA Vials
- 11. Were any sample containers received broken? Yes No
- 12. Does paperwork match bottle labels? Yes No
(Note discrepancies on chain of custody)
- 13. Are matrices correctly identified on Chain of Custody? Yes No
- 14. Is it clear what analyses were requested? Yes No
- 15. Were all holding times able to be met? Yes No
(If no, notify customer for authorization.)

of preserved bottles checked for pH: _____
 (<2 or >12 unless noted)
 Adjusted? _____
 Checked by: _____

Special Handling (if applicable)


- 16. Was client notified of all discrepancies with this order? Yes No NA

Person Notified: _____ Date: _____
 By Whom: _____ Via: eMail Phone Fax In Person
 Regarding: _____
 Client Instructions: _____

17. Additional remarks:

Cooler Information

Cooler No	Temp °C	Condition	Seal Intact	Seal No	Seal Date	Signed By
1	2.9	Good	Yes			



Hall Environmental Analysis Laboratory
4901 Hawkins NE
Albuquerque, NM 87109
TEL: 505-345-3975 FAX: 505-345-4107
Website: www.hallenvironmental.com

March 24, 2016

Kelsey Christiansen
Williams Field Services
188 Co. Rd 4900
Bloomfield, NM 87413
TEL: (505) 632-4442
FAX

RE: Crow Mesa CDP Outside Fence

OrderNo.: 1603848

Dear Kelsey Christiansen:

Hall Environmental Analysis Laboratory received 1 sample(s) on 3/16/2016 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent. To access our accredited tests please go to www.hallenvironmental.com or the state specific web sites. In order to properly interpret your results it is imperative that you review this report in its entirety. See the sample checklist and/or the Chain of Custody for information regarding the sample receipt temperature and preservation. Data qualifiers or a narrative will be provided if the sample analysis or analytical quality control parameters require a flag. When necessary, data qualifiers are provided on both the sample analysis report and the QC summary report, both sections should be reviewed. All samples are reported, as received, unless otherwise indicated. Lab measurement of analytes considered field parameters that require analysis within 15 minutes of sampling such as pH and residual chlorine are qualified as being analyzed outside of the recommended holding time.

Please don't hesitate to contact HEAL for any additional information or clarifications.

ADHS Cert #AZ0682 -- NMED-DWB Cert #NM9425 -- NMED-Micro Cert #NM0190

Sincerely,

A handwritten signature in black ink, appearing to read "Andy Freeman".

Andy Freeman
Laboratory Manager
4901 Hawkins NE
Albuquerque, NM 87109

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Williams Field Services **Client Sample ID:** Crow Mesa CDP Outside Fence
Project: Crow Mesa CDP Outside Fence **Collection Date:** 3/15/2016 1:45:00 PM
Lab ID: 1603848-001 **Matrix:** SOIL **Received Date:** 3/16/2016 7:45:00 AM

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed	Batch
EPA METHOD 300.0: ANIONS							Analyst: LGT
Chloride	ND	30		mg/Kg	20	3/22/2016 7:02:51 PM	24388
EPA METHOD 8015M/D: DIESEL RANGE ORGANICS							Analyst: KJH
Diesel Range Organics (DRO)	ND	9.6		mg/Kg	1	3/18/2016 9:42:35 AM	24294
Surr: DNOP	89.9	70-130		%Rec	1	3/18/2016 9:42:35 AM	24294
EPA METHOD 8015D: GASOLINE RANGE							Analyst: NSB
Gasoline Range Organics (GRO)	ND	4.7		mg/Kg	1	3/18/2016 9:27:44 PM	24316
Surr: BFB	91.3	66.2-112		%Rec	1	3/18/2016 9:27:44 PM	24316
EPA METHOD 8021B: VOLATILES							Analyst: NSB
Benzene	ND	0.024		mg/Kg	1	3/18/2016 9:27:44 PM	24316
Toluene	ND	0.047		mg/Kg	1	3/18/2016 9:27:44 PM	24316
Ethylbenzene	ND	0.047		mg/Kg	1	3/18/2016 9:27:44 PM	24316
Xylenes, Total	ND	0.095		mg/Kg	1	3/18/2016 9:27:44 PM	24316
Surr: 4-Bromofluorobenzene	113	80-120		%Rec	1	3/18/2016 9:27:44 PM	24316

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:		
*	Value exceeds Maximum Contaminant Level.	B Analyte detected in the associated Method Blank
D	Sample Diluted Due to Matrix	E Value above quantitation range
H	Holding times for preparation or analysis exceeded	J Analyte detected below quantitation limits
ND	Not Detected at the Reporting Limit	P Sample pH Not In Range
R	RPD outside accepted recovery limits	RL Reporting Detection Limit
S	% Recovery outside of range due to dilution or matrix	W Sample container temperature is out of limit as specified

QC SUMMARY REPORT
Hall Environmental Analysis Laboratory, Inc.

WO#: 1603848
 24-Mar-16

Client: Williams Field Services
Project: Crow Mesa CDP Outside Fence

Sample ID	MB-24388	SampType:	MBLK	TestCode:	EPA Method 300.0: Anions					
Client ID:	PBS	Batch ID:	24388	RunNo:	33002					
Prep Date:	3/22/2016	Analysis Date:	3/22/2016	SeqNo:	1012346	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Chloride	ND	1.5								

Sample ID	LCS-24388	SampType:	LCS	TestCode:	EPA Method 300.0: Anions					
Client ID:	LCSS	Batch ID:	24388	RunNo:	33002					
Prep Date:	3/22/2016	Analysis Date:	3/22/2016	SeqNo:	1012347	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Chloride	14	1.5	15.00	0	95.2	90	110			

Qualifiers:

- | | |
|---|---|
| * Value exceeds Maximum Contaminant Level. | B Analyte detected in the associated Method Blank |
| D Sample Diluted Due to Matrix | E Value above quantitation range |
| H Holding times for preparation or analysis exceeded | J Analyte detected below quantitation limits |
| ND Not Detected at the Reporting Limit | P Sample pH Not In Range |
| R RPD outside accepted recovery limits | RL Reporting Detection Limit |
| S % Recovery outside of range due to dilution or matrix | W Sample container temperature is out of limit as specified |

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1603848

24-Mar-16

Client: Williams Field Services
Project: Crow Mesa CDP Outside Fence

Sample ID LCS-24294	SampType: LCS		TestCode: EPA Method 8015M/D: Diesel Range Organics							
Client ID: LCSS	Batch ID: 24294		RunNo: 32883							
Prep Date: 3/17/2016	Analysis Date: 3/18/2016		SeqNo: 1008135				Units: mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	47	10	50.00	0	94.3	65.8	136			
Surr: DNOP	3.8		5.000		76.8	70	130			

Sample ID MB-24294	SampType: MBLK		TestCode: EPA Method 8015M/D: Diesel Range Organics							
Client ID: PBS	Batch ID: 24294		RunNo: 32883							
Prep Date: 3/17/2016	Analysis Date: 3/18/2016		SeqNo: 1008137				Units: mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	ND	10								
Surr: DNOP	8.6		10.00		86.1	70	130			

Qualifiers:

- | | |
|---|---|
| * Value exceeds Maximum Contaminant Level. | B Analyte detected in the associated Method Blank |
| D Sample Diluted Due to Matrix | E Value above quantitation range |
| H Holding times for preparation or analysis exceeded | J Analyte detected below quantitation limits |
| ND Not Detected at the Reporting Limit | P Sample pH Not In Range |
| R RPD outside accepted recovery limits | RL Reporting Detection Limit |
| S % Recovery outside of range due to dilution or matrix | W Sample container temperature is out of limit as specified |

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1603848

24-Mar-16

Client: Williams Field Services
Project: Crow Mesa CDP Outside Fence

Sample ID: MB-24321	SampType: MBLK	TestCode: EPA Method 8015D: Gasoline Range								
Client ID: PBS	Batch ID: 24321	RunNo: 32893								
Prep Date: 3/17/2016	Analysis Date: 3/18/2016	SeqNo: 1008613			Units: %Rec					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Surr: BFB	1100		1000		108	66.2	112			

Sample ID: LCS-24321	SampType: LCS	TestCode: EPA Method 8015D: Gasoline Range								
Client ID: LCSS	Batch ID: 24321	RunNo: 32893								
Prep Date: 3/17/2016	Analysis Date: 3/18/2016	SeqNo: 1008614			Units: %Rec					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Surr: BFB	1200		1000		117	66.2	112			S

Sample ID: MB-24316	SampType: MBLK	TestCode: EPA Method 8015D: Gasoline Range								
Client ID: PBS	Batch ID: 24316	RunNo: 32893								
Prep Date: 3/17/2016	Analysis Date: 3/18/2016	SeqNo: 1008621			Units: mg/Kg					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	ND	5.0								
Surr: BFB	1100		1000		106	66.2	112			

Sample ID: LCS-24316	SampType: LCS	TestCode: EPA Method 8015D: Gasoline Range								
Client ID: LCSS	Batch ID: 24316	RunNo: 32893								
Prep Date: 3/17/2016	Analysis Date: 3/18/2016	SeqNo: 1008622			Units: mg/Kg					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	26	5.0	25.00	0	103	80	120			
Surr: BFB	1100		1000		114	66.2	112			S

Qualifiers:

- | | |
|---|---|
| * Value exceeds Maximum Contaminant Level. | B Analyte detected in the associated Method Blank |
| D Sample Diluted Due to Matrix | E Value above quantitation range |
| H Holding times for preparation or analysis exceeded | J Analyte detected below quantitation limits |
| ND Not Detected at the Reporting Limit | P Sample pH Not In Range |
| R RPD outside accepted recovery limits | RL Reporting Detection Limit |
| S % Recovery outside of range due to dilution or matrix | W Sample container temperature is out of limit as specified |

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1603848

24-Mar-16

Client: Williams Field Services
Project: Crow Mesa CDP Outside Fence

Sample ID MB-24321	SampType: MBLK	TestCode: EPA Method 8021B: Volatiles								
Client ID: PBS	Batch ID: 24321	RunNo: 32893								
Prep Date: 3/17/2016	Analysis Date: 3/18/2016	SeqNo: 1008645 Units: %Rec								
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Surr: 4-Bromofluorobenzene	1.1		1.000		113	80	120			


Sample ID LCS-24321	SampType: LCS	TestCode: EPA Method 8021B: Volatiles								
Client ID: LCSS	Batch ID: 24321	RunNo: 32893								
Prep Date: 3/17/2016	Analysis Date: 3/18/2016	SeqNo: 1008646 Units: %Rec								
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Surr: 4-Bromofluorobenzene	1.2		1.000		121	80	120			S

Sample ID MB-24316	SampType: MBLK	TestCode: EPA Method 8021B: Volatiles								
Client ID: PBS	Batch ID: 24316	RunNo: 32893								
Prep Date: 3/17/2016	Analysis Date: 3/18/2016	SeqNo: 1008653 Units: mg/Kg								
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	ND	0.025								
Toluene	ND	0.050								
Ethylbenzene	ND	0.050								
Xylenes, Total	ND	0.10								
Surr: 4-Bromofluorobenzene	1.1		1.000		113	80	120			

Sample ID LCS-24316	SampType: LCS	TestCode: EPA Method 8021B: Volatiles								
Client ID: LCSS	Batch ID: 24316	RunNo: 32893								
Prep Date: 3/17/2016	Analysis Date: 3/18/2016	SeqNo: 1008654 Units: mg/Kg								
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	1.0	0.025	1.000	0	102	80	120			
Toluene	0.98	0.050	1.000	0	97.7	80	120			
Ethylbenzene	0.99	0.050	1.000	0	98.9	80	120			
Xylenes, Total	2.9	0.10	3.000	0	98.1	80	120			
Surr: 4-Bromofluorobenzene	1.2		1.000		116	80	120			

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified



Hall Environmental Analysis Laboratory
 4901 Hawkins NE
 Albuquerque, NM 87109
 TEL: 505-345-3975 FAX: 505-345-4107
 Website: www.hallenvironmental.com

Sample Log-In Check List

Client Name: WILLIAMS FIELD SERVI Work Order Number: 1603848 RcptNo: 1

Received by/date: *[Signature]* 03/16/16
 Logged By: Lindsay Mangin 3/16/2016 7:45:00 AM *[Signature]*
 Completed By: Lindsay Mangin 3/16/2016 3:11:43 PM *[Signature]*
 Reviewed By: *[Signature]* 03/17/16

Chain of Custody

- 1. Custody seals intact on sample bottles? Yes No Not Present
- 2. Is Chain of Custody complete? Yes No Not Present
- 3. How was the sample delivered? Courier

Log In

- 4. Was an attempt made to cool the samples? Yes No NA
- 5. Were all samples received at a temperature of >0° C to 6.0°C Yes No NA
- 6. Sample(s) in proper container(s)? Yes No
- 7. Sufficient sample volume for indicated test(s)? Yes No
- 8. Are samples (except VOA and ONG) properly preserved? Yes No
- 9. Was preservative added to bottles? Yes No NA
- 10. VOA vials have zero headspace? Yes No No VOA Vials
- 11. Were any sample containers received broken? Yes No
- 12. Does paperwork match bottle labels? Yes No # of preserved bottles checked for pH: _____
(Note discrepancies on chain of custody)
- 13. Are matrices correctly identified on Chain of Custody? Yes No Adjusted? _____
(<2 or >12 unless noted)
- 14. Is it clear what analyses were requested? Yes No
- 15. Were all holding times able to be met? Yes No Checked by: _____
(If no, notify customer for authorization.)

Special Handling (if applicable)

- 16. Was client notified of all discrepancies with this order? Yes No NA

Person Notified: _____ Date: _____
 By Whom: _____ Via: eMail Phone Fax In Person
 Regarding: _____
 Client Instructions: _____

17. Additional remarks:

18. Cooler Information

Cooler No	Temp °C	Condition	Seal Intact	Seal No	Seal Date	Signed By
1	1.3	Good	Yes			

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Mitch Morris
Address 1755 Arroyo Drive, Bloomfield, NM 87413	Telephone No. 505-632-4708
Facility Name Kutz Canyon Gas Plant	Facility Type Natural Gas Processing Plant
Surface Owner Bureau of Land Management	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter D	Section 13	Township 28N	Range 11W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------------------

Latitude 36° 40.064 N Longitude 107° 57.795 W

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 50.424 MCF	Volume Recovered 0
Source of Release Pressure Relief Valve (PRV)	Date and Hour of Occurrence 4/29/2016, 03:55 AM MST	Date and Hour of Discovery 4/29/2016, 03:55 AM MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Not Applicable	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse Not Applicable	

OIL CONS. DIV DIST. 3

MAY 18 2016

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Loss of compression at Kutz Plant caused an over-pressure situation in the recycle gas stream. Pressure Relief Valves (PRV) are designed to open at a predetermined set point to protect the integrity of equipment and ensure safe operating conditions. When compression was re-established, pressures in the plant normalized allowing the PRV to close automatically.

Describe Area Affected and Cleanup Action Taken.*

No cleanup required with a gas release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Mitch Morris	Approval Date: <u>6/7/2016</u>	Expiration Date:
Title: Environmental Specialist	Conditions of Approval: 	
E-mail Address: Mitch.Morris@williams.com	Attached <input type="checkbox"/>	
Date: 05/06/2016 Phone: 505-632-4708		

* Attach Additional Sheets If Necessary

NVF1615938029

①

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

JUN 10 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Mitch Morris
Address 1755 Arroyo Drive, Bloomfield, NM 87413	Telephone No. 505-632-4708
Facility Name Buena Vista	Facility Type Compressor Station
Surface Owner Bureau of Land Management	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	32	24N	8W					San Juan

Latitude 36.2756 Longitude -107.698

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 539 MCF	Volume Recovered 0 MCF
Source of Release Valve	Date and Hour of Occurrence 5/20/2016, 10:30AM	Date and Hour of Discovery 5/20/2016, 10:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith, NMOCD via Phone Call and follow-up Email	
By Whom? Mitch Morris	Date and Hour: Email 5/20/2016 3:49 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Williams operator arrived on-site at 10:30 am and discovered the ESD Vent Valve on the start gas piping open. The valve was open for 11.25 hours allowing 539 MCF of natural gas to be released to atmosphere.


BLM Business Lease No. BL-2127

Describe Area Affected and Cleanup Action Taken.*

No cleanup required with gas release to atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 

Printed Name: Mitch Morris

Title: Environmental Specialist

E-mail Address: mitch.morris@williams.com

Date: June 2, 2016

Phone: 505-632-4708

Approved by Environmental Specialist:

Approval Date: 06/15/2016

Expiration Date:

Conditions of Approval:

Attached

* Attach Additional Sheets If Necessary

NVF 1616733078

①

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 10 2016 Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Kijun Hong
Address 1755 Arroyo Drive, Bloomfield, NM 87413	Telephone No. 505-632-4475
Facility Name Hubbard 3A Meter	Facility Type Natural Gas Pipeline
Surface Owner Private	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter E	Section 15	Township 32N	Range 12W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	---------------------------

Latitude 36.98833 Longitude -108.08944

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 134.502 MCF	Volume Recovered 0
Source of Release Broken 1/4 inch sample port	Date and Hour of Occurrence 5/31/2016, 11:00 AM MST	Date and Hour of Discovery 6/01/2016, 09:00 AM MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Not Applicable	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not Applicable	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Broken 1/4 inch sample port caused release of natural gas to atmosphere. Livestock rubbing against the port is the most likely cause. The broken port was isolated and the gas release stopped

Describe Area Affected and Cleanup Action Taken.*
No cleanup required with a gas release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kijun Hong	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 06/15/2016	Expiration Date:
E-mail Address: Kijun.Hong@Williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/03/2016 Phone: 505-632-4475		

* Attach Additional Sheets If Necessary

NVF1616735187

①

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 10 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Michael Hannan
Address 1755 Arroyo Dr, Bloomfield, NM 87413	Telephone No. 505-632-4807
Facility Name Milagro Gas Plant	Facility Type Facility

Surface Owner Private	Mineral Owner	API No.
-----------------------	---------------	---------

LOCATION OF RELEASE

Unit Letter O	Section 12	Township 29N	Range 11W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
---------------	------------	--------------	-----------	---------------	------------------	---------------	----------------	-----------------

Latitude 36.735966° N Longitude -107.942329° W

NATURE OF RELEASE

Type of Release Water	Volume of Release 34,000 Gallons Boiler Feed Water/Deionized Water mixture	Volume Recovered 17,000 Gallons Boiler Feed Water/Deionized Water mixture
Source of Release Boiler Feed Water Vessel	Date and Hour of Occurrence 5/23/16 12:00 PM MST	Date and Hour of Discovery 5/23/16 12:00 PM MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith, NMOCD	
By Whom? Matt Webre	Date and Hour 05/24/16 at 7:45 AM MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*The boiler feed water vessel overheated due to the inability of the excess steam bays to dissipate the heat in the recirculated water. As a result, a tank of deionized water was released into the boiler feed water vessel to maintain temperature. This resulted in the vessel overflowing and releasing approximately 34,000 gallons of a mixture of boiler feed water and deionized water. The water traveled to a drainage ditch located southwest of the plant and FCA office. The water stopped traveling in a low topographic drainage area. The water was recovered from the drainage with vacuum trucks to alleviate any potential concern from water reaching the wash located a few hundred feet to the south/southwest. The cause of the boiler water release was attributed to the installation of the new excess steam bay. During the outage, operations eliminated the choke point between the two stream bays so this release is not expected to reoccur in the future.


Describe Area Affected and Cleanup Action Taken.* Approximately 17,000 gallons of water was recovered and mixed with exempt E&P water from the Milagro facility prior to disposal. Water and soil samples were taken as directed by OCD (Vanessa Fields) and the results were transmitted via email on 6/1/16. The results and process knowledge indicated that the water mixture was non-exempt non-hazardous waste. Analytical results for both the soil and water samples are attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 

Approved by Environmental Specialist:



Printed Name: Michael Hannan, P.E.

Title: Engineer, Sr.

Approval Date: 06/15/2016 Expiration Date:

E-mail Address: Michael.hannan@williams.com

Conditions of Approval:

Attached

Date: 06/06/16 Phone: 505-632-4807

* Attach Additional Sheets If Necessary

NVF 1616735651

24



Hall Environmental Analysis Laboratory
4901 Hawkins NE
Albuquerque, NM 87109
TEL: 505-345-3975 FAX: 505-345-4107
Website: www.hallenvironmental.com

May 27, 2016

Michael Hannan
Williams Four Corners
188 CR 4900
Bloomfield, NM 87413
TEL: (505) 632-4442
FAX

RE: FCA Boiler Release

OrderNo.: 1605B89

Dear Michael Hannan:

Hall Environmental Analysis Laboratory received 1 sample(s) on 5/26/2016 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent. To access our accredited tests please go to www.hallenvironmental.com or the state specific web sites. In order to properly interpret your results it is imperative that you review this report in its entirety. See the sample checklist and/or the Chain of Custody for information regarding the sample receipt temperature and preservation. Data qualifiers or a narrative will be provided if the sample analysis or analytical quality control parameters require a flag. When necessary, data qualifiers are provided on both the sample analysis report and the QC summary report, both sections should be reviewed. All samples are reported, as received, unless otherwise indicated. Lab measurement of analytes considered field parameters that require analysis within 15 minutes of sampling such as pH and residual chlorine are qualified as being analyzed outside of the recommended holding time.

Please don't hesitate to contact HEAL for any additional information or clarifications.

ADHS Cert #AZ0682 -- NMED-DWB Cert #NM9425 -- NMED-Micro Cert #NM0190

Sincerely,

A handwritten signature in black ink, appearing to read 'Andy Freeman', is written over a light blue horizontal line.

Andy Freeman
Laboratory Manager
4901 Hawkins NE
Albuquerque, NM 87109

Analytical Report

Lab Order **1605B89**

Date Reported: 5/27/2016

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Williams Four Corners

Client Sample ID: Milagro BFW

Project: FCA Boiler Release

Collection Date: 5/25/2016 2:30:00 PM

Lab ID: 1605B89-001

Matrix: MEOH (SOIL)

Received Date: 5/26/2016 7:54:00 AM

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed	Batch
EPA METHOD 8015M/D: DIESEL RANGE ORGANICS							Analyst: KJH
Diesel Range Organics (DRO)	ND	9.8		mg/Kg	1	5/26/2016 12:01:59 PM	25515
Surr: DNOP	84.5	70-130		%Rec	1	5/26/2016 12:01:59 PM	25515
EPA METHOD 8015D: GASOLINE RANGE							Analyst: NSB
Gasoline Range Organics (GRO)	ND	3.9		mg/Kg	1	5/26/2016 10:25:50 PM	25505
Surr: BFB	111	80-120		%Rec	1	5/26/2016 10:25:50 PM	25505
EPA METHOD 8021B: VOLATILES							Analyst: NSB
Benzene	ND	0.020		mg/Kg	1	5/26/2016 10:25:50 PM	25505
Toluene	ND	0.039		mg/Kg	1	5/26/2016 10:25:50 PM	25505
Ethylbenzene	ND	0.039		mg/Kg	1	5/26/2016 10:25:50 PM	25505
Xylenes, Total	ND	0.079		mg/Kg	1	5/26/2016 10:25:50 PM	25505
Surr: 4-Bromofluorobenzene	111	80-120		%Rec	1	5/26/2016 10:25:50 PM	25505

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:	* Value exceeds Maximum Contaminant Level.	B Analyte detected in the associated Method Blank
	D Sample Diluted Due to Matrix	E Value above quantitation range
	H Holding times for preparation or analysis exceeded	J Analyte detected below quantitation limits
	ND Not Detected at the Reporting Limit	P Sample pH Not In Range
	R RPD outside accepted recovery limits	RL Reporting Detection Limit
	S % Recovery outside of range due to dilution or matrix	W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B89

27-May-16

Client: Williams Four Corners

Project: FCA Boiler Release

Sample ID	LCS-25515	SampType:	LCS	TestCode:	EPA Method 8015M/D: Diesel Range Organics					
Client ID:	LCSS	Batch ID:	25515	RunNo:	34493					
Prep Date:	5/26/2016	Analysis Date:	5/26/2016	SeqNo:	1063925	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	47	10	50.00	0	94.0	62.6	124			
Surr: DNOP	4.8		5.000		95.5	70	130			

Sample ID	MB-25515	SampType:	MBLK	TestCode:	EPA Method 8015M/D: Diesel Range Organics					
Client ID:	PBS	Batch ID:	25515	RunNo:	34493					
Prep Date:	5/26/2016	Analysis Date:	5/26/2016	SeqNo:	1063926	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	ND	10								
Surr: DNOP	9.9		10.00		98.7	70	130			

Qualifiers:

- | | |
|---|---|
| * Value exceeds Maximum Contaminant Level. | B Analyte detected in the associated Method Blank |
| D Sample Diluted Due to Matrix | E Value above quantitation range |
| H Holding times for preparation or analysis exceeded | J Analyte detected below quantitation limits |
| ND Not Detected at the Reporting Limit | P Sample pH Not In Range |
| R RPD outside accepted recovery limits | RL Reporting Detection Limit |
| S % Recovery outside of range due to dilution or matrix | W Sample container temperature is out of limit as specified |

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B89

27-May-16

Client: Williams Four Corners

Project: FCA Boiler Release

Sample ID	MB-25505	SampType:	MBLK	TestCode:	EPA Method 8015D: Gasoline Range					
Client ID:	PBS	Batch ID:	25505	RunNo:	34502					
Prep Date:	5/25/2016	Analysis Date:	5/26/2016	SeqNo:	1064463	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	ND	5.0								
Surr: BFB	1100		1000		107	80	120			

Sample ID	LCS-25505	SampType:	LCS	TestCode:	EPA Method 8015D: Gasoline Range					
Client ID:	LCSS	Batch ID:	25505	RunNo:	34502					
Prep Date:	5/25/2016	Analysis Date:	5/26/2016	SeqNo:	1064464	Units:	mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	23	5.0	25.00	0	91.4	80	120			
Surr: BFB	1200		1000		120	80	120			S

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B89

27-May-16

Client: Williams Four Corners


Project: FCA Boiler Release

Sample ID MB-25505	SampType: MBLK	TestCode: EPA Method 8021B: Volatiles								
Client ID: PBS	Batch ID: 25505	RunNo: 34502								
Prep Date: 5/25/2016	Analysis Date: 5/26/2016	SeqNo: 1064483			Units: mg/Kg					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	ND	0.025								
Toluene	ND	0.050								
Ethylbenzene	ND	0.050								
Xylenes, Total	ND	0.10								
Surr: 4-Bromofluorobenzene	1.1		1.000		110	80	120			

Sample ID LCS-25505	SampType: LCS	TestCode: EPA Method 8021B: Volatiles								
Client ID: LCSS	Batch ID: 25505	RunNo: 34502								
Prep Date: 5/25/2016	Analysis Date: 5/26/2016	SeqNo: 1064484			Units: mg/Kg					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	0.96	0.025	1.000	0	96.3	75.3	123			
Toluene	0.98	0.050	1.000	0	98.2	80	124			
Ethylbenzene	0.97	0.050	1.000	0	96.8	82.8	121			
Xylenes, Total	2.9	0.10	3.000	0	96.3	83.9	122			
Surr: 4-Bromofluorobenzene	1.2		1.000		117	80	120			

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified



Hall Environmental Analysis Laboratory
 4901 Hawkins NE
 Albuquerque, NM 87109
 TEL: 505-345-3975 FAX: 505-345-4107
 Website: www.hallenvironmental.com

Sample Log-In Check List

Client Name: WILLIAMS FOUR CORN

Work Order Number: 1605B89

RcptNo: 1

Received by/date: AS/26/16

Logged By: Lindsay Mangin 5/26/2016 7:54:00 AM *Lindsay Mangin*

Completed By: Lindsay Mangin 5/26/2016 8:26:18 AM *Lindsay Mangin*

Reviewed By: *AG* 05/26/16

Chain of Custody

- 1. Custody seals intact on sample bottles? Yes No Not Present
- 2. Is Chain of Custody complete? Yes No Not Present
- 3. How was the sample delivered? Courier

Log In

- 4. Was an attempt made to cool the samples? Yes No NA
- 5. Were all samples received at a temperature of >0° C to 6.0°C Yes No NA
- 6. Sample(s) in proper container(s)? Yes No
- 7. Sufficient sample volume for indicated test(s)? Yes No
- 8. Are samples (except VOA and ONG) properly preserved? Yes No
- 9. Was preservative added to bottles? Yes No NA
- 10. VOA vials have zero headspace? Yes No No VOA Vials
- 11. Were any sample containers received broken? Yes No
- 12. Does paperwork match bottle labels? (Note discrepancies on chain of custody) Yes No
- 13. Are matrices correctly identified on Chain of Custody? Yes No
- 14. Is it clear what analyses were requested? Yes No
- 15. Were all holding times able to be met? (If no, notify customer for authorization.) Yes No

of preserved bottles checked for pH: _____
 (<2 or >12 unless noted)
 Adjusted? _____
 Checked by: _____

Special Handling (if applicable)

- 16. Was client notified of all discrepancies with this order? Yes No NA

Person Notified: _____ Date: _____
 By Whom: _____ Via: eMail Phone Fax In Person
 Regarding: _____
 Client Instructions: _____

17. Additional remarks:

18. Cooler Information

Cooler No	Temp °C	Condition	Seal Intact	Seal No	Seal Date	Signed By
1	1.5	Good	Yes			



Hall Environmental Analysis Laboratory
4901 Hawkins NE
Albuquerque, NM 87109
TEL: 505-345-3975 FAX: 505-345-4107
Website: www.hallenvironmental.com

May 27, 2016

Ashley Ager
LTE
2243 Main Ave Suite 3
Durango, CO 81301
TEL: (970) 946-1093
FAX

RE: FCA Boller release

OrderNo.: 1605B24

Dear Ashley Ager:

Hall Environmental Analysis Laboratory received 1 sample(s) on 5/25/2016 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent. To access our accredited tests please go to www.hallenvironmental.com or the state specific web sites. In order to properly interpret your results it is imperative that you review this report in its entirety. See the sample checklist and/or the Chain of Custody for information regarding the sample receipt temperature and preservation. Data qualifiers or a narrative will be provided if the sample analysis or analytical quality control parameters require a flag. When necessary, data qualifiers are provided on both the sample analysis report and the QC summary report, both sections should be reviewed. All samples are reported, as received, unless otherwise indicated. Lab measurement of analytes considered field parameters that require analysis within 15 minutes of sampling such as pH and residual chlorine are qualified as being analyzed outside of the recommended holding time.

Please don't hesitate to contact HEAL for any additional information or clarifications.

ADHS Cert #AZ0682 -- NMED-DWB Cert #NM9425 -- NMED-Micro Cert #NM0190

Sincerely,

A handwritten signature in black ink, appearing to read 'Andy Freeman', is written over a light blue horizontal line.

Andy Freeman
Laboratory Manager
4901 Hawkins NE
Albuquerque, NM 87109

Analytical Report

Lab Order 1605B24

Date Reported: 5/27/2016

Hall Environmental Analysis Laboratory, Inc.

CLIENT: LTE

Client Sample ID: WS-01

Project: FCA Boller release

Collection Date: 5/24/2016 10:00:00 AM

Lab ID: 1605B24-001

Matrix: AQUEOUS

Received Date: 5/25/2016 7:45:00 AM

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed
EPA METHOD 300.0: ANIONS						Analyst: LGT
Fluoride	ND	0.50		mg/L	5	5/25/2016 8:12:52 PM
Chloride	ND	2.5		mg/L	5	5/25/2016 8:12:52 PM
Nitrogen, Nitrite (As N)	ND	0.50		mg/L	5	5/25/2016 8:12:52 PM
Bromide	ND	0.50		mg/L	5	5/25/2016 8:12:52 PM
Nitrogen, Nitrate (As N)	ND	0.50		mg/L	5	5/25/2016 8:12:52 PM
Sulfate	46	2.5		mg/L	5	5/25/2016 8:12:52 PM
SM2340B: HARDNESS						Analyst: MED
Hardness (As CaCO3)	86	6.6		mg/L	1	5/26/2016 12:30:00 PM
EPA METHOD 7470: MERCURY						Analyst: pmf
Mercury	ND	0.00020		mg/L	1	5/26/2016 11:39:31 AM
EPA 6010B: TOTAL RECOVERABLE METALS						Analyst: MED
Arsenic	ND	0.020		mg/L	1	5/26/2016 12:58:37 PM
Barium	0.12	0.020		mg/L	1	5/26/2016 12:58:37 PM
Cadmium	ND	0.0020		mg/L	1	5/26/2016 12:58:37 PM
Calcium	32	1.0		mg/L	1	5/26/2016 12:58:37 PM
Chromium	ND	0.0060		mg/L	1	5/26/2016 12:58:37 PM
Iron	0.76	0.25		mg/L	5	5/26/2016 1:12:34 PM
Lead	0.0072	0.0050		mg/L	1	5/26/2016 12:58:37 PM
Magnesium	1.7	1.0		mg/L	1	5/26/2016 12:58:37 PM
Manganese	0.11	0.0020		mg/L	1	5/26/2016 12:58:37 PM
Potassium	2.9	1.0		mg/L	1	5/26/2016 12:58:37 PM
Selenium	ND	0.050		mg/L	1	5/26/2016 12:58:37 PM
Silver	ND	0.0050		mg/L	1	5/26/2016 12:58:37 PM
Sodium	7.4	1.0		mg/L	1	5/26/2016 12:58:37 PM
EPA METHOD 8260B: VOLATILES						Analyst: AG
Benzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Toluene	1.9	1.0		µg/L	1	5/25/2016 12:40:51 PM
Ethylbenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Methyl tert-butyl ether (MTBE)	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,2,4-Trimethylbenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,3,5-Trimethylbenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,2-Dichloroethane (EDC)	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,2-Dibromoethane (EDB)	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Naphthalene	ND	2.0		µg/L	1	5/25/2016 12:40:51 PM
1-Methylnaphthalene	ND	4.0		µg/L	1	5/25/2016 12:40:51 PM
2-Methylnaphthalene	ND	4.0		µg/L	1	5/25/2016 12:40:51 PM
Acetone	ND	10		µg/L	1	5/25/2016 12:40:51 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:	* Value exceeds Maximum Contaminant Level.	B Analyte detected in the associated Method Blank
	D Sample Diluted Due to Matrix	E Value above quantitation range
	H Holding times for preparation or analysis exceeded	J Analyte detected below quantitation limits
	ND Not Detected at the Reporting Limit	P Sample pH Not In Range
	R RPD outside accepted recovery limits	RL Reporting Detection Limit
	S % Recovery outside of range due to dilution or matrix	W Sample container temperature is out of limit as specified

Analytical Report

Lab Order 1605B24

Date Reported: 5/27/2016

Hall Environmental Analysis Laboratory, Inc.

CLIENT: LTE

Client Sample ID: WS-01

Project: FCA Boller release

Collection Date: 5/24/2016 10:00:00 AM

Lab ID: 1605B24-001

Matrix: AQUEOUS

Received Date: 5/25/2016 7:45:00 AM

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed
EPA METHOD 8260B: VOLATILES						Analyst: AG
Bromobenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Bromodichloromethane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Bromoform	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Bromomethane	ND	3.0		µg/L	1	5/25/2016 12:40:51 PM
2-Butanone	ND	10		µg/L	1	5/25/2016 12:40:51 PM
Carbon disulfide	ND	10		µg/L	1	5/25/2016 12:40:51 PM
Carbon Tetrachloride	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Chlorobenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Chloroethane	ND	2.0		µg/L	1	5/25/2016 12:40:51 PM
Chloroform	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Chloromethane	ND	3.0		µg/L	1	5/25/2016 12:40:51 PM
2-Chlorotoluene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
4-Chlorotoluene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
cis-1,2-DCE	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
cis-1,3-Dichloropropene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,2-Dibromo-3-chloropropane	ND	2.0		µg/L	1	5/25/2016 12:40:51 PM
Dibromochloromethane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Dibromomethane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,2-Dichlorobenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,3-Dichlorobenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,4-Dichlorobenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Dichlorodifluoromethane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,1-Dichloroethane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,1-Dichloroethene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,2-Dichloropropane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,3-Dichloropropane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
2,2-Dichloropropane	ND	2.0		µg/L	1	5/25/2016 12:40:51 PM
1,1-Dichloropropene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Hexachlorobutadiene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
2-Hexanone	ND	10		µg/L	1	5/25/2016 12:40:51 PM
Isopropylbenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
4-Isopropyltoluene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
4-Methyl-2-pentanone	ND	10		µg/L	1	5/25/2016 12:40:51 PM
Methylene Chloride	ND	3.0		µg/L	1	5/25/2016 12:40:51 PM
n-Butylbenzene	ND	3.0		µg/L	1	5/25/2016 12:40:51 PM
n-Propylbenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
sec-Butylbenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Styrene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
tert-Butylbenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:	* Value exceeds Maximum Contaminant Level.	B Analyte detected in the associated Method Blank
	D Sample Diluted Due to Matrix	E Value above quantitation range
	H Holding times for preparation or analysis exceeded	J Analyte detected below quantitation limits
	ND Not Detected at the Reporting Limit	P Sample pH Not In Range
	R RPD outside accepted recovery limits	RL Reporting Detection Limit
	S % Recovery outside of range due to dilution or matrix	W Sample container temperature is out of limit as specified

Analytical Report

Lab Order 1605B24

Date Reported: 5/27/2016

Hall Environmental Analysis Laboratory, Inc.

CLIENT: LTE

Client Sample ID: WS-01

Project: FCA Boller release

Collection Date: 5/24/2016 10:00:00 AM

Lab ID: 1605B24-001

Matrix: AQUEOUS

Received Date: 5/25/2016 7:45:00 AM

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed
EPA METHOD 8260B: VOLATILES						Analyst: AG
1,1,1,2-Tetrachloroethane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,1,2,2-Tetrachloroethane	ND	2.0		µg/L	1	5/25/2016 12:40:51 PM
Tetrachloroethene (PCE)	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
trans-1,2-DCE	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
trans-1,3-Dichloropropene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,2,3-Trichlorobenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,2,4-Trichlorobenzene	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,1,1-Trichloroethane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,1,2-Trichloroethane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Trichloroethene (TCE)	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Trichlorofluoromethane	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
1,2,3-Trichloropropane	ND	2.0		µg/L	1	5/25/2016 12:40:51 PM
Vinyl chloride	ND	1.0		µg/L	1	5/25/2016 12:40:51 PM
Xylenes, Total	ND	1.5		µg/L	1	5/25/2016 12:40:51 PM
Surr: 1,2-Dichloroethane-d4	87.0	70-130		%Rec	1	5/25/2016 12:40:51 PM
Surr: 4-Bromofluorobenzene	93.0	70-130		%Rec	1	5/25/2016 12:40:51 PM
Surr: Dibromofluoromethane	91.1	70-130		%Rec	1	5/25/2016 12:40:51 PM
Surr: Toluene-d8	101	70-130		%Rec	1	5/25/2016 12:40:51 PM
SM2510B: SPECIFIC CONDUCTANCE						Analyst: JRR
Conductivity	190	1.0		µmhos/cm	1	5/25/2016 6:08:02 PM
SM4500-H+B: PH						Analyst: JRR
pH	7.64	1.68	H	pH units	1	5/25/2016 6:08:02 PM
SM2320B: ALKALINITY						Analyst: JRR
Bicarbonate (As CaCO3)	38.12	20.00		mg/L CaCO3	1	5/25/2016 6:08:02 PM
Carbonate (As CaCO3)	ND	2.000		mg/L CaCO3	1	5/25/2016 6:08:02 PM
Total Alkalinity (as CaCO3)	38.12	20.00		mg/L CaCO3	1	5/25/2016 6:08:02 PM
SM2540C MOD: TOTAL DISSOLVED SOLIDS						Analyst: KS
Total Dissolved Solids	136	40.0	D	mg/L	1	5/26/2016 4:17:00 PM

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:	* Value exceeds Maximum Contaminant Level.	B Analyte detected in the associated Method Blank
	D Sample Diluted Due to Matrix	E Value above quantitation range
	H Holding times for preparation or analysis exceeded	J Analyte detected below quantitation limits
	ND Not Detected at the Reporting Limit	P Sample pH Not In Range
	R RPD outside accepted recovery limits	RL Reporting Detection Limit
	S % Recovery outside of range due to dilution or matrix	W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B24

27-May-16

Client: LTE
Project: FCA Boller release

Sample ID MB	SampType: MBLK	TestCode: EPA Method 300.0: Anions								
Client ID: PBW	Batch ID: A34487	RunNo: 34487								
Prep Date:	Analysis Date: 5/25/2016	SeqNo: 1063662	Units: mg/L							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual

Fluoride	ND	0.10								
Chloride	ND	0.50								
Nitrogen, Nitrite (As N)	ND	0.10								
Bromide	ND	0.10								
Nitrogen, Nitrate (As N)	ND	0.10								
Sulfate	ND	0.50								

Sample ID LCS	SampType: LCS	TestCode: EPA Method 300.0: Anions								
Client ID: LCSW	Batch ID: A34487	RunNo: 34487								
Prep Date:	Analysis Date: 5/25/2016	SeqNo: 1063663	Units: mg/L							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual

Fluoride	0.52	0.10	0.5000	0	105	90	110			
Chloride	4.8	0.50	5.000	0	96.3	90	110			
Nitrogen, Nitrite (As N)	0.98	0.10	1.000	0	98.3	90	110			
Bromide	2.5	0.10	2.500	0	98.6	90	110			
Nitrogen, Nitrate (As N)	2.5	0.10	2.500	0	100	90	110			
Sulfate	9.9	0.50	10.00	0	98.9	90	110			

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B24

27-May-16

Client: LTE
Project: FCA Boller release

Sample ID: 100ng lcs	SampType: LCS	TestCode: EPA Method 8260B: VOLATILES								
Client ID: LCSW	Batch ID: A34458	RunNo: 34458								
Prep Date:	Analysis Date: 5/25/2016	SeqNo: 1063591	Units: µg/L							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	21	1.0	20.00	0	106	70	130			
Toluene	20	1.0	20.00	0	101	70	130			
Chlorobenzene	19	1.0	20.00	0	93.9	70	130			
1,1-Dichloroethene	21	1.0	20.00	0	105	70	130			
Trichloroethene (TCE)	19	1.0	20.00	0	92.7	70	130			
Surr: 1,2-Dichloroethane-d4	8.9		10.00		89.2	70	130			
Surr: 4-Bromofluorobenzene	10		10.00		99.7	70	130			
Surr: Dibromofluoromethane	9.8		10.00		97.7	70	130			
Surr: Toluene-d8	10		10.00		99.6	70	130			

Sample ID: rb	SampType: MBLK	TestCode: EPA Method 8260B: VOLATILES								
Client ID: PBW	Batch ID: A34458	RunNo: 34458								
Prep Date:	Analysis Date: 5/25/2016	SeqNo: 1063592	Units: µg/L							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	ND	1.0								
Toluene	ND	1.0								
Ethylbenzene	ND	1.0								
Methyl tert-butyl ether (MTBE)	ND	1.0								
1,2,4-Trimethylbenzene	ND	1.0								
1,3,5-Trimethylbenzene	ND	1.0								
1,2-Dichloroethane (EDC)	ND	1.0								
1,2-Dibromoethane (EDB)	ND	1.0								
Naphthalene	ND	2.0								
1-Methylnaphthalene	ND	4.0								
2-Methylnaphthalene	ND	4.0								
Acetone	ND	10								
Bromobenzene	ND	1.0								
Bromodichloromethane	ND	1.0								
Bromoform	ND	1.0								
Bromomethane	ND	3.0								
2-Butanone	ND	10								
Carbon disulfide	ND	10								
Carbon Tetrachloride	ND	1.0								
Chlorobenzene	ND	1.0								
Chloroethane	ND	2.0								
Chloroform	ND	1.0								
Chloromethane	ND	3.0								
2-Chlorotoluene	ND	1.0								

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B24
27-May-16

Client: LTE
Project: FCA Boller release

Sample ID	rb	SampType: MBLK	TestCode: EPA Method 8260B: VOLATILES
Client ID:	PBW	Batch ID: A34458	RunNo: 34458
Prep Date:		Analysis Date: 5/25/2016	SeqNo: 1063592 Units: µg/L

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
4-Chlorotoluene	ND	1.0								
cis-1,2-DCE	ND	1.0								
cis-1,3-Dichloropropene	ND	1.0								
1,2-Dibromo-3-chloropropane	ND	2.0								
Dibromochloromethane	ND	1.0								
Dibromomethane	ND	1.0								
1,2-Dichlorobenzene	ND	1.0								
1,3-Dichlorobenzene	ND	1.0								
1,4-Dichlorobenzene	ND	1.0								
Dichlorodifluoromethane	ND	1.0								
1,1-Dichloroethane	ND	1.0								
1,1-Dichloroethene	ND	1.0								
1,2-Dichloropropane	ND	1.0								
1,3-Dichloropropane	ND	1.0								
2,2-Dichloropropane	ND	2.0								
1,1-Dichloropropene	ND	1.0								
Hexachlorobutadiene	ND	1.0								
2-Hexanone	ND	10								
Isopropylbenzene	ND	1.0								
4-Isopropyltoluene	ND	1.0								
4-Methyl-2-pentanone	ND	10								
Methylene Chloride	ND	3.0								
n-Butylbenzene	ND	3.0								
n-Propylbenzene	ND	1.0								
sec-Butylbenzene	ND	1.0								
Styrene	ND	1.0								
tert-Butylbenzene	ND	1.0								
1,1,1,2-Tetrachloroethane	ND	1.0								
1,1,2,2-Tetrachloroethane	ND	2.0								
Tetrachloroethene (PCE)	ND	1.0								
trans-1,2-DCE	ND	1.0								
trans-1,3-Dichloropropene	ND	1.0								
1,2,3-Trichlorobenzene	ND	1.0								
1,2,4-Trichlorobenzene	ND	1.0								
1,1,1-Trichloroethane	ND	1.0								
1,1,2-Trichloroethane	ND	1.0								
Trichloroethene (TCE)	ND	1.0								
Trichlorofluoromethane	ND	1.0								
1,2,3-Trichloropropane	ND	2.0								

Qualifiers:

- | | |
|---|---|
| * Value exceeds Maximum Contaminant Level. | B Analyte detected in the associated Method Blank |
| D Sample Diluted Due to Matrix | E Value above quantitation range |
| H Holding times for preparation or analysis exceeded | J Analyte detected below quantitation limits |
| ND Not Detected at the Reporting Limit | P Sample pH Not In Range |
| R RPD outside accepted recovery limits | RL Reporting Detection Limit |
| S % Recovery outside of range due to dilution or matrix | W Sample container temperature is out of limit as specified |

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B24

27-May-16

Client: LTE
Project: FCA Boller release

Sample ID	rb	SampType:	MBLK	TestCode:	EPA Method 8260B: VOLATILES						
Client ID:	PBW	Batch ID:	A34458	RunNo:	34458						
Prep Date:		Analysis Date:	5/25/2016	SeqNo:	1063592	Units:	µg/L				
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual	
Vinyl chloride	ND	1.0									
Xylenes, Total	ND	1.5									
Surr: 1,2-Dichloroethane-d4	9.0		10.00		89.6	70	130				
Surr: 4-Bromofluorobenzene	9.6		10.00		96.2	70	130				
Surr: Dibromofluoromethane	9.8		10.00		97.9	70	130				
Surr: Toluene-d8	9.8		10.00		98.0	70	130				

Sample ID	1605b24-001ams	SampType:	MS	TestCode:	EPA Method 8260B: VOLATILES						
Client ID:	WS-01	Batch ID:	A34458	RunNo:	34458						
Prep Date:		Analysis Date:	5/25/2016	SeqNo:	1063594	Units:	µg/L				
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual	
Benzene	23	1.0	20.00	0.4986	111	70	130				
Toluene	23	1.0	20.00	1.947	103	70	130				
Chlorobenzene	19	1.0	20.00	0	94.4	70	130				
1,1-Dichloroethene	22	1.0	20.00	0	112	70	130				
Trichloroethene (TCE)	19	1.0	20.00	0	94.9	70	130				
Surr: 1,2-Dichloroethane-d4	9.3		10.00		92.6	70	130				
Surr: 4-Bromofluorobenzene	9.9		10.00		99.1	70	130				
Surr: Dibromofluoromethane	10		10.00		103	70	130				
Surr: Toluene-d8	9.6		10.00		95.7	70	130				

Sample ID	1605b24-001amsd	SampType:	MSD	TestCode:	EPA Method 8260B: VOLATILES						
Client ID:	WS-01	Batch ID:	A34458	RunNo:	34458						
Prep Date:		Analysis Date:	5/25/2016	SeqNo:	1063595	Units:	µg/L				
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual	
Benzene	22	1.0	20.00	0.4986	106	70	130	5.00	20		
Toluene	22	1.0	20.00	1.947	102	70	130	1.54	20		
Chlorobenzene	19	1.0	20.00	0	93.4	70	130	1.11	20		
1,1-Dichloroethene	20	1.0	20.00	0	101	70	130	10.5	20		
Trichloroethene (TCE)	19	1.0	20.00	0	92.7	70	130	2.27	20		
Surr: 1,2-Dichloroethane-d4	9.6		10.00		96.0	70	130	0	0		
Surr: 4-Bromofluorobenzene	9.2		10.00		91.9	70	130	0	0		
Surr: Dibromofluoromethane	10		10.00		101	70	130	0	0		
Surr: Toluene-d8	10		10.00		100	70	130	0	0		

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B24

27-May-16

Client: LTE
Project: FCA Boller release

Sample ID	MB-25483	SampType:	MBLK	TestCode:	EPA Method 7470: Mercury					
Client ID:	PBW	Batch ID:	25483	RunNo:	34498					
Prep Date:	5/24/2016	Analysis Date:	5/26/2016	SeqNo:	1064042	Units:	mg/L			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Mercury	ND	0.00020								

Sample ID	LCS-25483	SampType:	LCS	TestCode:	EPA Method 7470: Mercury					
Client ID:	LCSW	Batch ID:	25483	RunNo:	34498					
Prep Date:	5/24/2016	Analysis Date:	5/26/2016	SeqNo:	1064043	Units:	mg/L			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Mercury	0.0051	0.00020	0.005000	0	103	80	120			

Sample ID	1605B24-001CMS	SampType:	MS	TestCode:	EPA Method 7470: Mercury					
Client ID:	WS-01	Batch ID:	25483	RunNo:	34498					
Prep Date:	5/24/2016	Analysis Date:	5/26/2016	SeqNo:	1064045	Units:	mg/L			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Mercury	0.0053	0.00020	0.005000	0.0001458	103	75	125			

Sample ID	1605B24-001CMSD	SampType:	MSD	TestCode:	EPA Method 7470: Mercury					
Client ID:	WS-01	Batch ID:	25483	RunNo:	34498					
Prep Date:	5/24/2016	Analysis Date:	5/26/2016	SeqNo:	1064046	Units:	mg/L			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Mercury	0.0053	0.00020	0.005000	0.0001458	103	75	125	0.643	20	

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B24

27-May-16

Client: LTE
Project: FCA Boller release

Sample ID: MB-25513	SampType: MBLK	TestCode: EPA 6010B: Total Recoverable Metals
Client ID: PBW	Batch ID: 25513	RunNo: 34500
Prep Date: 5/25/2016	Analysis Date: 5/26/2016	SeqNo: 1064085 Units: mg/L

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Arsenic	ND	0.020								
Barium	ND	0.020								
Cadmium	ND	0.0020								
Calcium	ND	1.0								
Chromium	ND	0.0060								
Iron	ND	0.050								
Lead	ND	0.0050								
Magnesium	ND	1.0								
Manganese	ND	0.0020								
Potassium	ND	1.0								
Selenium	ND	0.050								
Silver	ND	0.0050								
Sodium	ND	1.0								

Sample ID: LCS-25513	SampType: LCS	TestCode: EPA 6010B: Total Recoverable Metals
Client ID: LCSW	Batch ID: 25513	RunNo: 34500
Prep Date: 5/25/2016	Analysis Date: 5/26/2016	SeqNo: 1064086 Units: mg/L

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Arsenic	0.52	0.020	0.5000	0	104	80	120			
Barium	0.50	0.020	0.5000	0	100	80	120			
Cadmium	0.50	0.0020	0.5000	0	101	80	120			
Calcium	53	1.0	50.00	0	106	80	120			
Chromium	0.50	0.0060	0.5000	0	99.4	80	120			
Iron	0.50	0.050	0.5000	0	101	80	120			
Lead	0.50	0.0050	0.5000	0	99.4	80	120			
Magnesium	51	1.0	50.00	0	102	80	120			
Manganese	0.50	0.0020	0.5000	0	99.3	80	120			
Potassium	49	1.0	50.00	0	97.7	80	120			
Selenium	0.50	0.050	0.5000	0	100	80	120			
Silver	0.10	0.0050	0.1000	0	102	80	120			
Sodium	50	1.0	50.00	0	99.5	80	120			

Sample ID: 1605B24-001CMS	SampType: MS	TestCode: EPA 6010B: Total Recoverable Metals
Client ID: WS-01	Batch ID: 25513	RunNo: 34500
Prep Date: 5/25/2016	Analysis Date: 5/26/2016	SeqNo: 1064090 Units: mg/L

Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Arsenic	0.53	0.020	0.5000	0	106	75	125			
Barium	0.62	0.020	0.5000	0.1181	99.6	75	125			

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B24
27-May-16

Client: LTE
Project: FCA Boller release

Sample ID 1605B24-001CMS		SampType: MS		TestCode: EPA 6010B: Total Recoverable Metals						
Client ID: WS-01		Batch ID: 25513		RunNo: 34500						
Prep Date: 5/25/2016		Analysis Date: 5/26/2016		SeqNo: 1064090		Units: mg/L				
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Cadmium	0.50	0.0020	0.5000	0	100	75	125			
Calcium	85	1.0	50.00	31.81	107	75	125			
Chromium	0.50	0.0060	0.5000	0	99.3	75	125			
Lead	0.50	0.0050	0.5000	0.007170	97.9	75	125			
Magnesium	53	1.0	50.00	1.701	103	75	125			
Manganese	0.61	0.0020	0.5000	0.1134	98.7	75	125			
Potassium	52	1.0	50.00	2.938	98.0	75	125			
Selenium	0.51	0.050	0.5000	0	102	75	125			
Silver	0.10	0.0050	0.1000	0	102	75	125			
Sodium	57	1.0	50.00	7.418	99.9	75	125			

Sample ID 1605B24-001CMSD		SampType: MSD		TestCode: EPA 6010B: Total Recoverable Metals						
Client ID: WS-01		Batch ID: 25513		RunNo: 34500						
Prep Date: 5/25/2016		Analysis Date: 5/26/2016		SeqNo: 1064091		Units: mg/L				
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Arsenic	0.54	0.020	0.5000	0	108	75	125	1.85	20	
Barium	0.62	0.020	0.5000	0.1181	101	75	125	0.998	20	
Cadmium	0.51	0.0020	0.5000	0	101	75	125	1.01	20	
Calcium	86	1.0	50.00	31.81	107	75	125	0.262	20	
Chromium	0.50	0.0060	0.5000	0	100	75	125	1.16	20	
Lead	0.50	0.0050	0.5000	0.007170	99.2	75	125	1.28	20	
Magnesium	53	1.0	50.00	1.701	102	75	125	0.834	20	
Manganese	0.61	0.0020	0.5000	0.1134	99.9	75	125	1.01	20	
Potassium	52	1.0	50.00	2.938	97.4	75	125	0.583	20	
Selenium	0.51	0.050	0.5000	0	102	75	125	0.323	20	
Silver	0.10	0.0050	0.1000	0	102	75	125	0.343	20	
Sodium	57	1.0	50.00	7.418	99.3	75	125	0.482	20	

Sample ID 1605B24-001CMS		SampType: MS		TestCode: EPA 6010B: Total Recoverable Metals						
Client ID: WS-01		Batch ID: 25513		RunNo: 34500						
Prep Date: 5/25/2016		Analysis Date: 5/26/2016		SeqNo: 1064099		Units: mg/L				
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Iron	1.5	0.25	0.5000	0.7554	147	75	125			S

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B24

27-May-16

Client: LTE
Project: FCA Boller release

Sample ID	1605B24-001CMSD	SampType:	MSD	TestCode:	EPA 6010B: Total Recoverable Metals					
Client ID:	WS-01	Batch ID:	25513	RunNo:	34500					
Prep Date:	5/25/2016	Analysis Date:	5/26/2016	SeqNo:	1064100	Units:	mg/L			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Iron	1.6	0.25	0.5000	0.7554	160	75	125	4.52	20	S

Sample ID	1605B24-001CPS	SampType:	PS	TestCode:	EPA 6010B: Total Recoverable Metals					
Client ID:	WS-01	Batch ID:	25513	RunNo:	34500					
Prep Date:		Analysis Date:	5/26/2016	SeqNo:	1064102	Units:	mg/L			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Iron	3.2	0.25	2.500	0.7554	98.9	80	120			

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B24

27-May-16

Client: LTE
Project: FCA Boller release

Sample ID mb-1	SampType: mblk	TestCode: SM2320B: Alkalinity								
Client ID: PBW	Batch ID: R34491	RunNo: 34491								
Prep Date:	Analysis Date: 5/25/2016	SeqNo: 1063833	Units: mg/L CaCO3							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Total Alkalinity (as CaCO3)	ND	20.00								

Sample ID ics-1	SampType: ics	TestCode: SM2320B: Alkalinity								
Client ID: LCSW	Batch ID: R34491	RunNo: 34491								
Prep Date:	Analysis Date: 5/25/2016	SeqNo: 1063834	Units: mg/L CaCO3							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Total Alkalinity (as CaCO3)	77.20	20.00	80.00	0	96.5	90	110			

Sample ID mb-2	SampType: mblk	TestCode: SM2320B: Alkalinity								
Client ID: PBW	Batch ID: R34491	RunNo: 34491								
Prep Date:	Analysis Date: 5/25/2016	SeqNo: 1063857	Units: mg/L CaCO3							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Total Alkalinity (as CaCO3)	ND	20.00								

Sample ID ics-2	SampType: ics	TestCode: SM2320B: Alkalinity								
Client ID: LCSW	Batch ID: R34491	RunNo: 34491								
Prep Date:	Analysis Date: 5/25/2016	SeqNo: 1063858	Units: mg/L CaCO3							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Total Alkalinity (as CaCO3)	77.84	20.00	80.00	0	97.3	90	110			

Sample ID icsd-1	SampType: icsd	TestCode: SM2320B: Alkalinity								
Client ID: LCSS02	Batch ID: R34491	RunNo: 34491								
Prep Date:	Analysis Date: 5/25/2016	SeqNo: 1063860	Units: mg/L CaCO3							
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Total Alkalinity (as CaCO3)	78.56	20.00	80.00	0	98.2	90	110	1.75	20	

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1605B24

27-May-16


Client: LTE
Project: FCA Boller release

Sample ID	MB-25493	SampType:	MBLK	TestCode:	SM2540C MOD: Total Dissolved Solids					
Client ID:	PBW	Batch ID:	25493	RunNo:	34507					
Prep Date:	5/25/2016	Analysis Date:	5/26/2016	SeqNo:	1064181	Units:	mg/L			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Total Dissolved Solids	ND	20.0								

Sample ID	LCS-25493	SampType:	LCS	TestCode:	SM2540C MOD: Total Dissolved Solids					
Client ID:	LCSW	Batch ID:	25493	RunNo:	34507					
Prep Date:	5/25/2016	Analysis Date:	5/26/2016	SeqNo:	1064182	Units:	mg/L			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Total Dissolved Solids	1000	20.0	1000	0	100	80	120			

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified



Hall Environmental Analysis Laboratory
 4901 Hawkins NE
 Albuquerque, NM 87109
 TEL: 505-345-3975 FAX: 505-345-4107
 Website: www.hallenvironmental.com

Sample Log-In Check List

Client Name: LTE

Work Order Number: 1605B24

RcptNo: 1

Received by/date: UMC 05/25/16

Logged By: Anne Thorne 5/25/2016 7:45:00 AM *Anne Thorne*

Completed By: Anne Thorne 5/25/2016 *Anne Thorne*

Reviewed By: JO 05/25/16

Chain of Custody

- 1. Custody seals intact on sample bottles? Yes No Not Present
- 2. Is Chain of Custody complete? Yes No Not Present
- 3. How was the sample delivered? Courier

Log In

- 4. Was an attempt made to cool the samples? Yes No NA
- 5. Were all samples received at a temperature of >0° C to 6.0°C Yes No NA
- 6. Sample(s) in proper container(s)? Yes No
- 7. Sufficient sample volume for indicated test(s)? Yes No
- 8. Are samples (except VOA and ONG) properly preserved? Yes No
- 9. Was preservative added to bottles? Yes No NA
- 10. VOA vials have zero headspace? Yes No No VOA Vials
- 11. Were any sample containers received broken? Yes No
- 12. Does paperwork match bottle labels?
(Note discrepancies on chain of custody) Yes No
- 13. Are matrices correctly identified on Chain of Custody? Yes No
- 14. Is it clear what analyses were requested? Yes No
- 15. Were all holding times able to be met?
(If no, notify customer for authorization.) Yes No

of preserved bottles checked for pH: 1
 (2 or >12 unless noted)
 Adjusted? _____
 Checked by: AT 05/25/16

Special Handling (if applicable)

- 16. Was client notified of all discrepancies with this order? Yes No NA

Person Notified:	<input type="text"/>	Date:	<input type="text"/>
By Whom:	<input type="text"/>	Via:	<input type="checkbox"/> eMail <input type="checkbox"/> Phone <input type="checkbox"/> Fax <input type="checkbox"/> In Person
Regarding:	<input type="text"/>		
Client Instructions:	<input type="text"/>		

17. Additional remarks:

18. Cooler Information

Cooler No	Temp °C	Condition	Seal Intact	Seal No	Seal Date	Signed By
1	1.9	Good	Yes			

Chain-of-Custody Record

Turn-Around Time: ASAP

Standard Rush 24 hour

Project Name: Milagro AC
FCA Boiler release

Project #: TBD

Project Manager: Ashley Ager

Sampler: Alex Crooks

On Ice: Yes No

Sample Temperature: 9

Client: UT Environmental

Billing Address: 848 E 2nd Ave
Durango, CO 81301


Phone #: 970-385-1096

Email or Fax#: AAGER@LTENV.COM

QC Package:
 Standard Level 4 (Full Validation)

Creditation:
 NELAP Other _____

EDD (Type) _____



HALL ENVIRONMENTAL ANALYSIS LABORATORY

www.hallenvironmental.com
4901 Hawkins NE - Albuquerque, NM 87109
Tel. 505-345-3975 Fax 505-345-4107

RFH
AT
05/25/16

Analysis Request

Date	Time	Matrix	Sample Request ID	Container Type and #	Preservative Type	HEAL No.	BTEX + MTBE + TMB's (8021)	BTEX + MTBE + TPH (Gas only)	TPH 8015B (GRO / DRO / MRO)	TPH (Method 418.1)	EDB (Method 504.1)	PAH's (8310 or 8270 SIMS)	RCRA 8 Metals + Hexachlor	Anions (F, Cl, NO ₃ , NO ₂ , PO ₄ , SO ₄)	8081 Pesticides / 8082 PCB's	8260B (VOA)	8270 (Semi-VOA)	P# , e.g., TPS, Aik	General Chem	Phos, Ca, Fe, Mg, Mn	N, S, K	Air Bubbles (Y or N)	
5/24	1000	H ₂ O	Milagro AC WS-01	Vapors/5	HNO ₃ + cool	1605B24 201							X	X	X			X	X	X	X		

Date: 5/24	Time: 1421	Relinquished by: <u>Alex Crooks</u>	Received by: <u>Christina White</u>	Date: 5/24/16	Time: 1421
Date: 5/24/16	Time: 1942	Relinquished by: <u>Christina White</u>	Received by: <u>[Signature]</u>	Date: 05/25/16	Time: 0745

Remarks: CC: Bherb@ltenv.com No #2504 bottle for phos
A Crooks@ltenv.com At 05/25/16

If necessary, samples submitted to Hall Environmental may be subcontracted to other accredited laboratories. This serves as notice of this possibility. Any sub-contracted data will be clearly notated on the analytical report.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 17 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Williams Four Corners LLC	Contact Mitch Morris
Address 1755 Arroyo Drive, Bloomfield, NM 87413	Telephone No. 505-632-4708
Facility Name Kutz Canyon Gas Plant	Facility Type Natural Gas Processing Plant
Surface Owner Bureau of Land Management	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	13	28N	11W					San Juan

Latitude 36° 40.064 N Longitude 107° 57.795 W

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 216.650 MCF	Volume Recovered 0
Source of Release Pressure Relief Valve (PRV)	Date and Hour of Occurrence 6/11/2016, 09:29 AM MST	Date and Hour of Discovery 6/11/2016, 09:29 AM MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Not Applicable	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not Applicable	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Power to the DCS in the control room was lost. The lead operator was unable to see/manage pressure in the Kutz II process. Overpressure conditions occurred in the Kutz II Demethanizer tower, allowing a PRV to lift. The Demethanizer overhead PRV was allowed to re-seat itself once pressures returned to normal conditions. Pressure Relief Valves (PRV) are designed to open at a predetermined set point to protect the integrity of equipment and ensure safe operating conditions.

Describe Area Affected and Cleanup Action Taken.*

No cleanup required with a gas release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Mitch Morris	Approval Date: 6/30/2016	Expiration Date:
Title: Environmental Specialist	Conditions of Approval: 	
E-mail Address: Mitch.Morris@williams.com	Attached <input type="checkbox"/>	
Date: 06/13/2016 Phone: 505-632-4708		

* Attach Additional Sheets If Necessary

NVF1618251848

①