

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 29 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DAB1621456729

OPERATOR

Initial Report Final Report

260737

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS 002H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-37147
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	11	24S	30E	255		1300		Eddy

Latitude: 32.225975 Longitude: 103.847008

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 20 Barrels Oil	Volume Recovered: 20 barrels oil
Source of Release: Broken Sight Glass on production vessel	Date and Hour of Occurrence: 7-26-16 @ 1:00pm	Date and Hour of Discovery: 7-26-16 @ 2:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A sight glass broke on the production vessel releasing 20 barrels of oil to the lined containment. A vacuum truck was called to the location and was able to recover the majority of the fluid (very small amount remains due to production equipment). A very light mist covered a small area of caliche, this area has been scraped up and disposed of properly.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was called to the location and recovered the fluid from inside the lined containment. A backhoe was utilized to scrape up the lightly misted caliche area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>8/1/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: <i>7-28-16</i> Phone: 432-214-3704		

* Attach Additional Sheets If Necessary

2RP-3814

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Thursday, July 28, 2016 1:47 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Tucker, Shelly (stucker@blm.gov)
Cc: Blevins, Bradley
Subject: Initial/ Final C-141 PLU CVX JV BS 002H
Attachments: scan.pdf

Please find the attached initial/ final C-141 for the release that occurred at the PLU CVX JV BS 002H. If you have any questions or concerns please let me know. Thank you

Brad Blevins
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com