



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number:** pJXK1621139948

**1RP - 2743**

**NEW MEXICO SALT WATER DISPOSAL CO., INC**

### Release Notification and Corrective Action

#### OPERATOR

Initial Report     Final Report

Name of Company: New Mexico Salt Water Disposal Co.	Contact: William V. Palmer
Address: P.O. Box 1518 Roswell, NM 88202	Telephone No.: 575-396 5391
Facility Name: Simanola Main Station #11	Facility Type: Battery

Surface Owner: STATE	Mineral Owner	Lease No.:
----------------------	---------------	------------

#### LOCATION OF RELEASE

Unit Letter L	Section 21	Township 10S	Range 34E	Feet from the 2,606	North/South Line SOUTH	Feet from the 613'	East/West Line WEST	County LEA
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	---------------

Latitude: 33.432390

Longitude: -103.475694

#### NATURE OF RELEASE


Type of Release: produce water and oil	Volume of Release: 600BBL	Volume Recovered: 0BBLs
Source of Release: EXTERNAL EROSION (ROCK RUBBED HOLE ON SIDE OF P/L)	Date and Hour of Occurrence: between 10-5 & 6-11	Date and Hour of Discovery: 10-6-11 11:30AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? William V. Palmer called Maxey Brown	
By Whom? William V. Palmer	Date and Hour: 10-6-11 3:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* rock lying to close to p/l when installed and eventually rubbed hole on side of pipeline. Pipeline was shut in at Sta. 11, backhoe was called in to excavate leak area, WEE Inc./ET of NM called to document leak.

Describe Area Affected and Cleanup Action Taken.\* water ran from the leak source on the w. side of pipeline total distance 464'L x 34'W, and also to the east side of the pipeline 136' x 152'. Total approx. sqft is 32,132. TBS was called in to immediately start haul off of material. NMSWD will be slip lining the existing pipeline with a new poly line to help prevent future line leaks. WEE Inc. / ET of NM has been contracted for delineation of site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: William V. Palmer	Approved by <sup>ENV ENGINEER:</sup> District Supervisor: 	
Title: Manager	Approval Date: 10/21/11	Expiration Date: 12/21/11
E-mail Address:	Conditions of Approval: SUBMIT FINAL C-141 BY 12/21/11.	Attached <input type="checkbox"/>
Date: 10-21-11      Phone: 575.396.5391		IRP-10-11-2743

\* Attach Additional Sheets If Necessary