




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1621536472

1RP - 2810

BC OPERATING, INC.

RECEIVED

MAR 26 2012

HOBBSUCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <i>B.C. Operating</i>	Contact <i>Jerry Livingston</i>
Address	Telephone No.
Facility Name <i>WH Phades B NCT 1-#10</i>	Facility Type <i>Flowline</i>
Surface Owner <i>FED</i>	Mineral Owner
	API No. <i>30-025-12056</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>M</i>	<i>26</i>	<i>26S</i>	<i>37E</i>	<i>660</i>		<i>1980</i>		<i>LEA</i>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <i>Produced water</i>	Volume of Release <i>20 BBL</i>	Volume Recovered <i>0</i>
Source of Release <i>Flowline</i>	Date and Hour of Occurrence <i>10-22</i>	Date and Hour of Discovery <i>10-22</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Geoffrey Becking oca</i>	
By Whom? <i>Jacob Malancon</i>	Date and Hour <i>3-22-12</i>	<i>3:00 p.m.</i>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>none</i>	

If a Watercourse was Impacted, Describe Fully.*
none *GW @ 180'*

Describe Cause of Problem and Remedial Action Taken.*
Flowline leaked in pasture area west of Hwy 18 causing 20 BBL water to spill onto ground. 0 Barrels was recovered

Describe Area Affected and Cleanup Action Taken.*
Pasture area west of Hwy 18 20 BBL in pasture plan to dig out like fix line and then remediate site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michael Butler</i>	OIL CONSERVATION DIVISION		
Printed Name: <i>Michael Butler</i>	Approved by Environmental Specialist: <i>Jeff Becking</i>		
Title: <i>Permpur</i>	Approval Date: <i>5-18-12</i>	Expiration Date: <i>7-18-12</i>	
E-mail Address: <i>butler911@earthlink.net</i>	Conditions of Approval: <i>SUBMIT FINAL</i>		Attached <input type="checkbox"/>
Date: <i>3-23-12</i>	Phone: <i>432-940-7947</i>	<i>C-141 BY 7-18-12</i>	<i>IRP-5-12-2810</i>

* Attach Additional Sheets If Necessary