




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1621536619

1RP - 2811

BC OPERATING, INC.

District I
1625 N French Dr., Hobbs, NM 88240
District II
811 S First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company <i>B.C. operating</i>	Contact <i>Jerry Livingston</i>
Address	Telephone No. <i>432-664-3189</i>
Facility Name <i>RYB NCT 1-9</i>	Facility Type <i>Injection Well</i>
Surface Owner <i>FED</i>	Mineral Owner
API No. <i>30-025-12070</i>	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>P</i>	<i>27</i>	<i>265</i>	<i>37E</i>	<i>660</i>		<i>660</i>		<i>Lea</i>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <i>Produced water</i>	Volume of Release <i>15 BBL</i>	Volume Recovered <i>0</i>
Source of Release <i>Flowline</i>	Date and Hour of Occurrence <i>5-1</i>	Date and Hour of Discovery <i>5-2</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>2:00p.m.</i>	<i>11:00</i>
By Whom? <i>Jason Melancon</i>	Date and Hour <i>5-2-2012 3:00p.m.</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>0</i>	

If a Watercourse was Impacted, Describe Fully.*

none

190'

Describe Cause of Problem and Remedial Action Taken.*

Injection line had leak north of pad in pasture area causing 15 BBL to leak out into pasture, no fluid was recovered.

Describe Area Affected and Cleanup Action Taken.*

Pasture area north of pad - Dig out line put clamp on hole then scrape and haul contamination and sampler area

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Michael Butler</i>	Approved by Environmental Specialist:	
Printed Name: <i>Michael Butler</i>	Approval Date: <i>5-18-12</i>	Expiration Date: <i>7-18-12</i>
Title: <i>Pumper</i>	Conditions of Approval: <i>SUBMIT FINAL C-141</i>	
E-mail Address: <i>butler911@earthlink.net</i>	Attached <input type="checkbox"/>	<i>IRP-5-12-2811</i>
Date: _____ Phone: <i>532-940-7947</i>	<i>BY 7-18-12</i>	

* Attach Additional Sheets If Necessary

HOBBS OCD

MAY 04 2012

RECEIVED