



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKL1622234270

1RP - 4390

LEGACY RESERVES OPERATING, LP

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company - Legacy Reserves, LP	Contact - Brian Cunningham	
Address P.O. Box 10848 Midland, TX 79702	Telephone No. 432-234-9450	
Facility Name - Inca Federal #007 Line	Facility Type - Water Line	
Surface Owner - Federal	Mineral Owner - Federal	API No. 30-025-30061

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	17	18S	32E	660	North	1980	West	Lea

Latitude 32.743771 Longitude -103.807676

NATURE OF RELEASE

Type of Release - Produced Water	Volume of Release - ?	Volume Recovered - 0
Source of Release - Flow line leak	Date and Hour of Occurrence - ?	Date and Hour of Discovery -11/13/15 5:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kelly Jones	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A pipeline plane located a leak on Friday afternoon. Leak is contained and work plan is being drafted for approval.

Describe Area Affected and Cleanup Action Taken.*

Affected area is approximately 3,380 sq ft.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brian Cunningham	Approved by Environmental Specialist:	
Title: Production Foreman	Approval Date:	Expiration Date:
E-mail Address: bcunningham@legacyp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/16/15	Phone: 432 234 9450	

* Attach Additional Sheets If Necessary

Inca Water Line Leak

Sample Map

Legend

-  Sample Points
-  Will 693 Pasture



Google earth



100 ft