

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 11 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1622536836 OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS 007H (AKA BS 2-25-30 Battery)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner:	API No. 30-015-39344
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	2	25S	30E	350		1980		Eddy

Latitude: 32.153461 Longitude: 103.849312

NATURE OF RELEASE

Type of Release: Oil/ Produced Water	Volume of Release: 30 barrels of oil. 120 barrels PW	Volume Recovered: 30 barrels oil and 120 barrels of PW
Source of Release: Tank Overflowed	Date and Hour of Occurrence: 8-5-16 @ 11:00am	Date and Hour of Discovery: 8-5-16 @ 1:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson	
By Whom? Bradley Blevins	Date and Hour: 8-5-16 @ 5:57pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
BOPCO EHS was notified of a release that occurred at the Big Sinks 2-25-30 Battery (PLU CVX JV BS 007H), fluid was released due to suction screens being plugged up causing tanks to run over into impervious containment. All fluid remained inside the lined containment with the exception of a light mist in front of the lact area.

Describe Area Affected and Cleanup Action Taken.* A vacuum truck was called to the location and recovered the fluid from the impervious containment (150 barrels). The light misted area will be scraped up and hauled to disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>8/12/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: <i>8-11-16</i> Phone: 432-214-3704		

* Attach Additional Sheets If Necessary

ARD 3826

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Thursday, August 11, 2016 9:37 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: PLU CVX JV BS 007H (AKA BS 2-25-30 Battery) C-141
Attachments: C-141 PLU CVX JV BS 007H_8-5-16.pdf

Mike/ Heather

Please find the attached initial/ final C-141 for the release that occurred at the PLU CVX JV BS 007H. If you have any questions please let me know. Thanks

Brad Blevins
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Friday, August 05, 2016 5:57 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: Plu Big Sinks 2-25-30 Battery.

Mike/ Heather

BOPCO EHS was notified of a release that occurred at the Plu BS 2-25-30 battery. SCADA alarms failed to send a high level tank notification causing the tank to overflow into the zero perm containment. A small area outside containment was misted and will be scraped up and hauled to disposal. I will follow up Monday with C-141. If you have any questions please let me know. Thanks

Sent from my iPhone