

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141
Revised August 8, 2011

AUG 12 2016
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB16228386116

OPERATOR Initial Report Final Report

Name of Company: Chevron USA Inc. <i>4323</i>	Contact: Josepha DeLeon
Address: 1616 W. Bender Blvd, Hobbs, NM 88240	Telephone No.: 432-425-1528
Facility Name: Ross Ranch 6 Fed IH	Facility Type: Pipeline

Surface Owner: BLM	Mineral Owner	API No. : 30-015-36883
--------------------	---------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	06	26S	30E	350	South	1330	East	Eddy

Latitude: N32W 03' 55.15" Longitude: W 103° 55'08.57"

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 83.5 BW	Volume Recovered: 83 BW
Source of Release: Heater Treater Mechanical Failure	Date and Hour of Occurrence: 7/30/2016; 7:30 p.m.	Date and Hour of Discovery: 7/30/2016; 7:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES. To Whom? Jim Amos - BLM; Heather Patterson - NMOCD via phone message and follow up with email	
By Whom? Josepha DeLeon	Date and Hour: 7/30/2016; 4:18 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES. Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Heater Treater mechanical failure leading to water leak. Shut and secure well Call a vacuum truck and remove all water from containment		
Describe Area Affected and Cleanup Action Taken.* We have contacted EPI to help us put together a work plan for clean up at this lease.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Josepha DeLeon</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Josepha DeLeon	Approval Date: <i>8/15/16</i>	Expiration Date: <i>NIA</i>
Title: HES Compliance Support - Environmental Specialist	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
E-mail Address: jdxdc@chevron.com	SUBMIT REMEDIATION PROPOSAL NO	
Date: 8/12/2016 Phone: 432-425-1528	LATER THAN: <i>9/15/16</i>	

* Attach Additional Sheets If Necessary

ARI-3832

Patterson, Heather, EMNRD

From: DeLeon, Josepha <JDXD@chevron.com>
Sent: Friday, August 12, 2016 1:43 PM
To: Patterson, Heather, EMNRD; jamos@blm.gov
Cc: Debeyssey, Svetlana; Barakat, Eli; Klahsen, Kim D. (kdkl); Davis, Allen
Subject: RE: ROSS RANCH SPILL - 83.5 BBLS PW
Attachments: Ross Ranch C-141 07302016.pdf

Attached is the completed C-141 for this spill. A copy will be shared with EPI for cleanup of this lease.

Josie DeLeon, HES Specialist -

Compliance Support - Environmental

Chevron - MCBU

(SE NM Areas, Dollarhide, Eunice, Hobbs and Vacuum)

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

jdx@chevron.com

<https://www.chevroncontractorsafety.com/contractormcbu/> - CHESM Contractor Website



Green/Red - The Doing Thinker

From: DeLeon, Josepha
Sent: Saturday, July 30, 2016 4:18 PM
To: 'Patterson, Heather, EMNRD'; 'jamos@blm.gov'
Cc: Debeyssey, Svetlana; Barakat, Eli; Klahsen, Kim D. (kdkl)
Subject: ROSS RANCH SPILL - 83.3 BBLS PW

As stated in the voice message that I left today with Heather (NMOCD) and Jim (BLM). Chevron had a 83. BBLS produced water and a "shine of oil" spill at the Ross Ranch today due to a heater treater failure today. I received notification at approximately 3:45 p.m. All fluid was in secondary containment and most all was recovered. Everything is under control and PW has been recovered. I will follow up with exact volumes and remediation plan on Monday and a C-141 to the state and BLM.

Josie DeLeon, HES Specialist -

Compliance Support - Environmental

Chevron - MCBU

(SE NM Areas, Dollarhide, Eunice, Hobbs and Vacuum)

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

idxd@chevron.com

<https://www.chevroncontractorsafety.com/contractormcbu/> - CHESM Contractor Website



Green/Red – The Doing Thinker

Patterson, Heather, EMNRD

From: DeLeon, Josepha <JDxD@chevron.com>
Sent: Saturday, July 30, 2016 4:18 PM
To: Patterson, Heather, EMNRD; jamos@blm.gov
Cc: Debeysey, Svetlana; Barakat, Eli; Klahsen, Kim D. (kdkl)
Subject: ROSS RANCH SPILL - 83.3 BBLs PW

As stated in the voice message that I left today with Heather (NMOCD) and Jim (BLM). Chevron had a 83.3 BBLs produced water and a "shine of oil" spill at the Ross Ranch today due to a heater treater failure today. I received notification at approximately 3:45 p.m. All fluid was in secondary containment and most all was recovered. Everything is under control and PW has been recovered. I will follow up with exact volumes and remediation plan on Monday and a C-141 to the state and BLM.

Josie DeLeon, HES Specialist -

Compliance Support - Environmental

Chevron - MCBU

(SE NM Areas, Dollarhide, Eunice, Hobbs and Vacuum)

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

jdxd@chevron.com

<https://www.chevroncontractorsafety.com/contractormcbu/> - CHESM Contractor Website



Green/Red - The Doing Thinker