

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT Form C-141  
Revised August 8, 2011

AUG 12 2016  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*DABI/223839080*

Name of Company: COG Operating LLC <i>217455</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 600 West Illinois Avenue, Midland TX 79701		Contact: Robert McNeill		
Facility Name: BULLSEYE 22 STATE COM #001H		Telephone No. 432-683-7443		
		Facility Type: Tank Battery		
Surface Owner: State	Mineral Owner:	API No. 30-015-40162		

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	22	24S	27E	330'	North	990'	West	

Latitude 32.2091255 Longitude 104.1840591

**NATURE OF RELEASE**

Type of Release: Oil and Produced Water	Volume of Release: 14bbbls of Oil / 2bbbls of Produced Water	Volume Recovered: 14bbbls of Oil / 2bbbls of Produced Water
Source of Release: Hole in Separator	Date and Hour of Occurrence: 08-05-2016 07:20 am	Date and Hour of Discovery: 08-05-2016 07:20 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A hole developed in the separator due to age. The separator will be repaired tested and put back into operation.

Describe Area Affected and Cleanup Action Taken.\*  
The release was contained within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment will be cleaned and the facility will be put back into operation. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>8/15/16</i>	Expiration Date: <i>NIA</i>
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: August 12, 2016 Phone: 432-683-7443	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary  
LATER THAN: *9/15/16* *ARP-3833*

**Patterson, Heather, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Friday, August 12, 2016 10:06 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; 'agroves@slo.state.nm.us'; 'dvstrang@slo.state.nm.us'; Martin, Ed; Naranjo, Mark M.  
**Subject:** Bullseyes 22 Sate Com #001H (TB) (Initial)  
**Attachments:** Bullseyes 22 Sate Com #001H (TB) (Initial).pdf


MR. BRATCHER / MS. GROVES,

ATTACHED IS A C-141 INITIAL FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

*THANK YOU,*

**ROBERT GRUBBS JR.  
SR. ENVIRONMENTAL COORDINATOR  
432.683.7443 (MAIN)  
432.818.2369 (DIRECT)  
432.661.6601 (CELL)  
432.221.0892 (FAX)  
[RGRUBBS@CONCHO.COM](mailto:RGRUBBS@CONCHO.COM)  
MAILING ADDRESS:  
ONE CONCHO CENTER  
600 W. ILLINOIS AVENUE  
MIDLAND, TEXAS 79701**

**CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.**



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.