




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pGRL1021441925

1RP - 2595

NEW MEXICO SALT WATER DISPOSAL COMPANY

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 R Brazos Road, Aztec, NM 87410
District IV
1220 S Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	New Mexico Salt Water Disp. Co.	Contact	James B. Read
Address	P. O. Box 1518, Roswell, NM 88202	Telephone No.	575-622-3770 ext. 310
Facility Name	Station 11	Facility Type	SWD Station 11

Surface Owner	State of New Mexico	Mineral Owner		Lease No.	
---------------	---------------------	---------------	--	-----------	--

LOCATION OF RELEASE

CONTINENTAL ST #1 30-025-22551

Unit Identifier	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	21	10S	34E	850	North	850	West	Lea

Latitude 33.43766 Longitude 103.47523

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	130 bbls	Volume Recovered	120 bbls
Source of Release	Tank	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jeff Leking	Occurred:	5/23/2010 PM
By Whom?	James B. Read	Date and Hour	05/25/2010	Discovered:	5/23/2010 PM
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

WATER @ 35'

Describe Cause of Problem and Remedial Action Taken.*

Unknown outside party turned upstream pump on. Overflowed emergency tank. Water stayed within berms. Trucks immediately vacuumed up majority of water.

Describe Area Affected and Cleanup Action Taken.*

Water immediately recovered. Excavate impacted soil and back fill with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printer Name:	James B. Read	ENV. ENGINEER:	Approved by District Supervisor
Title:	Agent	Approval Date:	08/02/10 Expiration Date: 10/04/10
E-mail Address:	jbro@brightok.net	Conditions of Approval:	DECLINE TO CLEAN UP. SUBMIT FINAL C-141 BY 10/04/10
Date:	05/25/2010 Phone: 575-622-3770	Attached	<input type="checkbox"/> IRP-10-8-2595

Attach Additional Sheets If Necessary