



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number: pGRL1324727056**

**1RP - 2900**

**SOUTHERN UNION GAS SERVICES, LTD**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Southern Union Gas Services	Contact	Curt Stanley
Address	801 S. Loop 464, Monahans, TX 79756	Telephone No.	575-390-7595
Facility Name	6 Inch Lateral (Chicken Farm)	Facility Type	Natural Gas Pipeline
Surface Owner	Claude Kizzar	Lease No.	30-025-38822

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	21	25S	37E					Lea

**Latitude** 32 degrees 06' 59.98" North **Longitude** 103 degrees 10' 25.15" West

**NATURE OF RELEASE**

Type of Release	Natural Gas, Crude Oil and Produced Water	Volume of Release	> 5 bbl	Volume Recovered	None
Source of Release	6 inch Natural Gas Pipeline	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	November 30, 2012 - 0830 hours
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

GW@95<sup>1</sup>



Describe Cause of Problem and Remedial Action Taken.\*

A D-6 Caterpillar Bulldozer operated by a 3<sup>rd</sup> Party struck a 6-inch steel pipeline, slip-lined with 4-inch poly pipe. The resulting pipeline release did not cause any fire, injury or property damage. The pipeline was shut in, repairs were completed and the pipeline was placed back in service.

Describe Area Affected and Cleanup Action Taken.\*

This release was initially deemed non-reportable to the NMOCD. During remediation activities, Southern Union opted to reclassify this release as a reportable release, due to the depth of soil impact. The remediation of this release is in progress and this release will be remediated to NMOCD regulatory standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Curt D. Stanley	 Approved by Environmental Specialist: <b>Environmental Specialist</b>	
Title: Environmental Specialist	Approval Date: 1/14/13	Expiration Date: 3/14/13
E-mail Address: curt.stanley@sug.com	Conditions of Approval: <b>SUBMIT FINAL C-141 BY</b> Attached <input type="checkbox"/>	
Date: January 11, 2013 Phone: 575-390-7595	<b>HOBBS OCD</b> <b>LRP-1-13-2900</b>	

\* Attach Additional Sheets If Necessary

JAN 14 2013

RECEIVED