



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number: pKL1623634204**

**1RP - 4412**

**KEVIN O. BUTLER & ASSOCIATES, INC.**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

AUG 22 2016

RECEIVED

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company	Kevin O. Butler & Associates, Inc.	Contact	Lisa Builta
Address	P.O. Box 1171 Midland, TX 79701	Telephone No.	432-682-1178
Facility Name	New Mexico State X	Facility Type	Well
Surface Owner	Mineral Owner	API No. 30-025-03941	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	20	17S	36E	660	FNL	1980	FEL	LEA

Latitude 32.8258476 Longitude -103.3747177 NAD 83

#### NATURE OF RELEASE

Type of Release	Oil	Volume of Release	Volume Recovered
Source of Release		Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?		Date and Hour	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Soil contamination was caused by an old previous spill. We have attempted in the past to clean area up but were confronted with resistance from the surface owner Dar Angel. He will not allow Kevin O. Butler & Associates to haul in clean dirt in order to finish our clean up efforts. He wants us to use dirt from his pit area. Knowing that this would not be OCD approved, our efforts have halted. Mr. Angel was to get back to us with a company that he would allow to bring in dirt but never did. We made several phone calls to Mr. Angel for which he did not return.

Describe Area Affected and Cleanup Action Taken.\*

We would like to be able to finish cleaning contaminated area by remove contaminated dirt, having it hauled off and have clean dirt brought in. This will require cooperation from the surface owner Dar Angel Will contact OCD once complete.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Lisa Builta	Approved by Environmental Specialist: 	
Title: Compliance Reporting	Approval Date: 8/23/16	Expiration Date: 10/23/16
E-mail Address: lisab@kobutler.com	Conditions of Approval: Discrete Samples and Remediate Per NMOCD Guidelines. Ensure SLO Concurrence / Approval.	
Date: 08/11/2016 Phone: 432-682-1178	Attached <input type="checkbox"/> IRP-4412 NKL1623633095 PKL1623634204	

\* Attach Additional Sheets If Necessary

Also please see attached email of requirement.

## Lynch, Kristen, EMNRD

---

**To:** lisab@kobutler.com  
**Cc:** Keyes, Jamie, EMNRD; Oberding, Tomas, EMNRD; agroves@slo.state.nm.us  
**Subject:** 1RP-4412 New Mexico State X Initial C141

Good Morning,

NMOCD did receive your Initial C-141 for the New Mexico State X Oil Well.

In response to your Initial C-141 which was dated 8/11/2016, NMOCD conducted an on-site inspection on 8/4/2016. It was observed and noted that the spill was both historic and recent in nature, as the separator was leaking on the day of inspection. NMOCD is requiring the following:

- A.) Verify Depth to Ground Water via NMOSE
- B.) Discrete Samples be taken
- C.) Delineation and Remediation work plan needs to be submitted by 10/23/2016, as this site needs immediate attention.
- D.) Notify NMOCD prior to sampling to provide opportunity for sample witnessing.

An electronic copy of the Initial C-141 will be uploaded to NMOCD website Administrative/Environmental Orders.

An electronic copy of the C-141 is preferred and can be sent to [Jamie.keyes@state.nm.us](mailto:Jamie.keyes@state.nm.us) and [Kristen.lynch@state.nm.us](mailto:Kristen.lynch@state.nm.us)

*Kristen D. Lynch  
Environmental Specialist, District 1  
Oil Conservation Division, EMNRD  
(575) 393-6161 ext. 111  
575-370-3180 (emergency-cell)*

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.