

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1623933126 OPERATOR # 245779

Initial Report

Final Report

Name of Company	Agua Sucia L.L.C.	Contact
Address	10026-A South Mingo Road 290 Tulsa OKL. 74011	Telephone No. 918-984-8174
Facility Name	East Shugart Unit	Facility Type Well #27

HMP

NM OIL CONSERVATION  
ARTESIA DISTRICT

AUG 23 2016

RECEIVED

Surface Owner	BLM	Mineral Owner	BLM	API No.	30-015-05677
---------------	-----	---------------	-----	---------	--------------

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	34	18S	31E					EDDY

Latitude 32.699501 Longitude 103.8540955

NATURE OF RELEASE

Type of Release	Oil & Water	Volume of Release	22 bbls.	Volume Recovered	20bbls
Source of Release	Well Head	Date and Hour of Occurrence		Date and Hour of Discovery	8-18-2016
Was Immediate Notice Given?	Yes No Not Required	If YES, To Whom?			
By Whom?	Denis Schoenhofer	Date and Hour	8-19-2016		
Was a Watercourse Reached?	Yes No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* Leak in the Casing Nipple, filled the cellar and had a small run over. Emptied the cellar and picked up the contaminated soil.					
Describe Area Affected and Cleanup Action Taken.* Contained within 20' radius of the well head. Take the contaminated soil to a permitted waste facility. Back fill the remediated area with clean material.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature: 		Approved by Environmental Specialist: 	
Printed Name: Denis Schoenhofer			
Title: Owner <i>J mm</i>		Approval Date: <i>9/20/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: SWKFC@aol.com		Conditions of Approval:	Attached
Date: 8/19/2016	Phone: <i>918-984-8176</i>		<i>2RP-3844</i>

\* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines  
 SUBMIT REMEDIATION PROPOSAL NO  
 LATER THAN: *9/20/16*

**Patterson, Heather, EMNRD**

---

**From:** jschoenhofer@cox.net  
**Sent:** Tuesday, August 23, 2016 7:44 AM  
**To:** Patterson, Heather, EMNRD  
**Cc:** stucker@blm.gov  
**Subject:** Agua Sucia C-141  
**Attachments:** c-141 8-2016.pdf

Attached are the C-141's for Agua Sucia....

Thanks!  
Denis Schoenhofer  
Agua Sucia