

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

SEP 15 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

NAB/03/0342939

Initial Report Final Report

Name of Company <u>Devon Energy Production Company 16137</u>	Contact <u>Jake Harrington, Production Foreman</u>
Address <u>6488 Seven Rivers Hwy Artesia, NM 88210</u>	Telephone No. <u>432-214-5175</u>
Facility Name <u>Cotton Draw Unit #153H</u>	Facility Type <u>Oil</u>
Surface Owner <u>Federal</u>	Mineral Owner <u>Federal</u> API No <u>30-015-38535</u>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	3	25S	31E	200	North	1980	East	Eddy

Latitude: 32.1661758 Longitude: -103.7636108

NATURE OF RELEASE

Type of Release <u>Produced water</u>	Volume of Release <u>42 Gallons</u>	Volume Recovered <u>39 Gallons</u>
Source of Release <u>Transfer pump</u>	Date and Hour of Occurrence <u>9/14/2016 @ 11:45pm</u>	Date and Hour of Discovery <u>9/14/2016 @ 11:45pm</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>OCD-Mike Bratcher</u> <u>BLM-Jim Amos</u>	
By Whom? <u>Lolo Martinez, Lease Operator</u>	Date and Hour <u>OCD- 9/15/2016 @ 1:15am</u> <u>BLM- 9/15/2016 @ 1:20am</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse <u>N/A</u>	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

Due to corrosion on the swage on the discharge side of the transfer pump 42 gallons of produce water was released. The well and water injection pump was shut down immediately to prevent further release. Repairs to the swage on discharge pump are in progress.

Describe Area Affected and Cleanup Action Taken.*

42 gallons of produced water was released from a corroded swage on the discharge pump that runs from the produced water tank. Approximately 39 gallons went into lined containment and 3 gallons sprayed into a Westerly direction into the pasture. The approximate area affected was 6ft x 6ft in the pasture West of water injection pump. Approximately 3 gallons of the released produced water sprayed in a Westerly direction away from the pad into the pasture. The liner was checked for holes, no holes were found. Vacuum truck recovered approximately 39 gallons of the released produced water. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Sarah Gallegos-Troublefield</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Sarah Gallegos-Troublefield</u>	Signed By <u>Mike Bratcher</u>	
Title: <u>Field Admin Support</u>	Approved by Environmental Specialist:	Approval Date: <u>9/19/16</u> Expiration Date: <u>N/A</u>
E-mail Address: <u>Sarah.Gallegos-Troublefield@dvn.com</u>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: <u>9/15/2016</u> Phone: <u>575.748.1864</u>	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 10/22/16

2 RP-3892

Bratcher, Mike, EMNRD

From: Gallegos-Troublefield, Sarah <Sarah.Gallegos-Troublefield@dvn.com>
Sent: Thursday, September 15, 2016 2:58 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett; Scrogum, Sandy
Subject: Cotton Draw Unit #153H_42 gallons_9-14-16_Initial C-141
Attachments: Cotton Draw Unit 153H_1BBL PW_9-14-15_Pic 3 of 3.jpg; Cotton Draw Unit 153H_1 BBL PW_9-14-16_GIS Image.pdf; Cotton Draw Unit 153H_1 BBL PW_9-14-16_Initial C-141.doc; Cotton Draw Unit 153H_1BBL PW_9-14-15_Pic 1 of 3.jpg; Cotton Draw Unit 153H_1BBL PW_9-14-15_Pic 2 of 3.jpg

Good afternoon,

Please find attached the Initial C-141, GIS Image and 3 photos of the Cotton Draw Unit #153H release of 42 gallons produced water that occurred on 9/14/2016. Please be advised that the blue dot in the GIS Image represents the approximate location of the origin of the release.
Please contact me with any questions you may have.

Thank you very much and have a wonderful day.

Respectfully,

Sarah Gallegos-Troublefield
Field Admin Support
Production

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 748 1864 Direct Line



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.