

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

State of New Mexico
Energy Minerals and Natural Resources

SEP 12 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NAB 1626355901 Release Notification and Corrective Action

FAB 1626355519

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company <i>10137</i>		Contact Jake Harrington, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210		Telephone No. 432-214-5175
Facility Name Cotton Draw Unit 11 BS CTB		Facility Type Central Tank Battery (CTB)
Surface Owner Federal	Mineral Owner Federal	API No N/A

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	11	25S	31E					Eddy

Latitude: 32°08'57.706 N

Longitude: -103°44'48.453 W

32.151993 N

103.746536 W

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5bbls	Volume Recovered 5bbls
Source of Release Produced water tank	Date and Hour of Occurrence September 8, 2016 @ 10:00 AM	Date and Hour of Discovery September 8, 2016 @ 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM Mike Bratcher, OCD	
By Whom? Mike McMahan, Asst. Foreman	Date and Hour Jim Amos, BLM September 9, 2016 @ 9:00 AM Mike Bratcher, OCD September 9, 2016 @ 9:05 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Small leak developed at the fill line of the number 2 produced water tank. The tank was isolated and a vacuum truck was contacted to empty the tank. Repairs have been made and the produced water tank is back in service.

Describe Area Affected and Cleanup Action Taken.*

Approximately 5bbls produced water was released from a produced water tank into surrounding lined containment. A vacuum truck was called and recovered 5bbls produced water from lined containment. The containment was checked for holes and none were found. No further action is required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: <i>9/19/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: Sheila.fisher@dm.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 9/12/16	Phone: 575.748.1829	

* Attach Additional Sheets If Necessary

2RP.3896

Bratcher, Mike, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Monday, September 12, 2016 8:36 AM
To: Shelly Tucker (stucker@blm.gov); Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Harrington, Jake; Carter, Ray; McMahan, Mike; Fulks, Brett
Subject: Cotton Draw Unit 11 BS CTB_5bbl produced water release_9.8.16
Attachments: Cotton Draw Unit 11 BS CTB_5bbl produced water release_Initial & Final C-141_9.8.16.doc; Cotton Draw Unit 11 BS CTB_5bbl produced water release_GIS Image_9.8.16.pdf; Cotton Draw Unit 11 BS CTB_5bbl produced water release_pic 1 of 2_9.8.16.jpeg; Cotton Draw Unit 11 BS CTB_5bbl produced water release_pic 2 of 2_9.8.16.JPG

Good Morning,

Attached please find the Initial & Final C-141, GIS Image and photos for the 5bbl produced water release at the Cotton Draw Unit 11 BS CTB on 9.8.16.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.