

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION  
ARTESIA DISTRICT

SEP 22 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

*NAB 1626754917*

**OPERATOR**

Initial Report  Final Report

Name of Company Devon Energy Production Company <i>6137</i>		Contact Danny Velo, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210		Telephone No. 575-703-3360
Facility Name Parkway West SWD 1		Facility Type Salt Water Disposal
Surface Owner State	Mineral Owner State	API No 30-015-40835

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	19S	29E	1255'	FNL	430'	FWL	Eddy

Latitude: 32.6354904

Longitude: -104.0698929

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 21bbbs	Volume Recovered 10bbbs
Source of Release Suction hose	Date and Hour of Occurrence September 17, 2016 @ 12:00 PM	Date and Hour of Discovery September 17, 2016 @ 12:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Danny Velo, Production Foreman	Date and Hour Shelly Tucker, BLM September 17, 2016 @ 3:30 PM Mike Bratcher, OCD September 17, 2016 @ 3:35 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Due to vibration from the horizontal pump the clamps on the suction flex hose connected to the pump became loose causing the flex hose to loosen at the connection. The line was immediately isolated to stop the release. Repairs are scheduled to be completed.

Describe Area Affected and Cleanup Action Taken.\*  
Approximately 21bbbs produced water was released into surrounding cement containment overflowing out of containment onto location and into the pasture. Approximately 10bbbs produced water was recovered from cement containment with 0bbbs produced water recovered from location or pasture that had overflowed from containment. The produced water that overflowed from the cement containment flowed in a Southern direction affecting an area approximately 22'x22' on location and traveled South into pasture affecting an area approximately 14"x370'. An environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Sheila Fisher	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: <b>Field Admin Support</b>	Approval Date: <i>9/22/16</i>	Expiration Date: <i>NIA</i>
E-mail Address: <b>Sheila.fisher@dvn.com</b>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 9/19/16 Phone: 575.748.1829	<b>SUBMIT REMEDIATION PROPOSAL NO</b> LATER THAN: <i>10/26/16</i>	

\* Attach Additional Sheets If Necessary

*2RP-3906*

## Bratcher, Mike, EMNRD

---

**From:** Fisher, Sheila <Sheila.Fisher@dvn.com>  
**Sent:** Thursday, September 22, 2016 9:31 AM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; Amber Groves (agroves@slo.state.nm.us)  
**Cc:** Velo, Danny; Armendariz, Jesse; Fulks, Brett  
**Subject:** Parkway West SWD 1\_21bbbls produced water release\_9.17.16  
**Attachments:** Parkway West SWD 1\_21bbbls produced water release\_Initial C-141\_9.17.16.doc; Parkway West SWD 1\_21bbbls produced water release\_GIS Image\_9.17.16.pdf; Parkway West SWD 1\_21bbbls produced water release\_pic 1 of 3\_9.17.16.jpg; Parkway West SWD 1\_21bbbls produced water release\_pic 2 of 3\_9.17.16.JPG; Parkway West SWD 1\_21bbbls produced water release\_pic 3 of 3\_9.17.16.JPG

Good Morning,

Attached please find the Initial C-141, GIS Image and photos for the 21bbl produced water release at the Parkway West SWD 1 on 9.17.16.

If you have any questions please feel free to contact me.

Thank you,

*Sheila Fisher*  
Field Admin Support  
Production  
B-Schedule

**Devon Energy Corporation**  
PO Box 250  
Artesia, NM 88211  
575 748 1829 Direct



**Confidentiality Warning:** This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.