

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**Release Notification and Corrective Action**

**NAB1627152334**      **OPERATOR**       Initial Report       Final Report

Name of Company: Chevron USA Inc. <b>4323</b>	Contact: Josepha DeLeon
Address: 6301 Deauville Blvd., Midland, TX 79706	Telephone No.: 575-263-0424
Facility Name: Brushy 12 Federal No. 001	Facility Type: Oil Well

Surface Owner: Federal	Mineral Owner	API No.: 30-015-25416
------------------------	---------------	-----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	12	26S	29E	560	South	1980	West	Eddy

Latitude: 32.051010 Longitude: 103.9384

**NATURE OF RELEASE**

Type of Release: Spill	Volume of Release: 2.97 BO 11.87 BW	Volume Recovered: 2.97 BO 11.87 BW
Source of Release: Water tank overflow	Date and Hour of Occurrence: 08/26/2016 10:00 AM	Date and Hour of Discovery: 08/26/2016 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson - NMOCD Jim Amos - BLM	
By Whom? Josepha DeLeon	Date and Hour: 08/26/2016: 01:40 PM	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.*  Water tank overflow to lined secondary containment. All fluid was recovered.		
Describe Area Affected and Cleanup Action Taken.*  Vaccum truck picked all fluid.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:  Printed Name: Josepha DeLeon Title: HES Specialist - Compliance Support, Environmental E-mail Address: jdx@chevron.com Date: 09/08/2016      Phone: 575-263-0424	<p><b>OIL CONSERVATION DIVISION</b></p> Approved by Environmental Specialist:  Approval Date: 9/26/16      Expiration Date: N/A Conditions of Approval: <b>FINAL</b> Attached <input type="checkbox"/>
---	--

\* Attach Additional Sheets If Necessary

**2RD-3912**

## **Patterson, Heather, EMNRD**

---

**From:** DeLeon, Josepha <JDxD@chevron.com>  
**Sent:** Monday, September 26, 2016 1:48 PM  
**To:** Patterson, Heather, EMNRD; jamos@blm.gov  
**Cc:** Bustamante, Amalia, EMNRD  
**Subject:** RE: Spill 7/14/2016  
**Attachments:** Brushy Flats 12-001 Spill C-141.pdf

*Attached is the C141 for this spill.*

*Josie DeLeon, HES Specialist -*

*Compliance Support - Environmental*

**Chevron - MCBU**

**(SE NM Areas, Dollarhide, Eunice, Hobbs and Vacuum)**

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

[jdxd@chevron.com](mailto:jdxd@chevron.com)

<https://www.chevroncontractorsafety.com/contractormcbu/> - CHESM Contractor Website



Green/Red - The Doing Thinker

---

**From:** Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]  
**Sent:** Monday, September 26, 2016 1:19 PM  
**To:** DeLeon, Josepha; jamos@blm.gov  
**Cc:** Bustamante, Amalia, EMNRD  
**Subject:** **[\*\*EXTERNAL\*\*]** RE: Spill 7/14/2016

Josie,

Did you send the C-141 for this release yet? I don't have it in my records.

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** DeLeon, Josepha [mailto:JDxD@chevron.com]  
**Sent:** Friday, August 26, 2016 1:40 PM  
**To:** Patterson, Heather, EMNRD; [jamos@blm.gov](mailto:jamos@blm.gov)  
**Cc:** Bustamante, Amalia, EMNRD; Klahsen, Kim D. (kdkl); Debeysey, Svetlana; Barakat, Eli; Davis, Allen  
**Subject:** RE: Spill 7/14/2016

*Heather and Amos, as a follow up to voice message I just left, I am reporting a spill that occurred this morning at the Brushy Draw 12-1 – Carlsbad, NM.*

*As stated all was recovered and was in secondary containment (liner). Estimated volumes are listed below. As soon as final calculations are confirmed I will follow up with state report C-141.*

**Within Secondary Containment:**

- **Total: 14.84 bbls of fluid**
- Oil: 2.97 bbls
- Water: 11.87 bbls

*Josie DeLeon, HES Specialist -  
Compliance Support - Environmental*

**Chevron - MCBU  
(SE NM Areas, Dollarhide, Eunice, Hobbs and Vacuum)**

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

[idxd@chevron.com](mailto:idxd@chevron.com)

<https://www.chevroncontractorsafety.com/contractormcbu/> - CHESM Contractor Website



Green/Red – The Doing Thinker