

NM OIL CONSERVATION

ARTESIA DISTRICT

CDistrict I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

SEP 28 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1627451198

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit 17 Battery	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27784
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	6	23S	31E	1970	North	1930	West	Eddy

Latitude 32.235007° Longitude -103.819183°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	22 bbls	Volume Recovered	15 bbls
Source of Release	Heater Treater water line	Date and Hour of Occurrence	9/19/2016 time unknown	Date and Hour of Discovery	9/19/2016 approx. 9 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					

Describe Cause of Problem and Remedial Action Taken.*
Buried water dump line from heater treater to produced water tank developed hole due to corrosion. Line was isolated and clamped until repairs can be made.

Describe Area Affected and Cleanup Action Taken.*
The leak affected approximately 50 square feet of pasture west of the battery location and 2,600 square feet of caliche pad on location. Standing fluids were removed and impacted surface soils have been scraped and removed to disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amy C. Ruth</i>	OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist <i>Mike B...</i>	
Title: EHS Remediation Specialist	Approval Date: <i>9/29/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 9/28/2016 Phone: 432-661-0571	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 11/4/16

2RP-3919

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Wednesday, September 28, 2016 4:03 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: jamos@blm.gov; Tucker, Shelly
Subject: Initial C-141 - JRU 17 Battery 9-19-16
Attachments: Initial C-141 JRU 17 Battery 9-19-2016.pdf

All,

Please find attached the initial form C-141 for a release at the James Ranch Unit 17 Battery on the caliche pad. The buried water dump line from the heater treater corroded. The line is clamped until repairs can be made. Standing fluids were recovered and impacted surface soils were scraped up and removed. Soil samples are also being collected from the leak area. Please call me with any questions. Thank you.



Amy C. Ruth

BOPCO, L.P.

EH&S Remediation Specialist
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office: (575)887-7329
Fax: (575)887-7473
Cell: (432)661-0571