

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

OCT 07 2016  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: JACK FEDERAL #001H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-38643
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	31	25S	27E	330	North	380	West	Eddy

32.092617,-104.2367325

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 7 bbls PW	Volume Recovered: 6 bbls PW
Source of Release: Hole in Fire Tube	Date and Hour of Occurrence: 10/4/2016 unknown	Date and Hour of Discovery: 10/4/2016 11:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a hole in the fire tube. The heater has been drained and the fire tube repaired.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within the lined facility. A vacuum truck was dispatched to recover standing fluid and the contaminated gravel has been replaced with fresh gravel. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dakota Neel</i>	<b>OIL CONSERVATION DIVISION</b>	
	Approved by Environmental Specialist: <i>H. P.</i>	
Printed Name: Dakota Neel	Approval Date: 10/11/16	Expiration Date: N/A
Title: Environmental Coordinator	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
E-mail Address: dneel2@concho.com	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	
Date: October 7, 2016 Phone: 575-748-6933	LATER THAN: <u>11/2/16</u>	

\* Attach Additional Sheets If Necessary.

ARD-3934

## **Patterson, Heather, EMNRD**

---

**From:** Dakota Neel <DNeel2@concho.com>  
**Sent:** Friday, October 07, 2016 9:35 AM  
**To:** Patterson, Heather, EMNRD; James\_Amos@blm.gov; Bratcher, Mike, EMNRD; stucker@blm.gov  
**Cc:** Robert McNeill  
**Subject:** (C-141 Initial) Jack Federal #1H (30-015-38643)  
**Attachments:** 10-4-2016 Jack Federal #1H (TB) Initial (30-015-38643).pdf

Mr. Bratcher/Ms. Tucker,

Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

**Dakota Neel**  
Environmental Coordinator  
COG Operating LLC  
Cell: **432-215-2783**  
[dneel2@concho.com](mailto:dneel2@concho.com)

2407 Pecos Ave.  
Artesia , NM 88210



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.