

NM OIL CONSERVATION

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico ARTESIA DISTRICT
Energy Minerals and Natural Resources
Form C-141
Revised August 8, 2011
Oil Conservation Division
1220 South St. Francis Dr. **RECEIVED**
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action ~~FAB1627456818~~

OPERATOR

Initial Report Final Report **NAB1628851398**

Name of Company DCP Midstream, LP	Contact Yvonne Blair
Address 10 Desta Drive, Suite 400 West	Telephone No. cell 575-361-2406
Facility Name: 10100 Ext 2 Pipeline	Facility Type: Pipeline

Surface Owner BLM	Mineral Owner	API No.
-------------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section 3	Township 21S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	-----------	--------------	-----------	---------------	------------------	---------------	----------------	-------------

Latitude 32.51747 **Longitude** -103.75776

NATURE OF RELEASE

Type of Release: Condensate	Volume of Release 5 bbl	Volume Recovered 0 bbl
Source of Release 10100 Ext 2 Gas Pipeline	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 10-13-16
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N / A		
Describe Cause of Problem and Remedial Action Taken.* DCPM was notified of a line release on the 10100 Ext 2 line. DCPM dispatched field operators to shut in the line and blow down line.		
Describe Area Affected and Cleanup Action Taken.* A cleanup plan will be submitted for BLM and OCD Approval. The excavation from the repairs will be left open until remediation can be completed.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: 	
Printed Name: Yvonne Blair	Approval Date: 10/14/16	Expiration Date: N/A
Title: Compliance Coordinator	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines checked <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
E-mail Address: yblair@dcpmidstream.com	LATER THAN: 11/14/16	
Date: 10/13/16 Phone: 575-361-2406		

* Attach Additional Sheets If Necessary

NM OIL CONSERVATION
ARTESIA DISTRICT

OCT 13 2016

RECEIVED

2RP-3941

Patterson, Heather, EMNRD

From: Blair, Yvonne B <YBBlair@dcpmidstream.com>
Sent: Thursday, October 13, 2016 12:55 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Rhoades, Alexandra M; Conder, Haskell P; Cook, John W
Subject: 10100 Ext 2 Line Leak
Attachments: 10100 ext 2 C141 10.13.16.doc; 10100 Ext 2 Cleanup Plan 10.13.16.docx

Heather

Attached is the C141 and cleanup plan for the line leak on 10100 Ext 2 line located in Eddy County. DCP was notified of a line leak by a third party on 10.12.16 at approximately 4 p.m.

DCP construction will evaluate pipeline and make associated repairs. I will notify you when site is available for sampling and coordinate site visit.

If you have any questions or concerns please contact me.

Thanks,

Yvonne Blair
Compliance Coordinator
DCP Midstream
575-361-2406

Yvonne Blair
Compliance Coordinator
DCP Midstream
575-361-2406