

OCT 17 2016

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit a copy to appropriate District Office in accordance with 19.15.29 NMAC.

PAB 1629433888 Release Notification and Corrective Action

NAB 1629534007

OPERATOR

Initial Report Final Report

Name of Company <i>Enterprise Field Services LLC</i>	Contact <i>Alena Miro</i>
<i>PO Box 4324, Houston, TX 77210</i>	Telephone No. <i>575-628-6802</i>
Facility Name <i>South Eddy Cryo Plant</i>	Facility Type: <i>Natural Gas Processing Plant</i>
Surface Owner <i>Enterprise Field Services LLC</i>	Mineral Owner <i>NA</i>
	Lease No. <i>NA</i>

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>H</i>	<i>1</i>	<i>25S</i>	<i>30E</i>	<i>244</i>	<i>South</i>	<i>628</i>	<i>East</i>	<i>Eddy</i>

Latitude: *N 32.160280* Longitude: *W -103.827811*

NATURE OF RELEASE

Type of Release <i>Amine liquid and process material</i>	Volume of Release: <i>20 bbl liquids</i>	Volume Recovered: <i>15 bbl liquids</i>
Source of Release <i>Sump overflow</i>	Date and Hour of Occurrence <i>10/04/2016 @ 18:00 MST</i>	Date and Hour of Discovery <i>10/04/2016 @ 18:00 MST</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volumes Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <i>Amine system liquids were released due to a sump overflow. The sump was isolated and contaminated soil was contained on site. Approximately 20 bbls of liquid released.</i>		
Describe Area Affected and Cleanup Action Taken.* <i>A liquid spill of approximately 20 bbls of amine solution was released. All liquids were confined to the facility site. Remediation actions will follow the Enterprise, General Release Notification, Response and Remediation Plan (March 9, 2015).</i>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: <i>Jon E. Fields</i>	Approval Date: <i>10/19/16</i>	Expiration Date: <i>N/A</i>
Title: <i>Director, Field Environmental</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
E-mail Address: <i>jefields@eprod.com</i>	SUBMIT REMEDIATION PROPOSAL NO	
Date: <i>10/17/2016</i> Phone: <i>713-381-6684</i>	LATER THAN: <u>11/26/16</u>	

* Attach Additional Sheets If Necessary

277-3443

Bratcher, Mike, EMNRD

From: Mendez, Brenda <BJMendez@eprod.com>
Sent: Monday, October 17, 2016 12:12 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Miro, Alena; Ferguson, Dina; Nolan, Shiver
Subject: South Eddy Amine Spill C141 (October 4, 2016)
Attachments: South Eddy Cryo C141 Release Report (10-4) October 2016.pdf

Attached is the C-141 Form for the South Eddy Cryo Plant for October 4, 2016.

If you have questions or need additional information, please contact Alena Miro at 575-628-6802.

Thank you

Brenda J. Mendez – Planning and Reports Analyst
Enterprise Products Operating, LLC
Tel (713) 381-8270 – Fax (713) 880-6660
bjmendez@eprod.com

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.